



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Lu Weihan	Cust No/Name /Lu Weihan
BLK 973 HOUGANG ST 91	Reg No/Reg Date SLN6790Y / 15/05/201
#13-210	Date In/Mileage / 0
SINGAPORE 530973	Chassis No KNAFZ411MH5720548
Contact No Mobile: 96540398	Engine No G4FGGH641757
	Make/Model KIA/CERATO K3 1.6 A SX SR
	Colour/Trim K3R TEMPTATION RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00081	Cash	29/09/2022/ 13:06	TLE	261 / Edwin Caina	58156			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW RR BUMPER & BODY KIT REPAIR RHR FENDER					64 X 2			3200.00 1280
E PNT98000 RESPRAY RR BUMPER , BODY KIT & RHR FENDER					55 X 3			2200.00
E PNT88000 REMOVE & REFIT RR FLR BOARD , TRIM & CARPET								1650 X 300.00
A 54900099 CHECK WIRING ELECTRICAL SYSTEM								X 100.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM								280.00
E PNT88000 REMOVE & REFIT REVERSE SENSOR								80 100.00
M SUNDRY APPLY ANTI CORROSION ON AFFECTED AREAS								20 120.00
M SUNDRY Sundries								20 80.00
M NEW K3 TEMPTATION RED K3R					1.00	1177.00	00.00	1177.00
M COVER-RR BUMPER					1.00	688.00	00.00	688.00
M COVER-RR BUMPER,CTR					1.00	315.00	00.00	315.00
M BEAM-RR BUMPER					1.00	318.00	00.00	318.00
M STAY-RR BUMPER RH					1.00	120.00	00.00	120.00
M GUARD-BUMPER REAR,RH					1.00	17.00	00.00	17.00
M BRACKET-RR BUMPER SIDE MTG,RH					1.00	29.00	00.00	29.00
M LAMP ASSY-REAR COMBINATION,RH					1.00	788.00	00.00	788.00
M LAMP ASSY-REAR COMB INSIDE,RH					1.00	710.00	00.00	710.00

Estimate

Star (LKK)

SURVEYOR NAME: 5/12/22, 2:00 PM

SURVEYOR SIGNATURE: PIP

DATE: 5/12/22

SURVEYOR NAME: Star (LKK)

SURVEYOR SIGNATURE: S/10/11, 2021

DATE: PIP

Confirm & accepted by

REMARKS: m R 4 dgs

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

Authorized signatory and company stamp

7% GST on 10542.00 737.94

Nett 10,542.00

Total Payable 11,279.94

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Signature:

Date:

Page 1 of 1