

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 3-Oct-22

INSURANCE:

MODEL: HYUNDAI I40

VEHICLE NO.: SH 7916 U

DESCRIPTION	QTY	LIST PRICE	AMOUNT
REAR FENDER (RH) <i>Double</i>	1	\$ 2,171.40	\$2,171.40
REAR FENDER INNER LINING (RH) <i>HH</i>	1	\$ 338.60	\$338.60
REAR FENDER AIR-DUCT (RH) <i>HH</i>	1	\$ 51.60	\$51.60
REAR FENDER TRIM BOARD (RH) <i>HH</i>	1	\$ 688.75	\$688.75
REAR WINDSCREEN MOULDING <i>HH</i>	1	\$ 51.80	\$51.80
REAR DOOR (RH) <i>HH</i>	1	\$2,707.70	\$2,707.70
REAR DOOR RUBBER (RH) <i>HH</i>	1	\$ 280.50	\$280.50
REAR DOOR REGULATOR (RH) <i>HH</i>	1	\$ 660.90	\$660.90
REAR DOOR POWER WINDOW MOTOR <i>HH</i>	1	\$ 386.20	\$386.20
REAR DOOR LOCK ASSY <i>HH</i>	1	\$ 468.20	\$468.20
REAR DOOR HINGE UPPER (RH) <i>HH</i>	1	\$ 114.50	\$114.50
REAR DOOR HINGE LOWER (RH) <i>HH</i>	1	\$ 123.50	\$123.50
REAR DOOR CHECK (RH) <i>HH</i>	1	\$ 92.90	\$92.90
REAR DOOR OUTER MOULDING (RH) <i>HH</i>	1	\$ 176.80	\$176.80
ROCKER PANEL OUTER GARNISH (RH) <i>mondy broken</i>	1	\$ 732.80	\$732.80
ROCKER PANEL STEP GARNISH (FRT) (RH) <i>HH</i>	1	\$ 31.70	\$31.70
ROCKER PANEL STEP GARNISH (RR) (RH) <i>HH</i>	1	\$ 31.70	\$31.70
REAR TYRE RIM (RH) <i>HH</i>	1	\$ 650.60	\$650.60
REAR TYRE WHEEL CAP <i>cut</i>	1	\$ 214.20	\$214.20
REAR WHEEL BEARING ING & HUB <i>HH</i>	1	\$ 724.00	\$724.00
REAR TRAILING ARM (RH) <i>HH</i>	1	\$ 384.00	\$384.00
REAR ASSIST (RH) <i>HH</i>	1	\$ 219.40	\$219.40
REAR SHOCK ABSORBER (RH) <i>HH</i>	1	\$ 683.70	\$683.70
REAR SHOCK ABSORBER MOUNTING (RH) <i>HH</i>	1	\$ 162.60	\$162.60
STABILIZER BAR <i>HH</i>	1	\$ 199.60	\$199.60
STABILIZER LINK <i>HH</i>	1	\$ 85.90	\$85.90
REAR UPPER ARM (RH) <i>HH</i>	1	\$ 335.75	\$335.75
REAR LOWER ARM (RH) <i>HH</i>	1	\$ 353.80	\$353.80
REAR KNUCKLE ARM (RH) <i>HH</i>	1	\$ 545.60	\$545.60
BONNET <i>HH</i>	1	\$2,508.80	\$2,508.80
BONNET RUBBER (RH) <i>HH</i>	1	\$ 35.70	\$35.70
BONNET HINGE (LH/RH) <i>o/s bt n/s HH</i>	2	\$ 126.70	\$253.40
BONNET LOCK <i>HH</i>	1	\$ 142.40	\$142.40
BONNET ABSORBER (LH/RH) <i>HH</i>	2	\$ 61.60	\$123.20
BONNET INSULATOR <i>HH</i>	1	\$ 202.50	\$202.50
BONNET INSULATOR CLIP 10 PCS <i>HH</i>	1	\$ 36.80	\$36.80
BONNET SEAL <i>HH</i>	1	\$ 31.90	\$31.90
FRONT BUMPER COVER <i>CRACK</i>	1	\$ 1,052.20	\$1,052.20
FRONT BUMPER BRACKET TOP (RH) <i>HH</i>	1	\$ 44.80	\$44.80
FRONT BUMPER BRACKET (RH) <i>broken</i>	1	\$ 49.20	\$49.20
FRONT BUMPER RETAINER MOUNTING RH <i>HH</i>	1	\$ 76.20	\$76.20
FRONT BUMPER GRILLE AIR DUCT (RH) <i>HH</i>	1	\$ 126.20	\$126.20
WIPER CONTAINER ASSY RH <i>broken</i>	1	\$ 281.60	\$281.60

HEADLAMP SUPPORT PANEL ASSY <i>broken</i>	1	\$ 907.40	\$907.40
HEADLAMP (RH) <i>broken</i>	1	\$ 2,776.00	\$2,776.00
FRONT FENDER (RH) <i>Damage</i>	1	\$ 663.00	\$663.00
FRONT FENDER APRON PANEL (RH) <i>Damage</i>	1	\$ 637.00	\$637.00
FRONT FENDER SHIELD (RH) <i>damaged</i>	1	\$ 174.90	\$174.90
FRONT DOOR MIRROR SIDE GARNISH <i>new</i>	1	\$ 225.00	\$225.00
FRONT DOOR BLACK PLASTIC COVER <i>new</i>	1	\$ 84.20	\$84.20
FRONT DOOR MIRROR ASSY (RH) <i>new</i>	1	\$ 893.50	\$893.50
FRONT DOOR (RH) <i>Damage</i>	1	\$2,707.70	\$2,707.70
FRONT DOOR RUBBER <i>new</i>	1	\$ 290.50	\$290.50
FRONT DOOR GEAR/REGULATOR (RH) <i>broken</i>	1	\$ 776.80	\$776.80
FRONT DOOR POWER MOTOR (RH) <i>new</i>	1	\$ 172.70	\$172.70
FRONT DOOR POWER MOTOR (RH) <i>new</i>	1	\$ 296.40	\$296.40
FRONT DOOR HINGE UPPER (RH) <i>new</i>	1	\$ 113.60	\$113.60
FRONT DOOR HINGE LOWER (RH) <i>new</i>	1	\$ 125.70	\$125.70
FRONT DOOR CHECK (RH) <i>new</i>	1	\$ 91.80	\$91.80
FRONT DOOR INNER LOCK (RH) <i>new</i>	1	\$ 490.80	\$490.80
FRONT DOOR OUTER MOULDING (RH) <i>new</i>	1	\$ 153.10	\$153.10
FRONT WHEEL RIM (RH) <i>distorted</i>	1	\$ 650.60	\$650.60
FRONT WHEEL HUB CAP (RH) <i>1st</i>	1	\$ 214.20	\$214.20
KNUCKLE ARM (RH) <i>distorted</i>	1	\$ 1,104.00	\$1,104.00
FRONT WHEEL BEARING AND HUB (RH) <i>Damage</i>	1	\$ 863.80	\$863.80
FRONT SUSPENSION LOWER ARM (RH) <i>1st</i>	1	\$ 595.90	\$595.90
FRONT SHOCK ABSORBER ASSY (RH) <i>1st</i>	1	\$ 684.40	\$684.40
FRONT SHOCK ABSORBER MOUNTING (RH) <i>new</i>	1	\$ 217.60	\$217.60
STG TIE ROD (RH) <i>new</i>	1	\$ 186.40	\$186.40
STG TIE END (RH) <i>1st</i>	1	\$ 125.20	\$125.20
STABILIZER BAR ASSY <i>new</i>	1	\$ 463.70	\$463.70
STABILIZER BAR LINK (RH) <i>new</i>	1	\$ 85.90	\$85.90
FRONT DRIVE SHAFT (RH) <i>new</i>	1	\$ 2,061.60	\$2,061.60
RACK & PINION ASSY <i>new</i>	1	\$ 1,820.00	\$1,820.00
SUB TOTAL			\$39,287.00
LESS 20%			\$7,857.40
DISCOUNTED TOTAL			\$31,429.60
REAR FENDER ADVERTISEMENT LOGO (RH) <i>new</i> SN	1	\$ 100.00	\$100.00
REAR WINDSCREEN SEALANT <i>new</i> SN	1	\$ 46.00	\$46.00
Rear Door Comfortdelgro & Apps Sticker(RH) <i>new</i> SN	1	\$ 80.00	\$ 80.00
REAR DOOR ADVERTISEMENT LOGO (RH) <i>new</i> SN	1	\$ 100.00	\$100.00
ROCKER PANEL ADVERTISEMENT(RH) <i>new</i> SN	1	\$ 120.00	\$ 120.00
REAR TYRE (RH) <i>new</i> SN	1	\$ 216.00	\$216.00
FRONT FENDER ADVERTISEMENT LOGO <i>new</i> SN	1	\$ 100.00	\$100.00
FRONT DOOR COMFORT LOGO (RH) <i>new</i> SN	1	\$ 75.00	\$75.00
FRONT DOOR ADVERTISEMENT LOGO <i>new</i> SN	1	\$ 100.00	\$100.00
FRONT TYRE (RH) <i>new 50% dep</i> SN	1	\$ 216.00	\$216.00
SUB TOTAL			\$1,153.00
Labour Charge			
Panel Beating	1	\$ 2,000.00	\$2,000.00
Spray Painting Charge	1	\$ 1,800.00	\$1,800.00
Wiring Charge	1	\$ 100.00	\$100.00
Tuff Kote	1	\$ 100.00	\$100.00
Towing Charge	1	\$ 80.00	\$80.00

1388.00

325.30

107.10

552.00

301.80

529.30

342.20

14,110.50

11,288.40

108.00

749.00

900/-

1000/-

301/-

401/-

new

cut

Remove/Refix Cushion & Upholstery Rear	1	\$ 150.00	\$150.00
Remove/Refix Rear Windscreen Glass	1	\$ 120.00	\$120.00
Remove/Refix Undercarriage (RR)	1	\$ 400.00	\$400.00
Transfer of Door Mechanism FRONT	1	\$ 80.00	\$80.00
Re-set Frt Power Window System	1	\$ 200.00	\$200.00
Transfer of Door Mechanism REAR	1	\$ 80.00	\$80.00
Re-set Rear Power Window System	1	\$ 200.00	\$200.00
Four Wheel Alignment	1	\$ 120.00	\$120.00
Remove/Refix Undercarriage (Frt)	1	\$ 400.00	\$400.00
Remove/Refix Radiator	1	\$ 90.00	\$90.00
Remove/Refix Aircon & Refill Gas	1	\$ 130.00	\$130.00
Remove/Refix Steering Rack/Wheel/Dr Shaft	1	\$ 150.00	\$150.00
Diagnostic & Resetting To Erase Fault Code	1	\$ 550.00	\$550.00
TOTAL LABOUR			\$6,750.00
ESTIMATE TOTAL			\$ 39,332.60

80/-
80/-
400/-
60/-
200/-
80/-
200/-
120/-
400/-
90/-
130/-
150/-
550/-

2400.00

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company. Please send your book value request to: claims_itr@bifrostauto.com


14,437.40

03/10/2022 @ 1730hrs

4/5 10,000/-

Not Actual repair unit.

2/5 same 48 days.



LKK Auto



Check part prices.
Provide BV before
Final quote.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: