

ASS. REC. BY:

REF:

AIG / 22009667/ke

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

09

days

Res.: Yes or No

Lum Sum:

20 HBT

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SNC 3002T

Yr Regn:

08/19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai Accent

c.c

1390

Colour

M. Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

50874

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

KMHCU 413TK4 470245

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/60R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

8

mm

Rear

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

29/9/22

D.O.I.

30/9/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

2/10 11:00 AM @ 52501 Cebu

Date/Time, File Pass to?



: Prell. Report

Days Of Repair:

1)



: Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

2)

Add Fee:



: Site Insp (\$



: Interview (\$



Tech Invs (\$



Weekend (\$

Survey Fee:

Transportation

\$ - RS. SI

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SNC3002T
7P/AIG

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

Estimate No: ES2291000

Date: 29 Sep 2022

Policy No: 5124545987

Veh Reg No: SNC3002T

Make/Model: HYUNDAI HYUNDAI
ACCENT (RB) 1.4 CVT

WS Ref: TP/AIG

Claim Type: Third Party

Accident Date: 29/09/2022

TP Veh Reg No: SKZ6608R

Chassis No: KMHCU41BTKU470245

Engine No: G4LCKU190572

Reg. Date: 28/08/2019

Estimate Repair Cost to Vehicle No :SNC3002T

PAGE:1/2

Description	U/Price	Quantity	List Price	Amount
			SS	SS
List Price			443	
1 REAR BUMPER	4,430.00	1 PC	4,430.00	✓
2 REAR BUMPER RETAINER LH	23.20	1 PC	23.20	✓
3 REAR BUMPER RETAINER RH	23.20	1 PC	23.20	✓
4 REAR BUMPER CLIP	3.50	6 PCS	21.00	✓
5 REAR BUMPER REINFORCEMENT BRACKET	376.50	1 PC	376.50	✓
6 REAR BUMPER UPPER BRACKET	8.50	3 PCS	25.50	X
7 REAR BUMPER LOWER BRACKET	8.50	2 PCS	17.00	2T
8 REAR UNDER LOWER COVER CLIP	3.50	6 PCS	21.00	✓
9 REAR BOOT 1301-30	1,301.30	1 PC	1,301.30	✓
10 REAR BOOT RUBBER	79.50	1 PC	79.50	✓
11 REAR BOOT UPPER LOCK	166.80	1 PC	166.80	✓
12 REAR BOOT HINGE LH	99.00	1 PC	99.00	X
13 REAR BOOT HINGE RH	99.00	1 PC	99.00	X
14 REAR BOOT EMBLEM - ACCENT	31.20	1 PC	31.20	✓
15 REAR BOOT CENTRE EMBLEM	27.60	1 PC	27.60	✓
16 REAR BOOT INSULATOR	84.80	1 PC	84.80	X
17 REAR BOOT INSULATOR CLIP	3.50	8 PCS	28.00	✓
18 REAR END PANEL 499.30	499.30	1 PC	499.30	✓
19 REAR END PANEL INNER TRIM	115.10	1 PC	115.10	✓
20 REAR END PANEL INNER TRIM CLIP	3.50	4 PCS	14.00	✓
21 REAR FLOORBOARD PANEL 433.90	433.90	1 PC	433.90	✓
22 REAR FLOOR LH TOOL TRAY	86.00	1 PC	86.00	X
23 REAR SPARE TYRE TRAY	296.20	1 PC	296.20	✓
24 REAR SPARE TYRE HOLD DOWN BOLT	23.10	1 PC	23.10	X
25 REAR PDC SENSOR	195.90	2 PCS	391.80	✓
26 REAR PDC SENSOR WIRE HARNESS	105.00	1 SET	105.00	X
27 ANTENA SENSOR	80.20	1 PC	80.20	✓
			8,899.20	
		Less 20%	1,779.84	7,119.36
Labour				
28 TO REMOVE REAR SEATS, TRIMS, COVERING, BOOT INTERIOR PARTS, REAR END DAMAGED BODY PARTS; PANEL BEAT & REPAIR RR FENERS, CHASSIS MEMBER; CUT, WELD AND REPALCE DAMAGED PARTS	1,300.00	1 LA	1,300.00	1200
29 TO TRANSFER REVERSE CAMERA AND INSTALL REAR PDC SENSOR	50.00	1 LA	50.00	✓

Not Authorised
Repairing B6 pain
1/1/2022 @ 52501
9 days

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
ES2291000/YISHUN
#07-16 AIG BUILDING
SINGAPORE 079120
TEL: 64193000 FAX: 64153727
ATTN: Motor Claim Department

WS Ref: TP/AIG
Claim Type: Third Party
Accident Date: 29/09/2022
TP Veh Reg No: SKZ6608R

Estimate No: **ES2291000**

Date: 29 Sep 2022
Policy No: 5124545987
Veh Reg No: **SNC3002T**
Make/Model: HYUNDAI HYUNDAI
ACCENT (RB) 1.4 CVT
Chassis No: KMHCU41BTKU470245
Engine No: G4LCKU190572
Reg. Date: 28/08/2019

Estimate Repair Cost to Vehicle No :SNC3002T

PAGE:2/2

Description	U/Price	Quantity	List Price S\$	Amount S\$
30 TO RESPRAY PAINTING ON REAR BUMPER, BOOTLID, REAR END PANEL, FLOOR PANEL, SIDE EXTENSION PANEL, BOTH REAR FENDERS AND ALL ACCIDENT AFFECTED	1,200.00	1 LA	1,200.00	1100
31 RUSTPROOFING	60.00	1 LA	60.00 ✓	
			2,610.00	
		Less 20%	522.00	2,088.00
		Total		S\$ 9,207.36
		Add GST @ 7%		644.52
		Total Amount Payable		S\$ 9,851.88

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
TEL: 64193000 FAX: 64153727
ATTN: Motor Claim Department

Estimate No: ES2291000/YISHUN
Date: 04 Oct 2022
Policy No: 5124545987
Veh Reg No: SNC3002T
Make/Model: HYUNDAI HYUNDAI
ACCENT (RB) 1.4 CVT
Chassis No: KMHCU41BTKU470245
Engine No: G4LCKU190572
Reg. Date: 28/08/2019

WS Ref: TP/AIG
Claim Type: Third Party
Accident Date: 29/09/2022
TP Veh Reg No: SKZ6608R

Estimate Repair Cost to Vehicle No :SNC3002T

Description	U/Price	Quantity	List Price S\$	Amount S\$
Supplementary 1				
List Price				
1 TAILLAMPS	326.50	2 PC	653.00	
2 REAR BOOT CHROME MOULDING	183.00	1 PC	183.00	
			836.00	
		Less 20%	167.20	668.80
		Total		S\$ 668.80
		GST Amount		S\$ 46.82
		Total Amount Payable		S\$ 715.62

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 187D

Vehicle Details

Vehicle No.: SNC3002T
Vehicle to be Exported: No
Intended Deregistration Date: 29 Sep 2022
Vehicle Make: HYUNDAI
Vehicle Model: ACCENT (RB) 1.4 CVT
Primary Colour: Silver
Manufacturing Year: 2019
Engine No.: G4LCKU190572
Chassis No.: KMHCU41BTKU470245
Maximum Power Output: 73.6 kW (98 bhp)
Open Market Value: \$9,205.00
Original Registration Date: 28 Aug 2019
First Registration Date: 28 Aug 2019
Transfer Count: 1
Actual ARF Paid: \$9,205.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 27 Aug 2029
PARF Rebate Amount: \$6,903.00

Intended COE Rebate Details

COE Expiry Date: 27 Aug 2029
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$31,917.00
COE Rebate Amount: \$22,058.00
Total Rebate Amount: \$28,961.00

The information contained herein is correct as at 29 Sep 2022

OK