

## Estimate

48 Toh Guan Road East (Enterprise Hub)  
#02-146, Singapore 608586  
Tel: 64688834 Fax: 67228585  
E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2209-528-TG  
DATE : 29-Sep-2022  
POLICY NO. :  
VEHICLE REG. NO. : SLV7330T  
VEHICLE MAKE : MAZDA2 SEDAN 1.5 AT STANDARD PLUS

TO Motor Claim Department  
China Taiping Insurance (Singapore) Pte. Ltd  
3 Anson Road, #15-00 Springleaf Tower  
Singapore 079909  
Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

### ESTIMATE REPAIR COST

| NO.                  | DESCRIPTION   | QUANTITY | UNIT COST   | TOTAL COST  |
|----------------------|---|----------|-------------|-------------|
| <b>SPARE PARTS</b>   |   |          |             |             |
| 1                    | Rear Bumper   | 1        | \$ 1,216.70 | \$ 1,216.70 |
| 2                    | Rear Bumper Side Retainer RH                              | 1        | \$ 44.50    | \$ 44.50    |
| 3                    | Rear Bumper Reflector RH                                  | 1        | \$ 85.00    | \$ 85.00    |
| 4                    | Rear Fender RH  | 1        | \$ 1,035.00 | \$ 1,035.00 |
| 5                    | Rear Fender Innershield RH                                | 1        | \$ 78.20    | \$ 78.20    |
| 6                    | Rear Door RH  | 1        | \$ 1,000.00 | \$ 1,000.00 |
| 7                    | Rear Door Lock RH   | 1        | \$ 215.60   | \$ 215.60   |
| 8                    | Rear Door Weatherstrip RH                                 | 1        | \$ 110.50   | \$ 110.50   |
| 9                    | Rear Door Black Tape RH                                   | 1        | \$ 48.35    | \$ 48.35    |
| 10                   | Rear Windscreen Moulding                                  | 1        | \$ 183.00   | \$ 183.00   |
| Part Less 20%        |   |          |             | \$ (766.77) |
| Total Spare Parts    |   |          |             | \$ 3,250.08 |
| <b>SPECIAL NETT</b>  |   |          |             |             |
| 11                   | Rear Bumper Clips   | 10       | \$ 5.00     | \$ 50.00    |
| 12                   | Rear Fender Innershield Clips                             | 10       | \$ 5.00     | \$ 50.00    |
| Total Special Nett   |   |          |             | \$ 100.00   |
| <b>LABOUR</b>        |   |          |             |             |
| 13                   | Remove, Refit, Repair and Replace Accident Affected Parts | 1        | \$ 800.00   | \$ 800.00   |
| 14                   | Spray Paint (Rear Bumper, Rear Fender RH, Rear Door RH)   | 1        | \$ 800.00   | \$ 800.00   |
| 15                   | To Perform 4 Wheel Alignment                              | 1        | \$ 70.00    | \$ 70.00    |
| 16                   | Remove & Refit Rear Windscreen                            | 1        | \$ 120.00   | \$ 120.00   |
| 17                   | Transfer door fitting and window mechanism to new door    | 1        | \$ 80.00    | \$ 80.00    |
| 18                   | Check and Rectify Electrical Wiring                       | 1        | \$ 50.00    | \$ 50.00    |
| Total Labour         |   |          |             | \$ 1,920.00 |
| Amount Before Excess |   |          |             | \$ 5,270.08 |
| Add GST @ 7%         |   |          |             | 268.91      |
| Total Amount Payable |   |          |             | \$ 5,638.99 |

Estimate prepared by: James Tan

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.

Tan J'm 97495749  
WP: 30/9/22 07pm  
L/S Resurvey after repair  
tan j'm 01/10/2022  
6 days

Page 1 of 1

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

3073.35  
 2458.68  
 30  
 30  
 600  
 700  
 60  
 1550  
 2458.68  
 30  
 1550  
 4038.68  
 153200  
 06 days  
 #