

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672



Date Generated : 09/11/2022

User ID PohSuan

Section A - Accident Details

Registration Number	SHB103G
Case Reference Number	TAX/09/22/2067
Registration Date	8/3/2013
Company Type	Strides Taxi Pte Ltd
Make	LONDON TAXI
Model	TX4
Name of Driver	CHIN YOKE HANG
Type of Accident	Side Swipe
Accident Date and Time	25/9/2022 9:17 AM
Accident Reported Date and Time	26/9/2022 4:01 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24116376
Special Instruction to ARC, if any	LEFT PORTION
Prepared Date and Time	27/9/2022 8:19 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$676.00	\$300.00
Total Spray Cost	\$756.00	\$400.00
Total Spare Part Cost	\$3,031.69	\$0.00
Total Other Cost	\$380.00	(\$150.00)
TOTAL COST	\$4,843.69	\$550.00 (L/S)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	4.0	3.0
Prepared / Adjusted By	Boon Chew Tay	Rasul (LKK) / ERGO
ARC / Surveyor Sign Off Date	28/09/2022 1:40 PM	27/09/2022 4:11 PM
Signature		
Remarks	REQ NBV / Lump sum repair / After repair photo FOR CHECK ITEM and REPLACE ITEM PLEASE CALL SURVEYOR RASUL / HP : 9001 0068. email: rasul@lkkauto.com	

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 09/11/2022

User ID PohSuan

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2210-0115	Invoice Number	
Quotation Date	11.10.2022	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR LH PORTION	\$676.00	\$300.00
Total Labour	\$676.00	\$300.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT FENDER LH	\$378.00	\$200.00
TO RESPRAY FRONT DOOR LH	\$378.00	\$200.00
Total Spray Painting & Panel Beating	\$756.00	\$400.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO WASH AND VACUUM	\$60.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	\$0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
Lump Sum Adjustment by Surveyor	\$0.00	(\$150.00)
Total Other Costs	\$380.00	(\$150.00)

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		1182001000	DOOR ASSY FRONT LH	1.00	\$2,536.93	100.00	\$0.00	Replace	Repair
		5380247100	FENDER SUB-ASSY, FR , LH	1.00	\$1,060.70	100.00	\$0.00	Replace	Repair
		538764710	LINER, FR FENDER, LH	0.00	\$219.10	0.00	\$0.00	Replace	Not Given
		6872012151	HINGE ASSY, FRONT DOOR , UPPER LH	0.00	\$105.50	0.00	\$0.00	Replace	Not Given
		6874012120	HINGE ASSY, FRONT DOOR , LOWER LH	0.00	\$120.00	0.00	\$0.00	Replace	Not Given
Total					\$4,042.23		\$0.00		

R
R
X
X
X

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

	0.00	
+	300.00	
+	400.00	L/S \$550/-
	700.00	
	-20%	
	560.00	