

ASS. REC. BY:

REF:

NS/INC22009676/Rvc

369k

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SHF 30L

at Workshop m/s STRIDES

of 60, WOODWARDS Lnd PK E4

Insured: SKV 8364B INC

Policy No. _____


Claims No. MT/1190486-003

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SHF 30L Yr Regn: 2657 / NOV

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA PRIMO Hybrid 1.8 CVT c.c 1798

Colour: MAROON A/C: Insured / Std / NI / NA

Sp. Reading: 761429 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDK83FU903573-489

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/55R15
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or FIRENZA

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 21/09/22 D.O.I. 28/09/22

Survey held at STRIDES

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FRONT & REAR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
18/11/22	Rasul informed LS \$9750 (red 36,960.20, 79%)

Date/Time, File Pass to?

☐ : Preli. Report

1) _____

☐ : Final Report

Date/Time, File Return to?

2) 23/11/22-typist

Days Of Repair: 10

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Report Form: TP

Lump Sum / L.S. \$9750

Case Details

Case Reference Number : TAX/09/22/2070
Type of Repair : Accident Repair
Vehicle Registration Number : SHF30L

Company Type : Strides Taxi Pte Ltd
Estimation ID : EST-19444-ID
Assigned By : Taxi Claims Manager Team

Insurance Company Name : income insurance limited
Accident Date and Time : 27/09/2022 01:43 AM
Vehicle Age(In Months) : -

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			INSULATOR, HOOD CLIP	6	3.10	18.60	25.00	13.95	Replace	6	13.95	Replace	✓
One Time Key In	Main			COVER SUB-ASSY, FRONT PILLAR, UPR RH	1	108.70	108.70	25.00	81.53	Replace	0	0	Not Give	Xm
Standard	Main			COVER, FR BUMPER	1	560.30	560.30	25.00	420.22	Replace	1	420.22	Replace	de ✓
Standard	Main			SUPPORT, FR BUMPER RH	1	86.20	86.20	25.00	64.65	Replace	0	0	Check	?
Standard	Main			SUPPORT, FR BUMPER LH	1	86.20	86.20	25.00	64.65	Replace	1	0	Old Dam	Xm
Standard	Main			COVER, FR BUMPER RH	1	31.80	31.80	25.00	23.85	Replace	1	23.85	Replace	sc ✓
Standard	Main			COVER, FR BUMPER LH	1	31.80	31.80	25.00	23.85	Replace	0	0	Not Give	Xm
Standard	Main			BRACKET, FR BUMPER	1	111.80	111.80	25.00	83.85	Replace	0	0	Check	?
Standard	Main			NUMBER PLATE	1	35.00	35.00	0.00	35.00	Replace	1	35.00	Replace	sf ✓
Standard	Main			NUMBER PLATE FRAME	1	25.00	25.00	0.00	25.00	Replace	1	0	Repair	R
Standard	Main			REINFORCEMENT FRONT UPPER	1	773.90	773.90	25.00	580.43	Replace	0	0	Not Give	Xm
Standard	Main			ABSORBER, FR BUMPER	1	85.90	85.90	25.00	64.43	Replace	1	64.43	Replace	cm ✓
Standard	Main			EXTENSION SUB-ASSY, LH	1	129.90	129.90	25.00	97.43	Replace	0	0	Not Give	Xm
Standard	Main			EXTENSION SUB-ASSY, RH	1	129.90	129.90	25.00	97.43	Replace	0	0	Check	?
Standard	Main			REINFORCEMENT FRONT LOWER	1	265.90	265.90	25.00	199.42	Replace	0	0	Not Give	Xm

Total Spare Part Cost 30,972.48

Surveyor Total 8,520.21

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 24,777.98

Final Sur Total 6,816.17

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
Standard	Main			ABSORBER, FR BUMPER LOWER	1	143.60	143.60	25.00	107.70	Replace	0	0	Not Give	✓ X11
Standard	Main			SEAL, HOOD TO FR END	1	55.80	55.80	25.00	41.85	Replace	1	41.85	Replace	✓ M1
Standard	Main			EMBLEM ASSY FRONT	1	98.70	98.70	25.00	74.03	Replace	1	74.03	Replace	✓ M1
Standard	Main			GRILLE, RADIATOR	1	183.90	183.90	25.00	137.93	Replace	0	0	Not Give	✓ X11
Standard	Main			GRILLE SUB-ASSY	1	374.40	374.40	25.00	280.80	Replace	0	0	Not Give	✓ X11
Standard	Main			CLIPS PIECE, FRT & RR BUMPER	10	4.80	48.00	25.00	36.00	Replace	10	36.00	Replace	✓ M1
Standard	Main			RETAINER, FR BUMPER, LH & RH	1	9.50	9.50	25.00	7.13	Replace	0	0	Not Give	✓ X11
Standard	Main			COVER ASSY, ENGINE	1	201.00	201.00	25.00	150.75	Replace	0	0	Not Give	✓ X11
Standard	Main			COVER ASSY, ENGINE UNDER CENTER SET	1	511.20	511.20	25.00	383.40	Replace	0	0	Not Give	✓ X11
Standard	Main			COVER, ENGINE UNDER SIDE RH	1	86.20	86.20	25.00	64.65	Replace	0	0	Not Give	✓ X11
Standard	Main			COVER, ENGINE UNDER SIDE LH	1	86.20	86.20	25.00	64.65	Replace	0	0	Not Give	✓ X11
Standard	Main			LAMP ASSY, FOG, RH	1	1,029.90	1,029.90	10.00	926.91	Replace	1	926.91	Replace	✓ M1
Standard	Main			LAMP ASSY, FOG, LH	1	1,029.90	1,029.90	10.00	926.91	Replace	0	0	Not Give	✓ X11
Standard	Main			UNIT, HEADLAMP, LH	1	2,852.40	2,852.40	10.00	2,567.16	Replace	0	0	Not Give	✓ X11
Standard	Main			UNIT, HEADLAMP, RH	1	2,852.40	2,852.40	10.00	2,567.16	Replace	1	2,567.16	Replace	✓ M1
Standard	Main			COMPUTER SUB-ASSY, HEADLAMP, LH NO.1	1	1,039.90	1,039.90	10.00	935.91	Replace	0	0	Not Give	✓ X11
Standard	Main			COMPUTER SUB-ASSY, HEADLAMP, RH NO.1	1	1,039.90	1,039.90	10.00	935.91	Replace	0	0	Not Give	✓ X11
Standard	Main			INSULATOR, HOOD	1	444.40	444.40	25.00	333.30	Replace	0	0	Not Give	✓ X11
Standard	Main			HOOD SUB-ASSY	1	1,066.30	1,066.30	25.00	799.72	Replace	1	799.72	Replace	✓ M1
Standard	Main			COVER, RADIATOR	1	254.70	254.70	25.00	191.02	Replace	0	0	Not Give	✓ X11
Standard	Main			HINGE ASSY, HOOD, RH	1	63.70	63.70	25.00	47.78	Replace	1	47.78	Replace	✓ M1
Standard	Main			HINGE ASSY, HOOD, LH	1	63.70	63.70	25.00	47.78	Replace	0	0	Not Give	✓ X11
Standard	Main			CABLE ASSY, HOOD	1	59.50	59.50	25.00	44.63	Replace	0	0	Not Give	✓ X11
Total Spare Part Cost									30,972.48	Surveyor Total 8,520.21				
Lump Sum Discount (%)									20.00	Lump Sum Dis (%) 20				
Final Spare Part Cost									24,777.98	Final Sur Total 6,816.17				

Remarks

SMRT Recommendation														
Surveyor Approval														
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
Standard	Main			LEVER SUB-ASSY, HOOD	1	80.60	80.60	25.00	60.45	Replace	0	0	Not Give	Xan
Standard	Main			BOLT, HOOD LOCK	1	11.20	11.20	25.00	8.40	Replace	0	0	Not Give	Xan
Standard	Main			LOCK ASSY, HOOD	1	146.10	146.10	25.00	109.57	Replace	0	0	Not Give	Xan
Standard	Main			BRACE, HOOD LOCK SUPPORT	1	84.40	84.40	25.00	63.30	Replace	0	0	Not Give	Xan
Standard	Main			FRONT REINFORCEMENT SIDE RH	1	144.30	144.30	25.00	108.23	Replace	0	0	Not Give	Xan
Standard	Main			FRONT REINFORCEMENT SIDE LH	1	144.30	144.30	25.00	108.23	Replace	0	0	Not Give	Xan
Standard	Main			FRONT PLATE, FR SUSPENSION	1	10.50	10.50	25.00	7.88	Replace	0	0	Not Give	Xan
Standard	Main			SUPPORT S/A UPPER,	1	408.50	408.50	25.00	306.38	Replace	0	0	Not Give	Xan
Standard	Main			SUPPORT S/A RH	1	265.10	265.10	25.00	198.83	Replace	0	0	Not Give	Xan
Standard	Main			SUPPORT S/A LH	1	265.10	265.10	25.00	198.83	Replace	0	0	Not Give	Xan
Standard	Main			SUPPORT SUB-ASSY LOWER	1	443.50	443.50	25.00	332.63	Replace	0	0	Not Give	Xan
Standard	Main			SUPPORT, RADIATOR UPPER RH	1	85.20	85.20	25.00	63.90	Replace	0	0	Not Give	Xan
Standard	Main			SUPPORT, RADIATOR UPPER LH	1	85.20	85.20	25.00	63.90	Replace	0	0	Not Give	Xan
Standard	Main			WIPER WASHER INLET	1	72.30	72.30	25.00	54.22	Replace	0	0	Not Give	Xan
Standard	Main			WIPER WASHER JAR	1	236.90	236.90	25.00	177.68	Replace	1	177.61	Replace	de
Standard	Main			GUIDE, RADIATOR AIR,	1	122.10	122.10	25.00	91.57	Replace	0	0	Not Give	Xan
Standard	Main			SEAL, RADIATOR GRILLE	2	45.50	91.00	25.00	68.25	Replace	0	0	Not Give	Xan
Standard	Main			FENDER SUB-ASSY, FR, RH	1	1,060.70	1,060.70	25.00	795.53	Replace	1	795.51	Replace	bf
Standard	Main			EMBLEM, SIDE PANEL (HYBRID)	1	59.10	59.10	25.00	44.33	Replace	1	44.33	Replace	ne
Standard	Main			LINER, FR FENDER, RH	1	223.50	223.50	25.00	167.63	Replace	0	0	Check	?
Standard	Main			PAD, FR WHEEL RH	1	65.00	65.00	25.00	48.75	Replace	0	0	Not Give	Xan
Standard	Main			SEAL SUB-ASSY, RH	1	56.20	56.20	25.00	42.15	Replace	0	0	Not Give	Xan
Standard	Main			PROTECTOR, FR FENDER RH	1	101.80	101.80	25.00	76.35	Replace	0	0	Not Give	Xan

Total Spare Part Cost 30,972.48

Surveyor Total 8,520.21

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
Standard	Main			APRON SUB-ASSY, FRONT FENDER , RH	1	1,060.90	1,060.90	25.00	795.68	Replace	0	0	Not Give	Xan
Standard	Main			MOULDING ASSY, BODY ROCKER PANEL , RH	1	649.10	649.10	25.00	486.83	Replace	0	0	Not Give	Xan
Standard	Main			PANEL SUB-ASSY, FRONT DOOR RH	1	1,407.80	1,407.80	25.00	1,055.85	Replace	1	0	Repair	R
Standard	Main			STICKER STRIDES TAXI (DOOR)	1	60.00	60.00	0.00	60.00	Replace	1	60.00	Replace	nu
Standard	Main			COVER, RR BUMPER ASSY	1	478.90	478.90	25.00	359.17	Replace	1	359.17	Replace	de
Standard	Main			REAR BUMPER REINFORCEMENT	1	360.10	360.10	25.00	270.08	Replace	1	270.08	Replace	bf
Standard	Main			PAD, RR BUMPER, RH & LH , 1	2	4.30	8.60	25.00	6.45	Replace	2	6.45	Replace	nu
Standard	Main			PAD, RR BUMPER, RH & LH , 2	2	4.30	8.60	25.00	6.45	Replace	2	6.45	Replace	nu
Standard	Main			PAD, RR BUMPER, RH & LH , 3	2	4.30	8.60	25.00	6.45	Replace	2	6.45	Replace	nu
Standard	Main			PAD, RR BUMPER, CTR	1	2.50	2.50	25.00	1.88	Replace	1	1.88	Replace	nu
Standard	Main			SEAL, RR BUMPER ARM, RH & LH	1	12.30	12.30	25.00	9.23	Replace	1	9.23	Replace	nu
Standard	Main			STOPPER, RR BUMPER, RH & LH	1	4.80	4.80	25.00	3.60	Replace	0	0	Not Give	Xan
Standard	Main			RETAINER, RR BUMPER, RH	1	127.40	127.40	25.00	95.55	Replace	0	0	Not Give	Xan
Standard	Main			RETAINER, RR BUMPER, LH	1	127.40	127.40	25.00	95.55	Replace	0	0	Not Give	Xan
Standard	Main			SEAL, RR BUMPER , RH	1	95.50	95.50	25.00	71.63	Replace	0	0	Not Give	Xan
Standard	Main			SEAL, RR BUMPER , LH	1	95.50	95.50	25.00	71.63	Replace	0	0	Not Give	Xan
Standard	Main			CLIPS PIECE, FRT & RR BUMPER	10	4.80	48.00	25.00	36.00	Replace	10	36.00	Replace	de
Standard	Main			GUARD, RR BUMPER, LOWER	1	623.50	623.50	25.00	467.63	Replace	1	467.63	Replace	de
Standard	Main			FILLER, RR BUMPER , LH	1	168.60	168.60	25.00	126.45	Replace	1	126.45	Replace	ca
Standard	Main			FILLER, RR BUMPER , RH	1	168.60	168.60	25.00	126.45	Replace	0	0	Not Give	Xan
Standard	Main			COVER, GUARD RR BUMPER LOWER	1	16.70	16.70	25.00	12.52	Replace	0	0	Not Give	Xan
Standard	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	1	180.00	Replace	nu

Total Spare Part Cost 30,972.48

Surveyor Total 8,520.21

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 24,777.98

Final Sur Total 6,816.17

Remarks

SMRT Recommendation

Surveyor Approval

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
Standard	Main			ANTENNA, ELECTRICAL KEY	1	78.00	78.00	25.00	58.50	Replace	0	0	Not Give	Xm
Standard	Main			REAR BUMPER GROMMET SCREW	1	2.20	2.20	25.00	1.65	Replace	1	1.65	Replace	ne /
Standard	Main			LENS & BODY, REAR COMBINATION LAMP, RH	1	489.00	489.00	10.00	440.10	Replace	0	0	Not Give	Xm
Standard	Main			LENS & BODY, REAR COMBINATION LAMP, LH	1	489.00	489.00	10.00	440.10	Replace	0	0	Not Give	Xm
Standard	Main			LENS & BODY ASSY, RR BUMPER, RH	1	544.40	544.40	10.00	489.96	Replace	0	0	Not Give	Xm
Standard	Main			LENS & BODY ASSY, RR BUMPER, LH	1	544.40	544.40	10.00	489.96	Replace	0	0	Not Give	Xm
Standard	Main			COVER, REAR COMBINATION LAMP, RH	1	69.90	69.90	25.00	52.43	Replace	0	0	Not Give	Xm
Standard	Main			COVER, REAR COMBINATION LAMP, LH	1	69.90	69.90	25.00	52.43	Replace	0	0	Not Give	Xm
Standard	Main			COVER, REAR FLOOR UNDER, RH	1	189.20	189.20	25.00	141.90	Replace	0	0	Not Give	Xm
Standard	Main			COVER, REAR FLOOR UNDER, LH	1	261.60	261.60	25.00	196.20	Replace	0	0	Not Give	Xm
Standard	Main			COVER, REAR FLOOR UNDER CENTER	1	249.10	249.10	25.00	186.83	Replace	0	0	Not Give	Xm
Standard	Main			TAIL GATE PANEL SUB-ASSY, BACK DOOR	1	1,238.40	1,238.40	25.00	928.80	Replace	1	0	Repair	R
Standard	Main			TAIL GATE WEATHERSTRIP, BACK DOOR	1	402.50	402.50	25.00	301.88	Replace	0	0	Not Give	Xm
Standard	Main			TAIL GATE DAM, BACK DOOR GLASS UPPER ADHESIVE	1	31.10	31.10	25.00	23.33	Replace	0	0	Not Give	Xm
Standard	Main			TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	1	992.30	992.30	25.00	744.22	Replace	1	744.22	Replace	scu /
Standard	Main			NAME PLATE (HYBRID), LUGGAGE COMPARTMENT DOOR	1	59.10	59.10	25.00	44.33	Replace	1	44.33	Replace	ne /
Standard	Main			NAME PLATE (PRIUS), LUGGAGE COMPARTMENT DOOR	1	59.10	59.10	25.00	44.33	Replace	1	44.33	Replace	ne /

Total Spare Part Cost 30,972.48

Surveyor Total 8,520.21

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

SMRT Recommendation											Surveyor Approval			Remarks
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
Standard	Main			TAIL GATE GLASS SUB-ASSY, BACK DOOR	1	1,795.00	1,795.00	25.00	1,346.25	Replace	0	0	Not Give	Xm
Standard	Main			TAIL GATE LOWER GLASS SUB-ASSY, BACK DOOR	1	821.20	821.20	25.00	615.90	Replace	0	0	Not Give	Xm
Standard	Main			SEALANT W/SCREEN (3PCS)	3	37.00	111.00	0.00	111.00	Replace	0	0	Not Give	Xm
Standard	Main			TAIL GATE BACK DOOR HINGE ASSY, RH & LH	2	66.20	132.40	25.00	99.30	Replace	0	0	Not Give	Xm
Standard	Main			TAIL GATE LOCK ASSY, BACK DOOR	1	505.50	505.50	10.00	454.95	Replace	0	0	Not Give	Xm
Standard	Main			TAIL GATE LOCK COVER , BACK DOOR	1	32.70	32.70	25.00	24.53	Replace	0	0	Not Give	Xm
Standard	Main			EMBLEM SUB-ASSY REAR	1	77.40	77.40	25.00	58.05	Replace	1	58.05	Replace	ne
Standard	Main			SPOILER SUB-ASSY, REAR	1	1,704.20	1,704.20	25.00	1,278.15	Replace	0	0	Not Give	Xm
Standard	Main			LAMP SET, STOP CENTER	1	207.90	207.90	10.00	187.11	Replace	0	0	Not Give	Xm
Standard	Main			STRIDES LOGO	1	7.80	7.80	0.00	7.80	Replace	1	7.80	Replace	ne
Standard	Main			STICKER DECAL 6555 8888	1	21.60	21.60	0.00	21.60	Replace	1	21.60	Replace	ne
Standard	Main			END PANEL SUB-ASSY, BODY LOWER BACK	1	707.10	707.10	25.00	530.33	Replace	0	0	Not Give	Xm
Standard	Main			SPARE TYRE PANEL , PAN, REAR FLOOR	1	630.30	630.30	25.00	472.72	Replace	0	0	Not Give	Xm
Standard	Main			SEALANT SIKAFLEX	1	37.00	37.00	0.00	37.00	Replace	0	0	Not Give	Xm

Total Spare Part Cost 30,972.48

Surveyor Total 8,520.21

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 24,777.98

Final Sur Total 6,816.17

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR FRONT PORTION	1,014.00	700	
2	Main	TO REPAIR REAR PORTION	1,690.00	400	
Total:			2,704.00	1,100.00	

Spray Cost Detail

8/22, 4:55 PM

https://vacswb.smrt.com.sg/Estimation.aspx

S.No	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY FRONT BUMPER	378.00	200	
2	Main	TO RESPRAY FRONT HOOD	378.00	200	
3	Main	TO RESPRAY FRONT SUPPORT PANEL	180.00	0 <i>Xm</i>	
4	Main	TO RESPRAY FRONT FENDER RH	378.00	200	
5	Main	TO RESPRAY FRT MEMBER, RH	180.00	0 <i>Xm</i>	
6	Main	TO RESPRAY FRONT DOOR RH	378.00	200	
7	Main	TO RESPRAY ROCKER PANEL MOULDING	180.00	0 <i>Xm</i>	
8	Main	TO RESPRAY REAR BUMPER	378.00	200	
9	Main	TO RESPRAY REAR PANEL	180.00	0 <i>Xm</i>	
10	Main	TO RESPRAY REAR SPARE TYRE PANEL	180.00	0 <i>Xm</i>	
11	Main	TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	100	
12	Main	TO RESPRAY TAIL GATE	378.00	200	
13	Main	TO RESPRAY REAR SPOILER	180.00	0 <i>Xm</i>	
Total:			3,528.00	1,300.00	

Other Cost Detail

S.No	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO WASH AND VACUUM	60.00	0 <i>Xm</i>	
2	Main	TO CHECK WIRING AND SYSTEM FUNCTION	120.00	0 <i>Xm</i>	
3	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	40	
4	Main	TO TRANSFER REAR TAILGATE MECHANISM	120.00	0 <i>Xm</i>	
5	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	40	
6	Main	TO REMOVE AND REFIX REAR WINDSCREEN	240.00	0 <i>Xm</i>	
7	Main	TO REPLACE SUNDRY PARTS	100.00	0 <i>Xm</i>	
Total:					

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	24,777.98	6,816.17
Total Labour Cost	2,704.00	1,100.00
Total Spray Painting	3,528.00	1,300.00
Other	860.00	80.00
Overall Total	31,869.98	9,296.17
Lump Sum Repair Option	☐	☒
Lump Sum Total	31,850.00	9,300.00
Surveyor Approved Amount		9,300.00
No of Repair Days*	12	8
Remarks		RESURVEY AFTER REPAIR / LUMP SUM REPAIR
Surveyor Name		Rasul
Signature		
Survey Date	28/09/2022	Save Clear

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	27/09/2022 15:50 (SGT)
Reported by	Driver
Date of Accident	27/09/2022 09:43 (SGT)
Exact Location of Accident	Nicoll Hwy, Singapore
Additional Location Information	NICOLL HIGHWAY
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHF30L
INSURED/POLICYHOLDER	
Is company?	Yes
Name of Registered Owner	Strides Taxi Pte Ltd
Company Reg No	1XXXXX369K
Email Address	AUTO-SVCS-TARC@SMRT.COM.SG
Mobile Phone No	(Phone) +65-68662671
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Prius
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Taxi
Transmission	Auto
CC	1800

INSURANCE COMPANY

Name of Insurance Company	MS First Capital Insurance Ltd
Policy Number / Cover Note Number	D-22099115MFSH

DRIVER

Name of Driver	LOH NGIAN KWONG
NRIC No	SXXXX933B
Date Of Birth	14/01/1949
Occupation	Outdoor

Date Of Driving Pass	15/01/1985
Driving experience	37 YEARS AND 8 MONTHS
Gender	Male
Mobile Number	(Phone) +65-68662671
Alt. Phone Number	-
Email Address	AUTO-SVCS-TARC@SMRT.COM.SG
Address	11
Address complement	-
Postcode	-
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Hirer
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Chain Collision
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	3
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

I WAS DRIVING ALONG NICOLL HIGHWAY (NEAR F1 EVENT SITE), THE FRONT VEHICLE SLOWED DOWN AND I FOLLOW SUIT, SUDDENLY I FELT A BIG IMPACT FROM THE REAR AND THE IMPACT PUSHED MY TAXI FORWARD AND COLLIDED ONTO THE FRONT VEHICLE.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKV8364B
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car

Name of Driver	SS 33 75 2 200 00 00 00	-
Contact Number	SS 33 75 2 200 00 00 00	-
Address	SS 33 75 2 200 00 00 00	-
Address complement	SS 33 75 2 200 00 00 00	-
Postcode	SS 33 75 2 200 00 00 00	-
Insurance Company Name	SS 33 75 2 200 00 00 00	-
Nature Of Damage	SS 33 75 2 200 00 00 00	-
Details of property damaged in accident	SS 33 75 2 200 00 00 00	-
No. Of Passenger (Including Driver)	SS 33 75 2 200 00 00 00	-

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SLN1568L
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

SKETCH PLAN

IMPORTANT NOTICE

- 1 Please report correctly the details of the accident to speed up the claims process.
- 2 This Form must be completed by the Policyholder and/or the Actual Driver
- 3 Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4 The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5 **Any false reporting may be referred to the Traffic Police Department for investigation.**
- 6 This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7 By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8 **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that


- (a) My insurer, my workshop and the General Insurance Association of Singapore (GIA) may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages), and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes

Policyholder's Signature/Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)

Sketch Plan



A = 54F30L
B = SKV 8364B
C = SLN 1568L

Describe Circumstance of the Accident

Declaration
I/We declare the foregoing statements are true in every respect.

Declaration
I/We declare the foregoing statements are true in every respect.

Driver's Signature / Driver Name (in print) / Date & Time

Driver's Signature / Driver Name (in print) / Date & Time

2

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Company

Owner ID:

369K

Vehicle Details

Vehicle No.:

SHF30L

Vehicle to be Exported:

No

Intended Deregistration Date:

30 Sep 2022

Vehicle Make:

TOYOTA

Vehicle Model:

PRIUS HYBRID 1.8 CVT

Primary Colour:

Maroon

Manufacturing Year:

2017

Engine No.:

2ZR5100962

Chassis No.:

JTDKB3FU903573489

Maximum Power Output:

90.0 kW (120 bhp)

Open Market Value:

\$29,007.00

Original Registration Date:

01 Nov 2017

First Registration Date:

01 Nov 2017

Transfer Count:

0

Actual ARF Paid:

\$5,000.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

31 Oct 2025

PARF Rebate Amount:

\$3,750.00

Intended COE Rebate Details

COE Expiry Date:

31 Oct 2025

COE Category:

A - Car up to 1600cc & 97kW (130bhp)

COE Period (Years):

8

PQP Paid:

\$33,596.00

COE Rebate Amount:

\$12,948.00

Total Rebate Amount:

\$16,698.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 30 Sep 2022