


**Section A - Accident Details**

|                                    |                                          |
|------------------------------------|------------------------------------------|
| Registration Number                | SHF30L                                   |
| Case Reference Number              | TAX/09/22/2070                           |
| Registration Date                  | 1/11/2017                                |
| Company Type                       | Strides Taxi Pte Ltd                     |
| Make                               | TOYOTA                                   |
| Model                              | PRIUS4                                   |
| Name of Driver                     | LOH NGIAN KWONG                          |
| Type of Accident                   | Head to Rear                             |
| Accident Date and Time             | 27/9/2022 9:43 AM                        |
| Accident Reported Date and Time    | 27/9/2022 12:43 PM                       |
| Is Surveyor Required?              | Yes                                      |
| Survey by                          |                                          |
| Vehicle is Towed Back?             | No                                       |
| Towed Back Date and Time           |                                          |
| Replacement Vehicle issued?        | No                                       |
| Job Card Number                    | 24116381                                 |
| Special Instruction to ARC, if any | CHAIN COLLISION - DAMAGE TO FRONT & REAR |
| Prepared Date and Time             | 27/9/2022 3:14 PM                        |
| Chassis Number                     |                                          |
| Mileage                            |                                          |
| Work Shop                          |                                          |
| Repair Completion Date and Time    |                                          |

**Section B - Summary of Repair Estimates**

| Summary of Repair Estimates  |                                                                                     |                                                                                                                                                                    |
|------------------------------|-------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------|
|                              | Quotation from ARC                                                                  | Adjusted by Surveyor, if applicable                                                                                                                                |
| Total Labour Cost            | \$2,954.00                                                                          | \$1,200.00                                                                                                                                                         |
| Total Spray Cost             | \$3,708.00                                                                          | \$1,400.00                                                                                                                                                         |
| Total Spare Part Cost        | \$31,952.14                                                                         | \$9,499.91                                                                                                                                                         |
| Total Other Cost             | \$860.00                                                                            | (\$2,349.91)                                                                                                                                                       |
| <b>TOTAL COST</b>            | <b>\$39,474.14</b>                                                                  | <b>\$9,750.00 (L/S)</b>                                                                                                                                            |
| <b>Lump Sum Total</b>        | <b>\$0.00</b>                                                                       | <b>\$0.00</b>                                                                                                                                                      |
| Number of Repair Days        | 15.0                                                                                | 10.0                                                                                                                                                               |
| Prepared / Adjusted By       | <b>Boon Chew Tay</b>                                                                | <b>RASUL (LKK) / NTUC</b>                                                                                                                                          |
| ARC / Surveyor Sign Off Date | <b>05/10/2022 12:08 PM</b>                                                          | <b>05/10/2022 11:28 AM</b>                                                                                                                                         |
| Signature                    |  |                                                                                 |
| Remarks                      | Initial 12 days / sup 3days / 15 days                                               | LUMP SUM REPAIR / RESURVEY AFTER REPAIR / After repair photo FOR CHECK ITEM and REPLACE ITEM PLEASE CALL SURVEYOR RASUL / HP : 9001 0068. email: rasul@lkkauto.com |

**Section C - Quotation and Accident Invoice Details**

|                  |              |                |  |
|------------------|--------------|----------------|--|
| Quotation Number | QN-2211-0027 | Invoice Number |  |
| Quotation Date   | 03.11.2022   | Invoice Date   |  |
| Invoice Amount   |              | Prepared Date  |  |

**Section D - Details of Repair Estimates**

**Part 1 - Labour Works**

| Job Scope                | Quotation from AR | Adjusted by Surveyor, if applicable |
|--------------------------|-------------------|-------------------------------------|
| TO REPAIR FRONT PORTION  | \$1,014.00        | \$700.00                            |
| TO REPAIR REAR PORTION   | \$1,690.00        | \$400.00                            |
| TO REPAIR REAR END PANEL | \$250.00          | \$100.00                            |
| <b>Total Labour</b>      | <b>\$2,954.00</b> | <b>\$1,200.00</b>                   |

**Part 2 - Spray Painting & Panel Beating Related Works**

| Job Scope                                       | Quotation from ARC | Adjusted by Surveyor, if applicable |
|-------------------------------------------------|--------------------|-------------------------------------|
| TO RESPRAY FRONT BUMPER                         | \$378.00           | \$200.00                            |
| TO RESPRAY FRONT HOOD                           | \$378.00           | \$200.00                            |
| TO RESPRAY FRONT SUPPORT PANEL                  | \$180.00           | \$0.00                              |
| TO RESPRAY FRONT FENDER RH                      | \$378.00           | \$200.00                            |
| TO RESPRAY FRT MEMBER,RH                        | \$180.00           | \$0.00                              |
| TO RESPRAY FRONT DOOR RH                        | \$378.00           | \$200.00                            |
| TO RESPRAY ROCKER PANEL MOULDING                | \$180.00           | \$0.00                              |
| TO RESPRAY REAR BUMPER                          | \$378.00           | \$200.00                            |
| TO RESPRAY REAR PANEL                           | \$180.00           | \$0.00                              |
| TO RESPRAY REAR SPARE TYRE PANEL                | \$180.00           | \$0.00                              |
| TO RESPRAY TAILGATE OUTSIDE GARNISH             | \$180.00           | \$100.00                            |
| TO RESPRAY TAIL GATE                            | \$378.00           | \$200.00                            |
| TO RESPRAY REAR SPOILER                         | \$180.00           | \$0.00                              |
| TO RESPRAY REAR PANEL                           | \$180.00           | \$100.00                            |
| <b>Total Spray Painting &amp; Panel Beating</b> | <b>\$3,708.00</b>  | <b>\$1,400.00</b>                   |

**Part 3 - Other Costs - Accident and Accident Repair Related Expense**

| Job Scope                               | Quotation from ARC | Adjusted by Surveyor, if applicable |
|-----------------------------------------|--------------------|-------------------------------------|
| TO WASH AND VACUUM                      | \$60.00            | \$0.00                              |
| TO CHECK WIRING AND SYSTEM FUNCTION     | \$120.00           | \$0.00                              |
| TO APPLY RUST-PROOFING ON AFFECTED AREA | \$100.00           | \$40.00                             |
| TO TRANSFER REAR TAILGATE MECHANISM     | \$120.00           | \$0.00                              |
| TO TEST AND REFIX REVERSE SENSOR SYSTEM | \$120.00           | \$40.00                             |
| TO REMOVE AND REFIX REAR WINDSCREEN     | \$240.00           | \$0.00                              |
| TO REPLACE SUNDRY PARTS                 | \$100.00           | \$0.00                              |
| Lump Sum Adjustment by Surveyor         | \$0.00             | (\$2,429.91)                        |
| <b>Total Other Costs</b>                | <b>\$860.00</b>    | <b>(\$2,349.91)</b>                 |

**Part 4 - Spare Parts / Material Usage**

| Part Number | Portion | Stock Number | Part Name                             | Quantity | List Price (\$) | Discount (%) | Final Price (\$) | Estimator Approved | Surveyor Approved |
|-------------|---------|--------------|---------------------------------------|----------|-----------------|--------------|------------------|--------------------|-------------------|
|             |         | 9046709050   | INSULATOR, HOOD CLIP                  | 6.00     | \$3.10          | 25.00        | \$13.95          | Replace            | Replace           |
|             |         | 6011747020   | COVER SUB-ASSY, FRONT PILLAR , UPR RH | 0.00     | \$108.70        | 0.00         | \$0.00           | Replace            | Not Given         |

√  
X

**STRIDES Accident Vehicle Repair Estimates**

|                                                   |
|---------------------------------------------------|
| STRIDES Automotive Services Pte Ltd               |
| 60 Woodlands Industrial Park E4, Singapore 757705 |
| FAX Number : 63685592                             |
| Estimator Telephone Number : 68662623             |
| Accident Reporting Number : 68662672              |

Date Generated : 10/11/2022

User ID : PohSuan

|  |  |                  |                                         |       |            |        |            |         |            |   |
|--|--|------------------|-----------------------------------------|-------|------------|--------|------------|---------|------------|---|
|  |  | 52119479<br>62   | COVER, FR BUMPER                        | 1.00  | \$560.30   | 25.00  | \$420.23   | Replace | Replace    | √ |
|  |  | 52115470<br>50   | SUPPORT, FR BUMPER RH                   | 0.00  | \$86.20    | 0.00   | \$0.00     | Replace | Check      | X |
|  |  | 52116470<br>50   | SUPPORT, FR BUMPER LH                   | 1.00  | \$86.20    | 100.00 | \$0.00     | Replace | Old Damage | X |
|  |  | 52127479<br>07   | COVER, FR BUMPER RH                     | 1.00  | \$31.80    | 25.00  | \$23.85    | Replace | Replace    | √ |
|  |  | 52128479<br>06   | COVER, FR BUMPER LH                     | 0.00  | \$31.80    | 0.00   | \$0.00     | Replace | Not Given  | X |
|  |  | 52114471<br>90   | BRACKET, FR BUMPER                      | 0.00  | \$111.80   | 0.00   | \$0.00     | Replace | Check      | X |
|  |  |                  | NUMBER PLATE                            | 1.00  | \$35.00    | 0.00   | \$35.00    | Replace | Replace    | √ |
|  |  |                  | NUMBER PLATE FRAME                      | 1.00  | \$25.00    | 100.00 | \$0.00     | Replace | Repair     | R |
|  |  | 52021471<br>10   | REINFORCEMENT FRONT<br>UPPER            | 0.00  | \$773.90   | 0.00   | \$0.00     | Replace | Not Given  | X |
|  |  | 52611471<br>40   | ABSORBER, FR BUMPER                     | 1.00  | \$85.90    | 25.00  | \$64.43    | Replace | Replace    | √ |
|  |  | 52103470<br>10   | EXTENSION SUB-ASSY, LH                  | 0.00  | \$129.90   | 0.00   | \$0.00     | Replace | Not Given  | X |
|  |  | 52102470<br>20   | EXTENSION SUB-ASSY, RH                  | 0.00  | \$129.90   | 0.00   | \$0.00     | Replace | Check      | X |
|  |  | 52132470<br>10   | REINFORCEMENT FRONT<br>LOWER            | 0.00  | \$265.90   | 0.00   | \$0.00     | Replace | Not Given  | X |
|  |  | 52618470<br>90   | ABSORBER, FR BUMPER<br>LOWER            | 0.00  | \$143.60   | 0.00   | \$0.00     | Replace | Not Given  | X |
|  |  | 53395470<br>40   | SEAL, HOOD TO FR END                    | 1.00  | \$55.80    | 25.00  | \$41.85    | Replace | Replace    | √ |
|  |  | 75310470<br>60   | EMBLEM ASSY FRONT                       | 1.00  | \$98.70    | 25.00  | \$74.03    | Replace | Replace    | √ |
|  |  | 53112472<br>40   | GRILLE, RADIATOR                        | 0.00  | \$183.90   | 0.00   | \$0.00     | Replace | Not Given  | X |
|  |  | 53101470<br>80   | GRILLE SUB-ASSY                         | 0.00  | \$374.40   | 0.00   | \$0.00     | Replace | Not Given  | X |
|  |  | 52161160<br>10   | CLIPS PIECE, FRT & RR<br>BUMPER         | 10.00 | \$4.80     | 25.00  | \$36.00    | Replace | Replace    | √ |
|  |  | 52535500<br>60   | RETAINER, FR BUMPER, LH<br>& RH         | 0.00  | \$9.50     | 0.00   | \$0.00     | Replace | Not Given  | X |
|  |  | 51420470<br>30   | COVER ASSY, ENGINE                      | 0.00  | \$201.00   | 0.00   | \$0.00     | Replace | Not Given  | X |
|  |  | 51410470<br>20   | COVER ASSY, ENGINE<br>UNDER CENTER SET  | 0.00  | \$511.20   | 0.00   | \$0.00     | Replace | Not Given  | X |
|  |  | 51443470<br>20   | COVER, ENGINE UNDER<br>SIDE RH          | 0.00  | \$86.20    | 0.00   | \$0.00     | Replace | Not Given  | X |
|  |  | 51444470<br>10   | COVER, ENGINE UNDER<br>SIDE LH          | 0.00  | \$86.20    | 0.00   | \$0.00     | Replace | Not Given  | X |
|  |  | 81210470<br>20   | LAMP ASSY, FOG, RH                      | 1.00  | \$1,029.90 | 10.00  | \$926.91   | Replace | Replace    | √ |
|  |  | 81220470<br>20   | LAMP ASSY, FOG, LH                      | 0.00  | \$1,029.90 | 0.00   | \$0.00     | Replace | Not Given  | X |
|  |  | 81185476<br>91   | UNIT , HEADLAMP , LH                    | 0.00  | \$2,852.40 | 0.00   | \$0.00     | Replace | Not Given  | X |
|  |  | 81145476<br>91   | UNIT , HEADLAMP , RH                    | 1.00  | \$2,852.40 | 10.00  | \$2,567.16 | Replace | Replace    | √ |
|  |  | 81056476<br>90   | COMPUTER SUB-ASSY,<br>HEADLAMP, LH NO.1 | 0.00  | \$1,039.90 | 0.00   | \$0.00     | Replace | Not Given  | X |
|  |  | 81016476<br>90   | COMPUTER SUB-ASSY,<br>HEADLAMP, RH NO.1 | 0.00  | \$1,039.90 | 0.00   | \$0.00     | Replace | Not Given  | X |
|  |  | 53341470<br>40   | INSULATOR, HOOD                         | 0.00  | \$444.40   | 0.00   | \$0.00     | Replace | Not Given  | X |
|  |  | 53301471<br>10   | HOOD SUB-ASSY                           | 1.00  | \$1,066.30 | 25.00  | \$799.73   | Replace | Replace    | √ |
|  |  | 53289470<br>72   | COVER, RADIATOR                         | 0.00  | \$254.70   | 0.00   | \$0.00     | Replace | Not Given  | X |
|  |  | 53410471<br>30   | HINGE ASSY, HOOD, RH                    | 1.00  | \$63.70    | 25.00  | \$47.78    | Replace | Replace    | √ |
|  |  | 53420471<br>30   | HINGE ASSY, HOOD, LH                    | 0.00  | \$63.70    | 0.00   | \$0.00     | Replace | Not Given  | X |
|  |  | 53630470<br>90   | CABLE ASSY, HOOD                        | 0.00  | \$59.50    | 0.00   | \$0.00     | Replace | Not Given  | X |
|  |  | 53601520<br>10C1 | LEVER SUB-ASSY, HOOD                    | 0.00  | \$80.60    | 0.00   | \$0.00     | Replace | Not Given  | X |
|  |  | 53577330<br>10   | BOLT, HOOD LOCK                         | 0.00  | \$11.20    | 0.00   | \$0.00     | Replace | Not Given  | X |
|  |  | 53510471<br>40   | LOCK ASSY, HOOD                         | 0.00  | \$146.10   | 0.00   | \$0.00     | Replace | Not Given  | X |
|  |  | 53217470<br>30   | BRACE, HOOD LOCK<br>SUPPORT             | 0.00  | \$84.40    | 0.00   | \$0.00     | Replace | Not Given  | X |
|  |  | 51107470<br>20   | FRONT REINFORCEMENT<br>SIDE RH          | 0.00  | \$144.30   | 0.00   | \$0.00     | Replace | Not Given  | X |
|  |  | 51108470<br>20   | FRONT REINFORCEMENT<br>SIDE LH          | 0.00  | \$144.30   | 0.00   | \$0.00     | Replace | Not Given  | X |
|  |  | 51228470<br>10   | FRONT PLATE, FR<br>SUSPENSION           | 0.00  | \$10.50    | 0.00   | \$0.00     | Replace | Not Given  | X |
|  |  | 53205479<br>00   | SUPPORT S/A UPPER,                      | 0.00  | \$408.50   | 0.00   | \$0.00     | Replace | Not Given  | X |
|  |  | 53202479<br>01   | SUPPORT S/A RH                          | 0.00  | \$265.10   | 0.00   | \$0.00     | Replace | Not Given  | X |

**STRIDES Accident Vehicle Repair Estimates**

|                                                   |
|---------------------------------------------------|
| STRIDES Automotive Services Pte Ltd               |
| 60 Woodlands Industrial Park E4, Singapore 757705 |
| FAX Number : 63685592                             |
| Estimator Telephone Number : 68662623             |
| Accident Reporting Number : 68662672              |

Date Generated : 10/11/2022

User ID : PohSuan

|  |                |                                          |       |            |        |          |         |           |   |
|--|----------------|------------------------------------------|-------|------------|--------|----------|---------|-----------|---|
|  | 53203479<br>01 | SUPPORT S/A LH                           | 0.00  | \$265.10   | 0.00   | \$0.00   | Replace | Not Given | X |
|  | 53028470<br>10 | SUPPORT SUB-ASSY<br>LOWER                | 0.00  | \$443.50   | 0.00   | \$0.00   | Replace | Not Given | X |
|  | 53213470<br>50 | SUPPORT, RADIATOR<br>UPPER RH            | 0.00  | \$85.20    | 0.00   | \$0.00   | Replace | Not Given | X |
|  | 53214470<br>50 | SUPPORT, RADIATOR<br>UPPER LH            | 0.00  | \$85.20    | 0.00   | \$0.00   | Replace | Not Given | X |
|  | 85319471<br>70 | WIPER WASHER INLET                       | 0.00  | \$72.30    | 0.00   | \$0.00   | Replace | Not Given | X |
|  | 85315471<br>60 | WIPER WASHER JAR                         | 1.00  | \$236.90   | 25.00  | \$177.68 | Replace | Replace   | √ |
|  | 16592370<br>20 | GUIDE, RADIATOR AIR,                     | 0.00  | \$122.10   | 0.00   | \$0.00   | Replace | Not Given | X |
|  | 53155470<br>10 | SEAL, RADIATOR GRILLE                    | 0.00  | \$45.50    | 0.00   | \$0.00   | Replace | Not Given | X |
|  | 53801470<br>80 | FENDER SUB-ASSY, FR , RH                 | 1.00  | \$1,060.70 | 25.00  | \$795.53 | Replace | Replace   | √ |
|  | 75374471<br>40 | EMBLEM, SIDE PANEL (HYBRID)              | 1.00  | \$59.10    | 25.00  | \$44.33  | Replace | Replace   | √ |
|  | 53875470<br>70 | LINER, FR FENDER, RH                     | 0.00  | \$223.50   | 0.00   | \$0.00   | Replace | Check     | X |
|  | 53851470<br>61 | PAD, FR WHEEL RH                         | 0.00  | \$65.00    | 0.00   | \$0.00   | Replace | Not Given | X |
|  | 53807470<br>20 | SEAL SUB-ASSY, RH                        | 0.00  | \$56.20    | 0.00   | \$0.00   | Replace | Not Given | X |
|  | 53827470<br>50 | PROTECTOR, FR FENDER<br>RH               | 0.00  | \$101.80   | 0.00   | \$0.00   | Replace | Not Given | X |
|  | 53701471<br>11 | APRON SUB-ASSY, FRONT<br>FENDER , RH     | 0.00  | \$1,060.90 | 0.00   | \$0.00   | Replace | Not Given | X |
|  | 75850479<br>10 | MOULDING ASSY, BODY<br>ROCKER PANEL , RH | 0.00  | \$649.10   | 0.00   | \$0.00   | Replace | Not Given | X |
|  | 67001471<br>52 | PANEL SUB-ASSY, FRONT<br>DOOR RH         | 1.00  | \$1,407.80 | 100.00 | \$0.00   | Replace | Repair    | R |
|  |                | STICKER STRIDES TAXI (DOOR )             | 1.00  | \$60.00    | 0.00   | \$60.00  | Replace | Replace   | √ |
|  | 52159479<br>13 | COVER, RR BUMPER ASSY                    | 1.00  | \$478.90   | 25.00  | \$359.18 | Replace | Replace   | √ |
|  | 52023470<br>30 | REAR BUMPER<br>REINFORCEMENT             | 1.00  | \$360.10   | 25.00  | \$270.08 | Replace | Replace   | √ |
|  | 52462470<br>30 | PAD, RR BUMPER, RH & LH ,<br>1           | 2.00  | \$4.30     | 25.00  | \$6.45   | Replace | Replace   | √ |
|  | 52462470<br>20 | PAD, RR BUMPER, RH & LH ,<br>2           | 2.00  | \$4.30     | 25.00  | \$6.45   | Replace | Replace   | √ |
|  | 52462470<br>10 | PAD, RR BUMPER, RH & LH ,<br>3           | 2.00  | \$4.30     | 25.00  | \$6.45   | Replace | Replace   | √ |
|  | 52461470<br>10 | PAD, RR BUMPER, CTR                      | 1.00  | \$2.50     | 25.00  | \$1.88   | Replace | Replace   | √ |
|  | 52191470<br>30 | SEAL, RR BUMPER ARM, RH<br>& LH          | 1.00  | \$12.30    | 25.00  | \$9.23   | Replace | Replace   | √ |
|  | 52599680<br>30 | STOPPER, RR BUMPER, RH<br>& LH           | 0.00  | \$4.80     | 0.00   | \$0.00   | Replace | Not Given | X |
|  | 52575470<br>40 | RETAINER, RR BUMPER, RH                  | 0.00  | \$127.40   | 0.00   | \$0.00   | Replace | Not Given | X |
|  | 52576470<br>40 | RETAINER, RR BUMPER, LH                  | 0.00  | \$127.40   | 0.00   | \$0.00   | Replace | Not Given | X |
|  | 52591470<br>50 | SEAL, RR BUMPER , RH                     | 0.00  | \$95.50    | 0.00   | \$0.00   | Replace | Not Given | X |
|  | 52592470<br>40 | SEAL, RR BUMPER , LH                     | 0.00  | \$95.50    | 0.00   | \$0.00   | Replace | Not Given | X |
|  | 52161160<br>10 | CLIPS PIECE, FRT & RR<br>BUMPER          | 10.00 | \$4.80     | 25.00  | \$36.00  | Replace | Replace   | √ |
|  | 52453470<br>10 | GUARD, RR BUMPER,<br>LOWER               | 1.00  | \$623.50   | 25.00  | \$467.63 | Replace | Replace   | √ |
|  | 52566479<br>00 | FILLER, RR BUMPER , LH                   | 1.00  | \$168.60   | 25.00  | \$126.45 | Replace | Replace   | √ |
|  | 52565479<br>00 | FILLER, RR BUMPER , RH                   | 0.00  | \$168.60   | 0.00   | \$0.00   | Replace | Not Given | X |
|  | 52169470<br>20 | COVER, GUARD RR<br>BUMPER LOWER          | 0.00  | \$16.70    | 0.00   | \$0.00   | Replace | Not Given | X |
|  |                | SENSOR REVERSE                           | 1.00  | \$180.00   | 0.00   | \$180.00 | Replace | Replace   | √ |

**STRIDES Accident Vehicle Repair Estimates**

|                                                   |
|---------------------------------------------------|
| STRIDES Automotive Services Pte Ltd               |
| 60 Woodlands Industrial Park E4, Singapore 757705 |
| FAX Number : 63685592                             |
| Estimator Telephone Number : 68662623             |
| Accident Reporting Number : 68662672              |

Date Generated : 10/11/2022

User ID : PohSuan

|              |  |              |                                           |      |                    |        |                   |         |           |   |
|--------------|--|--------------|-------------------------------------------|------|--------------------|--------|-------------------|---------|-----------|---|
|              |  | 8999730100   | ANTENNA, ELECTRICAL KEY                   | 0.00 | \$78.00            | 0.00   | \$0.00            | Replace | Not Given | X |
|              |  | 9018906029   | REAR BUMPER GROMMET SCREW                 | 1.00 | \$2.20             | 25.00  | \$1.65            | Replace | Replace   | √ |
|              |  | 8155147281   | LENS & BODY, REAR COMBINATION LAMP , RH   | 0.00 | \$489.00           | 0.00   | \$0.00            | Replace | Not Given | X |
|              |  | 8156147151   | LENS & BODY, REAR COMBINATION LAMP , LH   | 0.00 | \$489.00           | 0.00   | \$0.00            | Replace | Not Given | X |
|              |  | 8158147010   | LENS & BODY ASSY , RR BUMPER , RH         | 0.00 | \$544.40           | 0.00   | \$0.00            | Replace | Not Given | X |
|              |  | 8159147010   | LENS & BODY ASSY , RR BUMPER , LH         | 0.00 | \$544.40           | 0.00   | \$0.00            | Replace | Not Given | X |
|              |  | 8149747020   | COVER, REAR COMBINATION LAMP, RH          | 0.00 | \$69.90            | 0.00   | \$0.00            | Replace | Not Given | X |
|              |  | 8149847020   | COVER, REAR COMBINATION LAMP, LH          | 0.00 | \$69.90            | 0.00   | \$0.00            | Replace | Not Given | X |
|              |  | 5839847050   | COVER, REAR FLOOR UNDER , RH              | 0.00 | \$189.20           | 0.00   | \$0.00            | Replace | Not Given | X |
|              |  | 5839947030   | COVER, REAR FLOOR UNDER , LH              | 0.00 | \$261.60           | 0.00   | \$0.00            | Replace | Not Given | X |
|              |  | 6625947010   | COVER, REAR FLOOR UNDER CENTER            | 0.00 | \$249.10           | 0.00   | \$0.00            | Replace | Not Given | X |
|              |  | 6700547440   | TAIL GATE PANEL SUB-ASSY, BACK DOOR       | 1.00 | \$1,238.40         | 100.00 | \$0.00            | Replace | Repair    | R |
|              |  | 6788147050   | TAIL GATE WEATHERSTRIP, BACK DOOR         | 0.00 | \$402.50           | 0.00   | \$0.00            | Replace | Not Given | X |
|              |  | 5611750140   | TAIL GATE DAM, BACK DOOR GLASS UPPER      | 0.00 | \$31.10            | 0.00   | \$0.00            | Replace | Not Given | X |
|              |  | 7680147110A1 | TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-  | 1.00 | \$992.30           | 25.00  | \$744.23          | Replace | Replace   | √ |
|              |  | 7544147090   | NAME PLATE (HYBRID) , LUGGAGE COMPARTMENT | 1.00 | \$59.10            | 25.00  | \$44.33           | Replace | Replace   | √ |
|              |  | 7544247130   | NAME PLATE (PRIUS) , LUGGAGE COMPARTMENT  | 1.00 | \$59.10            | 25.00  | \$44.33           | Replace | Replace   | √ |
|              |  | 6810547291   | TAIL GATE GLASS SUB-ASSY, BACK DOOR       | 0.00 | \$1,795.00         | 0.00   | \$0.00            | Replace | Not Given | X |
|              |  | 6480147031   | TAIL GATE LOWER GLASS SUB-ASSY, BACK DOOR | 0.00 | \$821.20           | 0.00   | \$0.00            | Replace | Not Given | X |
|              |  |              | SEALANT W/SCREEN ( 3PCS )                 | 0.00 | \$37.00            | 0.00   | \$0.00            | Replace | Not Given | X |
|              |  | 6881047061   | TAIL GATE BACK DOOR HINGE ASSY, RH & LH   | 0.00 | \$66.20            | 0.00   | \$0.00            | Replace | Not Given | X |
|              |  | 6935047050   | TAIL GATE LOCK ASSY, BACK DOOR            | 0.00 | \$505.50           | 0.00   | \$0.00            | Replace | Not Given | X |
|              |  | 6932147010   | TAIL GATE LOCK COVER , BACK DOOR          | 0.00 | \$32.70            | 0.00   | \$0.00            | Replace | Not Given | X |
|              |  | 7540348010   | EMBLEM SUB-ASSY REAR                      | 1.00 | \$77.40            | 25.00  | \$58.05           | Replace | Replace   | √ |
|              |  | 7608547916   | SPOILER SUB-ASSY, REAR                    | 0.00 | \$1,704.20         | 0.00   | \$0.00            | Replace | Not Given | X |
|              |  | 8100647030   | LAMP SET, STOP CENTER                     | 0.00 | \$207.90           | 0.00   | \$0.00            | Replace | Not Given | X |
|              |  |              | STRIDES LOGO                              | 1.00 | \$7.80             | 0.00   | \$7.80            | Replace | Replace   | √ |
|              |  |              | STICKER DECAL 6555 8888                   | 1.00 | \$21.60            | 0.00   | \$21.60           | Replace | Replace   | √ |
|              |  | 5830747090   | END PANEL SUB-ASSY, BODY LOWER BACK       | 0.00 | \$707.10           | 0.00   | \$0.00            | Replace | Not Given | X |
|              |  | 5831147130   | SPARE TYRE PANEL , PAN, REAR FLOOR        | 0.00 | \$630.30           | 0.00   | \$0.00            | Replace | Not Given | X |
|              |  |              | SEALANT SIKAFLEX                          | 0.00 | \$37.00            | 0.00   | \$0.00            | Replace | Not Given | X |
| <b>Total</b> |  |              |                                           |      | <b>\$38,311.90</b> |        | <b>\$8,520.25</b> |         |           |   |

| Added Spare Parts / Material Usage After Surveyor Signed off |         |              |                                |          |               |              |                  |           |                |
|--------------------------------------------------------------|---------|--------------|--------------------------------|----------|---------------|--------------|------------------|-----------|----------------|
| Part Number                                                  | Portion | Stock Number | Part Name                      | Quantity | List Price \$ | Discount (%) | Final Price (\$) | ARC Check | Surveyor Check |
|                                                              |         | 5211547050   | SUPPORT, FR BUMPER RH          | 1.00     | \$86.20       | 25.00        | \$64.65          | Replace   | Replace        |
|                                                              |         | 5211447190   | BRACKET, FR BUMPER             | 1.00     | \$111.80      | 25.00        | \$83.85          | Replace   | Replace        |
|                                                              |         | 5202147110   | REINFORCEMENT FRONT UPPER      | 1.00     | \$773.90      | 25.00        | \$580.43         | Replace   | Replace        |
|                                                              |         | 5321347050   | SUPPORT, RADIATOR UPPER RH     | 1.00     | \$85.20       | 25.00        | \$63.90          | Replace   | Replace        |
|                                                              |         | 6625947010   | COVER, REAR FLOOR UNDER CENTER | 1.00     | \$249.10      | 25.00        | \$186.83         | Replace   | Replace        |
| Total                                                        |         |              |                                |          | 1,306.20      |              | 979.66           |           |                |

9,499.91  
 + 1200.00  
 + 1480.00 L/S \$9,750/-  
 12,179.91  
 -20%  
 9,743.93