



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

HSBC LIFE (SINGAPORE) PTE LTD
10 MARINA BOULEVARD
#48-01 MARINA BAY FINANCIAL CENTRE TOWER
2SINGAPORE 018983
ATTN:VALE OH

Ref: CC4/ASM22009681/Rpa3q2

Date: 30/05/2023

Code: HSB

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SH 6506B	Veh. Inspected	SGB 404A
Policy No.	P2465714	Coverage (\$)	0.00
Claim No.	S2M04C2V	Excess (\$)	0.00
Assign From		Assign Date	03/10/2022

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ B180 STYLE	c.c	1595
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	WDD2462422J361292	Colour	BLACK
Odometer	92545 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R16	BRIDGESTONE	6 mm
L/H Front Tyre	205/55 R16	BRIDGESTONE	6 mm
R/H Rear Tyre	205/55 R16	BRIDGESTONE	6 mm
L/H Rear Tyre	205/55 R16	BRIDGESTONE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	30/09/2022	Inspection Date	03/10/2022
Survey held at	AUTO 101 LLP 2 YISHUN INDUSTRIAL STREET 1, #02-01, NORTH POINT BIZHUB, SINGAPORE 768159		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **5 Working Days**