



Auto 101 LLP

No. 2 Yishun Industrial St 1
 Northpoint Bizhub, #02-01
 Singapore 768159
 Tel: 67545101
 DATE: 3-10-2022

REPAIR ESTIMATE

VEHICLE: SGB 404 A
 MODEL: Mercedes B180

S/n	Description of part	Qty	Estimate
1	Front Door RH <i>Y</i> ✓		1,753.86 ✓
2	Front door rubber stripe RH <i>na</i> ✓		300.63 ✓
3	Front door lower hinge RH <i>7. X m</i>		135.75 X
4	side skirt RH clip - set <i>X m</i>		50.00 X
5	Front fender RH <i>repair</i>		753.34 XR
Sub-total 1			2,993.58
Less Discount 10%			2,694.22
6	Rim <i>300</i> ✓	1	850.00 <i>400 s/n 400</i>
Sub-total 2			850.00
Parts total			3,544.22
Labour			
7	To straighten and panel beating rear member. To remove and replace the above parts		700.00 <i>500</i>
8	To putty, re-spray painting and polish affected areas.		800.00 <i>600</i>
9	To transfer door components		120.00 <i>60</i>
10	To conduct electronic Alignment		150.00 <i>60</i>
11	To check and rectify wiring system.		80.00 <i>40</i>
12	To rust proof affected areas.		50.00 <i>30</i>
Labour total			1,900.00
Parts & Labour total			5,444.22

2058.49
10%
1849.04

1290

Repair
Hp 90010068
5 days
HS
03/10/22 @ 1700
Regy after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

1849.04
400.00
1290.00

3539.04
20%
2831.27
HS - \$2,800/5 days