

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0849/2022/EQ
DATE : 4-Oct-22
WIP : 44736

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 5/10/2022

Allianz Insurance Singapore Pte Ltd

79 Robinson Road

#09-01

Singapore 068897

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR AXEL BADER
ADDRESS : 33 KEPPEL BAY VIEW
#24-95
SINGAPORE 098419
TELEPHONE : HP +65 82015248
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : SP2001207703
VEHICLE NO : **SMJ 7843 G**
MODEL CODE : AUDI A3 SPORTBACK 1.0 TF
MODEL YEAR : 20/3/2019
ENGINE NO : CHZ C27715
CHASSIS NO : WAUZZZ8V0KA59576
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 29-Sep-22
PLACE OF ACCIDENT : KEPPEL BAY VIEW

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMJ 7843 G

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00 ✓	
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00 ✓	
3	TO DISMANTLE AND RENEW FRONT BUMPER AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,050.00 ✓ 700	
4	TO RESPRAY ^{Front} REAR BUMPER.	\$ 900.00 ✓ 700	
5	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ 2,852.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMJ 7843 G

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Repair</i>	1	\$ 2,146.00	<i>+</i>
2	FRONT BUMPER FIXING PARTS <i>new</i>	1	\$ 195.00	<i>+</i>
3	FRONT BUMPER GUIDE SECTION - RH <i>new</i>	1	\$ 43.00	<i>+</i>
4	FRONT BUMPER GRILLE - CENTER <i>new</i>	1	\$ 179.00	<i>+</i>
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>new</i>	1	\$ 332.00	<i>+</i>
6	FRONT BUMPER CLOSING ELEMENT - RH <i>new</i>	1	\$ 318.00	<i>+</i>
7	RADIATOR GRILLE <i>changed</i>	1	\$ 1,578.00	<i>✓</i>
8	RADIATOR GRILLE CLOSING ELEMENT <i>?</i>	1	\$ 210.00	<i>?</i> X NN
9	AIR CONDITIONER STICKER <i>new</i>	1	\$ 9.00	<i>✓</i> 8.30
10	CAUTION SIGN STICKER <i>new</i>	1	\$ 16.00	<i>✓</i> 15.50
11	FRONT BUMPER AIR GUIDE GRILLE - RH <i>new</i>	1	\$ 210.00	<i>+</i>
12	FRONT BUMPER REINFORCEMENT BEAM <i>new</i>	1	\$ 847.00	<i>+</i>
13	FRONT BUMPER FOAM FILLER PIECE	1	\$ 211.00	<i>+</i>
14	FRONT BUMPER TOP COVER <i>new</i>	1	\$ 136.00	<i>+</i>
15	HEADLIGHT - RH <i>new</i>	1	\$ 5,879.00	<i>+</i>
16	LIFT CYLINDER - RH <i>new</i>	1	\$ 156.00	<i>+</i>
17	LIFT CYLINDER HOSE	1	\$ 78.00	<i>+</i>
18	OUTSIDE TEMPERATURE SENSOR BRACKET <i>new</i>	1	\$ 21.00	<i>+</i>
19	RADIATOR AIR GUIDE - RH <i>new</i>	1	\$ 28.00	<i>+</i>
20	RADIATOR AIR GUIDE OUTER SEAL - RH	1	\$ 9.00	<i>+</i>
SUB TOTAL SPARE PARTS		:	\$ 12,601.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMJ 7843 G

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	RADIATOR AIR GUIDE - UPPER CENTRE <i>Not in</i>	1	\$ 14.00	<i>X</i>
22	FRONT NO PLATE <i>Dented</i>	S/N	\$ 60.00	<i>✓</i>
23	SUNDRIES <i>?</i>		\$ 400.00	<i>X</i> NN
TOTAL SPARE PARTS		:	\$ 13,075.00	
TOTAL LABOUR CHARGES		:	\$ 2,852.00	
GRAND TOTAL		:	\$ 15,927.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : Adrian
SURVEYED DATE : 05/10/22
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : Not Authorised, Excess To be advised.

03 Days

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT