

H C AUTO PTE LTD

160 Sin Ming Drive # 05-09 Sin Ming Auto City Singapore 575722

Tel : 6457 0678 Fax : 6457 8287

Co. and GST Reg. No. : 200820153N

Date : 29 / 09 / 2022

ESTIMATE COSTS OF REPAIR

Mr. Ng Jackie

C/o 160 Sin Ming Drive

05-09 Sin Ming Auto City

Singapore 575722

Dear Sir / Madam ,

Vehicle no. : SGV 7181 R - Honda Civic 2.0L A

Accident date : 28 / 09 / 2022

*Not Authorized
L1 Reg @ 520dp
Repair After Paint
6 days*

Quantity	Descriptions	Amount (S\$)
1 1 pc	boot lid <i>687</i>	\$ 1,090.70 ✓
2 1 pc	boot lid inner lock <i>194.90</i>	\$ 257.30 ✓
3 1 pc	boot lid lock catch	\$ 27.00 X
4 2 pcs	boot lid hinge 1 @ 255.00	\$ 510.00 X
5 2 pcs	boot lid hinge garnish 1 @ 200.00	\$ 400.00 X
6 1 pc	boot lid Honda logo	\$ 101.30 ✓
7 2 pcs	boot lid reflector 1 @ 184.80	\$ 369.60 X
8 2 pcs	boot lid no. plate lamp 1 @ 28.80	\$ 57.60 X
9 1 pc	boot lid no. plate lamp garnish	\$ 101.30 X
10 1 pc	boot lid inner trim	\$ 321.00 X
11 1 pc	boot lid weather strip	\$ 87.60 <i>508.1m 438.61m</i>
12 1 pc	rear bumper fascia <i>683.40</i>	\$ 801.20 ✓
13 2 pcs	rear bumper side retainer 1 @ 23.20	\$ 46.40 ✓
14 10 pcs	rear bumper clip 1 @ 3.50	\$ 35.00 ✓
15 1 pc	rear bumper lower lip	\$ 850.00 ✓
16 2 pcs	rear fender inner garnish 1 @ 314.00	\$ 628.00 X
17 1 pc	rear end panel	\$ 289.50 ✓
18 1 pc	rear end panel inner shield	\$ 145.00 X
19 2 pcs	tail lamps 1 @ 295.70	\$ 591.40 ✓
20 2 pcs	tail lamp panel 1 @ 159.40	\$ 318.80 X
21 1 pc	rear floor panel	\$ 911.40 X
22 1 pc	rear exhaust box <i>810.10</i>	\$ 3,500.00 ✓
23 1 pc	rear exhaust aluminium cover	\$ 191.00 X
24 1 pc	rear exhaust box center <i>1052.60</i>	\$ 1,800.00 X
25 6 pcs	rear exhaust mounting 1 @ 58.35	\$ 350.10 X
26 1 pc	rear windscreen glass molding	\$ 83.00 X
27 1 pc	rear spare tyre board	\$ 308.30 ✓
28 1 pc	rear spare tyre holder	\$ 19.80 X
		\$ 14,192.30
	Less 20 %	\$ 2,838.46
	Balance C/FD	\$ 11,353.84

*11.7 10.1 87.60 508.1m 438.61m
C/S R 611m 628.00 X*

H C AUTO PTE LTD

160 Sin Ming Drive # 05-09 Sin Ming Auto City Singapore 575722

Tel : 6457 0678 Fax : 6457 8287

Co. and GST Reg. No. : 200820153N

Balance B/FD (SGV7181R)

\$ 11,353.84

29	1 pc	rear end panel inner garnish (carbon)
30	1 pc	rear camera
31	1 pc	rear panel seal
32	4 pcs	rear reverse sensor 1 @ 226.90
33	1 pc	rear windscreen glass inner seal
34	1 pc	rear windscreen glass inner gum

\$	sn	350.00	sn	X
\$	sn	450.00	sn	X
\$	sn	250.00	sn	301sn
\$	sn	907.60	sn	2001sn
\$	sn	60.00	sn	X
\$	sn	60.00	sn	X

\$ 13,431.44

Labour charges
To putty and spray painting
To re-seal anti rust
To check wiring, & reset fault code
Remove rear exhaust box
Remove and refix rear reverse sensor
Remove and refix rear windscreen glass
Remove and refix rear cushion seat, garnish, carpet, etc

\$	2,200.00	7001
\$	2,000.00	8001
\$	200.00	602
\$	120.00	201
\$	180.00	801
\$	120.00	601
\$	160.00	X
\$	350.00	801

\$ 18,761.44

\$ 1,313.30

\$ 20,074.74

Plus: 7% GST

Grand total

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: