



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR22009689/Eny3m4 Date: 03/01/2023 Code: SMR	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SG 5818M	Veh. Inspected	SDZ 9111U
	Policy No.		Coverage (\$)	0.00
	Claim No.	BUS/09/22/7018	Excess (\$)	0.00
	Assign From	HUA YEN	Assign Date	03/10/2022
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	BMW 420I	c.c	1998
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	WBA4H32070BP27582	Colour	BLACK
	Odometer	44947 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	255/40R18	BRIDGESTONE	5 mm
	L/H Front Tyre	255/40R18	BRIDGESTONE	5 mm
	R/H Rear Tyre	255/40R18	BRIDGESTONE	5 mm
	L/H Rear Tyre	255/40R18	BRIDGESTONE	5 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	29/09/2022	Inspection Date	17/10/2022
	Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		12 Working Days	