



Supplementary

Estimate No. : **b1 63511**
Date Estimated : **03/10/2022**
Prepared By : **Inthiran A/L Thurasamy**

Page No. :

- ESTIMATE REPAIR FOR -

Quah Yew Kim, Sarah (Ke Youjin, Sarah)
4A Kew Drive

Singapore 465977

- ACCOUNT - 303

MS First Capital Insurance Limited
6 Raffles Quay
#21-00
Singapore 048580

REGN. NO.	CHASSI S NO.	REGN. DATE	MODEL	M LEAGE
SDZ9111U	WBA4H32070BP27582	01/11/2018	420i GC	45007

DESCRIPTION	ORIGINAL PRICE		NETT
* To spray paint rear bumper, rear RH fender, RH roof frame, tail end panel and RH rocker panel	3,888.00	0.00	3,888.00 ✓
* To remove and install boot compartment carpet and garnish to facilitate repairs	257.00	0.00	257.00 ✓
* To remove and install fuel tank to facilitate repairs including to extract fuel and conduct checks for leak	504.00	0.00	504.00 ✓

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# SNAP LOCK COUPLING	3.85	1.00	0.00 NEC	3.85 ✓
# EXPANDING NUT	0.55	1.00	0.00 NEC	0.55 ✓
# (DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	131.55	1.00	0.00 NEC	131.55 ✓
# (DG/SL) ADHESIVE PRIMER VP 206 (30ML)	27.85	1.00	0.00 NEC	27.85 ✓

SUPPLEMENTARY ITEMS

Total Labour :	4,649.00
Total Parts :	163.80
Total Labour & Parts :	4,812.80

Performance Motors Limited.

Sime Darby Performance Centre, 303 Alexandra Road

Tel: 1800-2255-269

Co Reg No. 197401559W

