

Hsiao Zong

CHOO MOTOR SPRAY PAINTER
1 KAKI BUKIT AVE 6 #01-39 AUTOBAY
SINGAPORE 417883

Not Authorised

3/10/22

L/3000
Hday

VEHICLE No: SJK 8361D

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1PC	BOOTLID	^^		\$1,266.10	X
1PC	BOOTLID REAR LOGO	^^		\$68.50	X
1PC	BOOTLID INNER LOCK	^^		\$409.10	X
1PC	BOOTLID LOCK STRICKER	^^		\$66.80	X
1PC	BOOTLID WEATHERSTRIP	^^		\$282.30	X
1PC	BOOTLID ANTENNA SENSOR	^^		\$366.10	X
1PC	REAR BUMPER	DD/cue	1450	\$1,655.10	—
2PCS	REAR BUMPER BRACKETS @105.00	o/s sent		\$210.00	1PC
2PCS	REAR BUMPER REFLECTORS @\$60.00	o/s sent		\$120.00	1PC
2PCS	REAR BUMPER SIDE RETAINERS @\$65.00	o/s sent		\$130.00	1PC
1SET	REAR BUMPER CLIPS	neu		\$50.00	—
1PC	REAR END PANEL	DD		\$788.20	—
1PC	REAR END PANEL TOP GARNISH	7m		\$362.30	—
2PCS	TAILLAMPS @\$580.00	^^		\$1,160.00	X
1PC	REAR FLOOR PANEL	^^		\$1,145.20	X
1PC	REAR FLOOR PANEL TOP BOARD	^^		\$420.50	X
				\$8,500.20	

(257)

S.NETT

1SET	REAR BUMPER REVERSE SENSOR	short	\$280.00	200
1PC	REAR END PANEL SEALANT	neu	\$50.00	✓
1SET	REAR FLOOR PANEL INSULATOR	^^	\$250.00	X

TO CHECK WIRING	\$50.00	20
TO DISMANTLE & REPLACED REVERSE SENSOR	\$80.00	50
TO DISMANTLE & REFIX BOOTLID MECHANISM	\$100.00	X
TO DISMANTLE & REFIX CUSHION UPHOLSTERY	\$120.00	80
TO SPRAY RUST PROOFING	\$100.00	30
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$1,000.00	600
TO PUTTY & SPRAY PAINTING	\$1,800.00	600
TOTAL	\$12,330.20	

P-2880-50
 252
 2160.37
 250
 1380
 3790.37