

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CC4/AIS22009694/Upa3

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: STD 91731C

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No: STD 9173K

Yr Regn:

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$

☐

: Preli. Report

☐

: Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL

PRECISE AUTO SERVICE

NO. 1 KAKI BUKIT AVE 6 #02-33/34/36 SINGAPORE 417883

TEL : 67457367 FAX : 68413390

CO. REG. NO. : 35766600C GST REG. NO. : 35766600C

19-11-2022

Date Of Accident : 21-09-2022

OUR REF : SJD 9173K/T/22

SIM TECK MENG
416 Yishun Ave 11
#07-367
Singapore 760416

Marcus.

Date in / out:

07/11/22 to 11/11/22

No of Authorised
dur
7/11/22
2/5 @ 1600
3 days.

ESTIMATE BILL ON VEH. NO. : SJD 9173K

MODEL : TOYOTA ALTIS

CHASSIS NO. : MR053ZEE106102663

LIST ITEM

Front Bumper	Deep cut	383.90	✓
Front Bumper Side Retainer LH	11	122.10	X
Front Bumper Clips 1 set	50 10 pcs @ 12.90	129.00	✓
Head Lamp LH	Scr	485.20	✓
Front Fender Emblum "VVTi"	11	83.75	✓
		1,203.95	
	Less Discount 25%:	300.99	
		902.96	

SPECIAL NETT ITEM

Sport Rim Assy (Front LH)	450 (4)	800.00	
---------------------------	---------	--------	--

LABOUR CHARGE

To Respray Affected Areas	400	600.00	
To Remove & Refix Front LH Sport Rim & Contact Wheel Balancing original	60	120.00	
TP renew Damaged Parts, Straighten & Repair And Aligned All Parts	350	580.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: Page 1 of 1

Date:

GST 7%:
TOTAL AMOUNT :

3,002.96
210.21
3,213.17

P-1002-81
257
752.13