

# TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub  
2 Kaki Bukit Ave 2  
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
E-Mail : sales@n51.com.sg  
Company Reg. No. : 200714616M  
GST Registration No. : 200714616M

MOHAMED ASIQ ALI S/O RAHAMATHULLA  
BLK 331 UBI AVE 1 #01-789  
SINGAPORE 400331

Contact : 90107831

## TAX INVOICE

Repair Code : CLM15679

Date in : 30/09/2022

Vehicle Num. : SNF2980K

Model : MITSUBISHI LANCER 2.0L MIVEC GT 6-CVT ABS D/AB HID

Chassis/Eng# : JMYSTCY4A9U001145/4B11CH1131

TP Chian.  
Veron.

### Parts and Labour Assessment

| Description of part                                    | Qty | Unit Price | Amount                   |
|--------------------------------------------------------|-----|------------|--------------------------|
| REAR BOOTLID <i>Dented</i>                             | 1   | 693.00     | ✓ 693.00                 |
| REAR BOOTLID 'GT' EMBLEM <i>3 per</i>                  | 1   | 40.00      | ✓ 40.00                  |
| REAR BOOTLID 'LOGO' EMBLEM                             | 1   | 41.80      | ✓ 41.80                  |
| REAR BOOTLID INNER TRIM GARNISH <i>torn</i>            | 1   | 267.00     | ✓ 267.00                 |
| REAR BOOTLID LOCK <i>Damaged</i>                       | 1   | 161.00     | ✓ 161.00                 |
| REAR BOOTLID LOCK STRIKER <i>Not m</i>                 | 1   | 30.00      | ✗ 30.00                  |
| REAR BOOTLID REFLECTOR BACK GASKET SEAL L/R <i>m m</i> | 2   | 20.00      | ✗ 40.00                  |
| REAR BOOTLID REFLECTOR L/R <i>LT cracked</i>           | 2   | 175.00     | 175.00 <del>350.00</del> |
| REAR BOOTLID WEATHER STRIP <i>cut</i>                  | 1   | 155.00     | ✓ 155.00                 |
| REAR BUMPER BEAM <i>Best</i>                           | 1   | 138.50     | ✓ 138.50                 |
| REAR BUMPER END SEAL COVER L/R <i>Not m</i>            | 2   | 48.00      | ✗ 96.00                  |
| REAR BUMPER REFLECTOR L/R <i>LT missing</i>            | 2   | 33.60      | 3360 <del>67.20</del>    |
| REAR BUMPER REINFORCEMENT <i>Dented</i>                | 1   | 210.00     | ✓ 210.00                 |
| REAR BUMPER SIDE RETAINER L/R <i>Damaged</i>           | 2   | 50.00      | ✓ 100.00                 |
| REAR BUMPER TOW HOOK COVER <i>Damaged</i>              | 1   | 22.00      | ✓ 22.00                  |
| REAR END PANEL <i>Dented</i>                           | 1   | 506.00     | ✓ 506.00                 |
| REAR END PANEL ANTENNA SENSOR <i>3 changed</i>         | 1   | 165.00     | ✓ 165.00                 |
| REAR END PANEL BUZZLE SENSOR                           | 1   | 119.70     | ✓ 119.70                 |

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

Kaki Bukit AutoHub  
 2 Kaki Bukit Ave 2  
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
 E-Mail : sales@n51.com.sg  
 Company Reg. No. : 200714616M  
 GST Registration No. : 200714616M

MOHAMED ASIQ ALI S/O RAHAMATHULLA  
 BLK 331 UBI AVE 1 #01-789  
 SINGAPORE 400331

Contact : 90107831

## TAX INVOICE

Repair Code : CLM15679

Date in : 30/09/2022

Vehicle Num. : SNF2980K

Model : MITSUBISHI LANCER 2.0L MIVEC GT 6-CVT ABS D/AB HID

Chassis/Eng# : JMYSTCY4A9U001145/4B11CH1131

|                                              |                    |   |         |      |          |
|----------------------------------------------|--------------------|---|---------|------|----------|
| REAR END PANEL INNER TOP GARNISH             | <i>Del'd</i>       | 1 | 191.00  | ✓    | 191.00   |
| REAR EXHAUST SILENCER GASKET                 | <i>new</i>         | 1 | 23.00   | ✓    | 23.00    |
| REAR EXHAUST SILENCER HEAT SHIELD COVER      | <i>coupled</i>     | 1 | 195.00  | ✓    | 195.00   |
| REAR EXHAUST SILENCER RUBBER MOUNTING        | <i>new</i>         | 2 | 55.00   | ✗    | 110.00   |
| REAR FENDER INNER TRIM GARNISH L/R           | <i>torn</i>        | 2 | 266.70  | ✓    | 533.40   |
| REAR NUMBER PLATE LAMP L/R                   | <i>new missing</i> | 2 | 65.00   | ✓    | 130.00   |
| REAR SPARE TYRE BOARD                        | <i>torn</i>        | 1 | 222.90  | ✓    | 222.90   |
| REAR TAILLAMP L/R                            | <i>coupled</i>     | 2 | 320.00  | ✓    | 640.00   |
| REAR TAILLAMP PANEL L/R                      | <i>Dented</i>      | 2 | 95.00   | ✓    | 190.00   |
| Subtotal before discount                     |                    |   |         |      | 5,437.50 |
| Percentage discount 10%                      |                    |   |         |      | 543.75   |
| Sub-total 1                                  |                    |   |         |      | 4,893.75 |
| REAR BOOTLID INNER TRIM GARNISH CLIPS - SET  | <i>new</i>         | 1 | 40.00   | 30   | 40.00    |
| REAR BUMPER ASSY                             | <i>Distorted</i>   | 1 | 2200.00 | 1000 | 2200.00  |
| REAR BUMPER CLIPS - SET                      | <i>new</i>         | 1 | 50.00   | 30   | 50.00    |
| REAR BUMPER REVERSE SENSOR                   | <i>Damaged</i>     | 1 | 250.00  | 200  | 250.00   |
| REAR END PANEL INNER TOP GARNISH CLIPS - SET | <i>new</i>         | 1 | 30.00   | 20   | 30.00    |
| REAR END PANEL SEALANT                       | <i>Nec</i>         | 1 | 100.00  | 60   | 100.00   |

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

Kaki Bukit AutoHub  
2 Kaki Bukit Ave 2  
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
E-Mail : sales@n51.com.sg  
Company Reg. No. : 200714616M  
GST Registration No. : 200714616M

MOHAMED ASIQ ALI S/O RAHAMATHULLA  
BLK 331 UBI AVE 1 #01-789  
SINGAPORE 400331

Contact : 90107831

## TAX INVOICE

Repair Code : CLM15679  
Date in : 30/09/2022  
Vehicle Num. : SNF2980K  
Model : MITSUBISHI LANCER 2.0L MIVEC GT 6-CVT ABS D/AB HID  
Chassis/Eng# : JMYSTCY4A9U001145/4B11CH1131

|                                                |   |         |           |
|------------------------------------------------|---|---------|-----------|
| REAR EXHAUST SILENCER BOX ASSY                 | 1 | 2300.00 | 2,300.00  |
| REAR FENDER INNER TRIM GARNISH CLIPS L/R - SET | 2 | 50.00   | 100.00    |
| REAR NUMBER PLATE                              | 1 | 25.00   | 25.00     |
| REAR SPARE TYRE PANEL INSULATOR PAD            | 1 | 250.00  | 250.00    |
| REAR TAILLAMP CLIPS L/R - SET                  | 2 | 20.00   | 40.00     |
| Subtotal before discount                       |   |         | 5,385.00  |
| Percentage discount 0%                         |   |         | 0.00      |
| Sub-total 2                                    |   |         | 5,385.00  |
| Parts-total                                    |   |         | 10,278.75 |

## LABOUR

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.  
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)  
To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare tyre panel and rear bumper.  
To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.  
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.  
To apply anti-rust chemical on repaired and replaced panel.

Labour Total

Parts & Labour Total

3,450.00

13,728.75

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

page 3

Total: 8079.91

Ys: 6.4K

07 Days.

0.7 Days