

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: JANICE KOH

Date: 05 Oct 2022

Preliminary Advice

Vehicle No	: SLG1485Z	Accident Date	: 30/09/2022
Make	: MERCEDES-BENZ E200	Policy No.	: SP2002495301-01
Assignment Date	: 03/10/2022	Excess	: S\$0.00
Date of Inspection	: 04/10/2022	Est. Duration of Repair	: 5
Inspection At	: KAN FOOK SING MOTOR WORKSHOP (DEFU) BLK 8 DEFU SOUTH STREET 1, DEFU INDUSTRIAL CITY #04-29 SINGAPORE 533758		

Point of Impact / General Description of Damages

Parts claimed are not consistent to the accident.

Repairer's Estimate (Gross)	:S\$	18,287.10
Revised Amount	:S\$	10,512.80
Check Items (Estimated)	:S\$	7,107.10
Total	:S\$	17,619.90

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	120,000.00
COE / PARF Rebate	:S\$	68,210.00
Salvage Value	:S\$	
Margin for Repair	:S\$	51,790.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments :the vehicle repair on part by parts basis.due to no 2nd hand parts available.
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.