# Note: This document has not been finalised. LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.

79 Robinson Road #09-01 Singapore 068897 From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: JANICE KOH Date: 14 Mar 2023

## **Preliminary Advice**

 Vehicle No
 : SLG1485Z
 Accident Date
 : 30/09/2022

 Make
 : MERCEDES-BENZ E200
 Policy No.
 : SP2002495301-01

Assignment Date : 03/10/2022 Excess : \$\$0.00 Date of Inspection : 04/10/2022 Est. Duration of Repair : 5

Inspection At : KAN FOOK SING MOTOR WORKSHOP (DEFU)

BLK 8 DEFU SOUTH STREET 1, DEFU INDUSTRIAL CITY #04-29

SINGAPORE 533758

### Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	19,180.85 (Estimate \$18,287.10 + Supplementary \$893.75)
Revised Amount	:S\$	12,327.25 (Inclusive of supplementary)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	12,327.25

:S\$

#### **Total Loss Consideration**

Lump Sum Repair

New for Old Value	:S\$	
Pre-Accident Value	:S\$	120,000.00
COE / PARF Rebate	:S\$	68,210.00
Salvage Value	:S\$	

Margin for Repair :S\$ 51,790.00

#### Remarks

( X )	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
( )	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
( X )	Other comments: KINDLY APPROVE ON SUPPLEMENTARY.