

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	AXA INSURANCE	PTE LTD	Ref:	CS/ASM22009704/Ucy3m4	
	8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811		Date:	17/10/2022	
	ATTN: LOH CYNTH	HIA	Code:	ASM	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLE 2B	Veh. Inspected	SLB 9294G	
	Policy No.	GA512427	Coverage (\$)	0.00	
	Claim No.	S2M04C1U	Excess (\$)	0.00	
	Assign From	LOH CYNTHIA	Assign Date	03/10/2022	
2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA ESTIMA (A)	c.c	2362	
	Engine No.	HIDDEN	Year of Reg.	2006	
	Chassis No.	ACR507004257	Colour	SILVER	
	Odometer	332170 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	215/55 ZR17	HABILEAD	6 mm	
	L/H Front Tyre	215/55 ZR17	HABILEAD	6 mm	
	R/H Rear Tyre	215/55 ZR17	HABILEAD	6 mm	
	L/H Rear Tyre	215/55 ZR17	HABILEAD	6 mm	
4.					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR & FRONT PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	30/09/2022	Inspection Date	03/10/2022	
	Survey held at SPEEDWERKZ PTE LTD				
	13 KAKI BUKIT ROAD 4, #01-20, BARTLEY BIZ CENTRE, SINGAPORE 417807				
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 10 Working Days				