

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: JANICE KOH

Date: 13 Jan 2023

Preliminary Advice

Vehicle No	: SMY9993P	Accident Date	: 07/09/2022
Make	: MERCEDES-BENZ E200	Policy No.	: SP2001903858-01
Assignment Date	: 03/10/2022	Excess	: S\$600.00
Date of Inspection	: 04/10/2022	Est. Duration of Repair	: 04 DAYS
Inspection At	: PREMIUM AUTOCARE		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,860.00 (Est \$10,460.00 + Supp \$400)
Revised Amount	:S\$	5,251.00 (Rev \$5,051 + Supp \$200)
Check Items (Estimated)	:S\$	575.00
Total	:S\$	5,826.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	218,000.00
COE / PARF Rebate	:S\$	88,517.00
Salvage Value	:S\$	
Margin for Repair	:S\$	129,483.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Kindly approve on Supplementary.
Part by Part repair.
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.