

PREMIUM AUTOCARE

24 BENOI SECTOR, SINGAPORE 629857
TEL : 6474 3323 FAX : 6264 6786
EMAIL: CLAIMS@PREMIUMAUTOCARE.COM.SG

ESTIMATE	:	ACCIDENT REPAIRS
WORKSHOP	:	24 BENOI SECTOR
CONTACT NO	:	6474 3323
FAX NO	:	6264 6786
REFERENCE	:	PAC/OD/0064/2022/GW
DATE	:	14-Sep-22
WIP	:	

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

ALLIANZ INSURANCE SINGAPORE PTE LTD
79 Robinson Road
#09-01
Singapore 068897

ATTN: MOTOR CLAIMS DEPT
Tel: 6297 2529 Fax: 6297 1956

OWNER'S NAME	:	MR. FAT SIONG TJIA
ADDRESS	:	9A PASIR RIS DRIVE 4 #02-20 SINGAPORE 519463
TELEPHONE	:	(HP) 94882551
TYPE OF CLAIM	:	OWN DAMAGE CLAIM
POLICY NO	:	SP2001903858-01
VEHICLE NO	:	SMY 9993 P
MODEL CODE	:	MERCEDES E200
MODEL YEAR	:	30/9/2021
ENGINE NO	:	
CHASSIS NO	:	W1K2130808A968674
MILEAGE	:	-
DATE IN	:	
ESTIMATED BY	:	ALLAN WU
ACCIDENT DATE	:	7-Sep-22
PLACE OF ACCIDENT	:	CHANGI VILLAGE RD



PREMIUM AUTOCARE

24 BENOI SECTOR, SINGAPORE 629857

TEL : 6474 3323 FAX : 6264 6786

EMAIL: CLAIMS@PREMIUMAUTOCARE.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMY 9993 P

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.	S/N	\$ 100.00	X
2	TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS.	S/N	\$ 100.00	80
3	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.		\$ 600.00	200
4	TO RESPRAY REAR BUMPER AND REAR LID.		\$ 600.00	200
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N	\$ 100.00	/
TOTAL LABOUR CHARGES		:	\$ 1,500.00	

PREMIUM AUTOCARE

24 BENOI SECTOR, SINGAPORE 629857
 TEL : 6474 3323 FAX : 6264 6786
 EMAIL: CLAIMS@PREMIUMAUTOCARE.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMY 9993 P

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
		S/NETT		
1 REAR LID / <i>OK</i>	1	\$	3,600.00	
2 REAR LID LOGO / <i>NE</i>	1	\$	70.00	
3 REAR LID EMBLEM 'E200' / <i>NE</i>	1	\$	120.00	
4 REAR LID HANDLE STRIP / <i>?</i>	1	\$	250.00	
5 REAR LID CHROME TRIM / <i>OK</i>	1	\$	220.00	
6 REAR LID WEATHER STRIP <i>X</i>	1	\$	350.00	
7 REAR BUMPER <i>X</i>	1	\$	3,725.00	
8 REAR BUMPER SIDE GUIDE - LH / RH <i>X</i>	2	\$	265.00	
9 REAR PLATE NO. <i>X</i> / <i>OK</i>	S/N	\$	60.00	
10 SUNDRIES / <i>?</i>		\$	300.00	
TOTAL PARTS CHARGES		:	\$	8,960.00
TOTAL LABOUR CHARGES		:	\$	1,500.00
GRAND TOTAL		:	\$	10,460.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.

*Cost + 10%
 Invoice*

PREMIUM AUTOCARE

24 BENOI SECTOR, SINGAPORE 629857

TEL : 6474 3323 FAX : 6264 6786

EMAIL: CLAIMS@PREMIUMAUTOCARE.COM.SG

NAME

:

Sten (LKK)

SURVEYED DATE

:

4/10/11, 10:30am

AUTHORISED DATE

:

EXCESS COST

:

0 D - L AL

LIABILITY

:

REMARKS

:

Excess - ?

PIP, My B. G, 3 days

PLEASE NOTE

:

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6474 3323 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOCARE CENTRE

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT