

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241

Fax: (65) 6741 7276

RCB No: 53231488C

GST Reg No : 53231488C

Blk 1 Kaki Bukit Ave 6

27/09/2022

01-43

Singapore 417883

Accident date : 16/06/2022

Estimated repair cost for vehicle no: GBH9782B TOYOTA DYNA 150 5 MT

CHASSIS: JTFAT35Y90K211706 (2018)

S/N	Qty	Items	U/price	Amount
1	1	REAR TAILGATE LOWER END PANEL <i>Repair</i>	\$898.40	\$898.40 +
2	1	REAR TAILGATE CROSS MEMBER <i>Repair</i>	\$750.00	\$750.00 +
3	2	REAR TAILLAMP PANEL <i>new</i>	\$248.20	\$496.40 +
4	2	REAR TAILLAMP PANEL <i>new</i>	\$259.10	\$518.20 +
5	1	REAR NUMBER PLATE PANEL <i>Best</i>	\$127.30	\$127.30 ✓
6	2	REAR NUMBER PLATE LAMP <i>new</i>	\$98.10	\$196.20 +
7	1	REAR SPARE TYRE LOCK <i>new</i>	\$283.10	\$283.10 +

375.50
281.62

TOTAL : \$3,269.60
LESS 25 % \$817.40
SUB-TOTAL : \$2,452.20

GBJ2424X TOYOTA DYNA 150 5MT

S/N	Qty	ITEMS / SPECIAL NETT	U/price	Amount
1	1	REAR TAILGATE LH <i>new</i>	\$3,200.00	\$3,200.00 +
2	1	REAR TAILGATE RH <i>Defect</i>	\$3,200.00	\$3,200.00 +
3	1	REAR TAILGATE LOCK LH <i>new</i>	\$1,200.00	\$1,200.00 +
4	1	REAR TAILGATE LOCK RH <i>Best</i>	\$1,200.00	\$1,200.00 +
5	1	REAR TAILGATE ADVISTERMENT STICKER <i>new</i>	\$1,800.00	\$1,800.00 +

- REVERSE SENSOR - \$350.00 *new*
- REVERSE SENSOR BRACKETS. *Best*

TOTAL: \$10,600.00
TOTAL PARTS: \$13,052.20

Labour charges

- LABOUR FOR PANEL BEATING
- LABOUR FOR SPRAYPAINTING
- WIRING CHECK
- TO APPLY TUFF COATING/RUST PROOF ACCIDENT AREAS
- LABOUR FOR REMOVE & RENEW REAR REAR TAILGATE
- LABOUR FOR REPAIR & STRAIGHTEN BOTH REAR CHASSIS FRAME

Adnan L
H/s 27/09/22.
OH Dyp
\$1,500.00
\$1,600.00
\$80.00
\$300.00
\$800.00
\$500.00

LKK Auto Consultants has advised the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total 4501.62
H/s! 3.6K
3.6K

Subtotal :- \$4,780.00
Total:- \$17,832.20