



Repair Estimate

VAG Singapore Pte Ltd

48 Toh Guan Road East

#05-136, Enterprise Hub

Singapore 608586

Tel: 6267 9916

Fax: 6267 9313

www.avantage.sg

Date : 29-Sep-2022

Vehicle Num : SME8891L

Make/Model : Mercedes Benz C180 Avantgrade (R17 LED)

Chassis No : WDD2050402R401442

S/N	PARTS	QTY	PRICE	TOTAL
1	RH Front Fender	1	\$ 792.68	\$ <i>bt</i> 792.68
2	RH Front Fender Shield	1	\$ 111.60	\$ <i>m</i> 111.60
3	Front Bumper	1	\$ 1,566.89	\$ <i>de</i> 1,566.89
4	RH Mounting Rail, Front Bumper	1	\$ 18.92	\$ <i>de</i> 18.92
5	RH Sensor, Outer	1	\$ 171.29	\$ <i>cut</i> 171.29
6	Ring Seal, Sensor	1	\$ 9.96	\$ <i>re</i> 9.96
7	RH Headlight	1	\$ 2,700.66	\$ <i>cut</i> 2,700.66
8	RH Front Wheel Rim	1	\$ 904.20	\$ <i>Ry</i> 904.20
				<i>SN 180</i>
<div style="border: 1px solid blue; padding: 5px; margin: 10px;"> <p><u>LKK Auto Consultants</u> hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: _____ Date: _____</p> </div>				
	TOTAL PARTS			\$ 6,276.20
	Less 10%			\$ 627.62
	TOTAL AMOUNT			\$ 5,648.58
MISCELLANEOUS ITEM				
1	Sunderies		\$ 30.00	\$? 30.00
2	Tuff Kote		\$ 25.00	\$ <i>✓</i> 25.00
LABOUR				
1	Remove and refit RH Front Fender, Shield, Bumper, Mount Rail, Sensor, Headlight and other associate components.		\$ 600.00	\$ <i>300</i> 600.00
2	Surface preparation, spray paint and polish RH Front Fender, Bumper, Sensor, and other affected areas.		\$ 600.00	\$ <i>450</i> 600.00
3	Remove, refit & balance RH Front Wheel Rim		\$ 30.00	\$ <i>✓</i> 30.00
4	Check & adjust Wheel alignment		\$ 100.00	\$ <i>80</i> 100.00
5	Diagnostic check and erase fault codes after the repair.		\$ 80.00	\$ <i>✓</i> 80.00
<p><i>Tan Jiah 97495149 / 62565561</i> <i>5/10/22 @ 130pm</i> <i>tanjiah@lkhauto.com</i> <i>ply Resurvey before paint</i> <i>3-4 days</i></p>				
	TOTAL			\$ 7,113.58
	GST 7%			\$ 497.95
	GRAND TOTAL			\$ 7,611.53

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Actual Driver**
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	29/09/2022 15:23 (SGT)
Reported by	Both
Date of Accident	28/09/2022 19:40 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	ALONG NORTH CANEL ROAD
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SME8891L
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	THAM KONG YANG
NRIC No	SXXXX502A
Email Address	KONGYANG.THAM@GMAIL.COM
Mobile Phone No	(Phone) +65-92716745
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Mercedes
Model	C180
Variant	AVANTGARDE (R17 LED)
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1595

INSURANCE COMPANY

Name of Insurance Company	Direct Asia Insurance (Singapore) Pte Ltd
Policy Number / Cover Note Number	MT/01032506

DRIVER

Name of Driver	THAM KONG YANG
NRIC No	SXXXX502A
Date Of Birth	30/09/1976
Occupation	Indoor

Date Of Driving Pass	07/10/1997
Driving experience	24 YEARS AND 11 MONTHS
Gender	Male
Mobile Number	(Phone) +65-92716745
Alt. Phone Number	-
Email Address	KONGYANG.THAM@GMAIL.COM
Address	9 SOPHIA ROAD #07-19
Address complement	-
Postcode	228193
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collided into Parked Vehicle
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

PLEASE REFER TO THE STATEMENT

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLT7280P
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-

Accident Toolkit

Sketch plan

Sketch of accident scene

Please illustrate the layout of roads with arrows showing the direction and position of vehicles at the time of impact. Also please note the road names, road signs and vehicle registration numbers.

If safe, please take photos or videos from all angles

My car (SLT7200P) was parked waiting
at the intersection of road 7 and road 5

When car SLT7200P was hit by the
side of my car, resulting in

✓ damaged four pumps, left foot into
panel & foot right lamp



Please indicate on vehicle A (your vehicle) and, vehicle B (third party vehicle), the point of impact and area(s) of visible damage with an arrow.



Vehicle A
SME7391L



Vehicle B
SLT7200P

direct
asia
Insurance

Call us direct
Customer Care
6665 5555
Claims Support 24/7 helpline
6532 1818
AN EXACT COPY OF THIS PAGE