



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDING SINGAPORE 048581			Ref: CS/FCI22009715/Tqy3e2 Date: 13/04/2023 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 1296P	Veh. Inspected	SKM 4936A	
Policy No.	D-210098513MSH	Coverage (\$)	0.00	
Claim No.	D220003007MSH	Excess (\$)	0.00	
Assign From	JOANNE TAN JO ANN	Assign Date	03/10/2022	
2. Vehicle Particulars & Condition				
Make & Model	VOLKSWAGEN GOLF	c.c	1395	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	WVWZZZAUZEW249056	Colour	SILVER	
Odometer	81852 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/40 R18	GOODYEAR	6 mm	
L/H Front Tyre	225/40 R18	GOODYEAR	6 mm	
R/H Rear Tyre	225/40 R18	GOODYEAR	6 mm	
L/H Rear Tyre	225/40 R18	GOODYEAR	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	23/09/2022	Inspection Date	05/10/2022	
Survey held at	48 TOH GUAN ROAD EAST #05-155 ENTERPRISE HUB			
Repairer	VAG SINGAPORE PTE LTD			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			7 Working Days	