



VAG Singapore Pte Ltd
48 Toh Guan Road East
#05-136, Enterprise Hub
Singapore 608586

Repair Estimate

Tel: 6267 9916
claims@vag.sg
www.avantage.sg

Date: 28-Sep-2022

Vehicle Num: SKM4936A

Make/Model: VW GOLF 1.4

Chassis No: WVVZZZAUZEW249056

S/N	PARTS	QTY	PRICE	TOTAL
1	Rear end panel	1	\$ 536.25	\$ 536.25
2	Rear bumper bracket (center)	1	\$ 57.75	\$ 57.75
3	Rear bumper bracket Lh	1	\$ 32.00	\$ 32.00
4	Rear bumper bracket Rh	1	\$ 39.65	\$ 39.65
5	Rear bumper retainer Lh	1	\$ 32.00	\$ 32.00
6	Rear bumper retainer Rh	1	\$ 32.00	\$ 32.00
7	Rear bumper reinforcement	1	\$ 429.25	\$ 429.25
8	Rear bumper	1	\$ 891.25	\$ 891.25
9	Rear bumper diffuser	1	\$ 288.75	\$ 288.75
10	Rear bumper light reflector Lh	1	\$ 49.50	\$ 49.50
11	Rear tail light (outer) Lh	1	\$ 227.70	\$ 227.70
12	Rear tail light (inner) Lh	1	\$ 206.25	\$ 206.25
13	Rear number plate lamp	1	\$ 25.00	\$ 25.00
14	Rear bumper parking sensor	2	\$ 150.00	\$ 300.00
15	Rear tailgate	1	\$ 1,485.55	\$ 1,485.55
16	Rear tailgate vw open micro switch	1	\$ 495.25	\$ 495.25
17	Rear tailgate lock	1	\$ 189.75	\$ 189.75
18	Rear tailgate seal	1	\$ 264.25	\$ 264.25
19	Rear tailgate trim panel	1	\$ 231.55	\$ 231.55
20	Rear tailgate emblem (golf)	1	\$ 68.40	\$ 68.40
21	Rear tailgate emblem (bluemotion technology)	1	\$ 74.25	\$ 74.25
22	Rear tailgate emblem (tsl)	1	\$ 74.25	\$ 74.25
23	Rear exhaust pipe (center)	1	\$ 415.80	\$ 415.80
24	Rear exhaust dual clip	1	\$ 49.50	\$ 49.50
25	Rear exhaust silencer	1	\$ 660.00	\$ 660.00
26	Rear exhaust silencer bracket	1	\$ 45.00	\$ 45.00
LKK Auto Consultants hence notify the Repairer of the following:				
• To resurvey before/after spray painting				
• To display damaged part(s) during resurvey				
• Parts prices are subject to confirmation				
• Third party survey is on a "Without Prejudice" basis				
• No illegal modification(s) is allowed				
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company				
ACKNOWLEDGED BY REPAIRER				
Signature:				
DATE:				
LABOUR				
1	Removal, refitting and panel beating of rear bumper, rear tailgate, rear fender Lh, rear end panel and affected panels		\$ 1,500.00	\$ 1,500.00
2	Surface preparation, spray paint and detailing of rear bumper, rear tailgate, rear end panel, rear fender Lh, Rh and other affected area.		\$ 1,500.00	\$ 1,500.00
3	Diagnostics, check wiring, connector and clearing of faults after repair		\$ 80.00	\$ 80.00
4	Remove and refit rear parking sensor to assist repair		\$ 20.00	\$ 20.00
5	Remove and refit rear windscreen glass to assist repair		\$ 120.00	\$ 120.00
6	Remove and refit rear exhaust pipe system		\$ 200.00	\$ 200.00
TOTAL				\$ 10,283.81
GST 7%				\$ 719.87
GRAND TOTAL				\$ 11,003.68

Supp
Rear top gemish
Trim light RH
wiring
names

149.60
22.88
176.22

bt
de
de

bt

379.50
379.50
dis 25
300

bt

nt

5592.15
5032.93

125

1820

\$6977.93

7 days
#

tanjiah e.khams.com
Bendahara