

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI22009720/TQY3Q2**Date:** 28/11/2022REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MP003138		
Claimant Vehicle No :	SHA3255L	Insured Vehicle No :	SNE5057L		
Date of Loss:	29/09/2022	Nature of Claim:	TP	Claim No:	M2205445

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA3255L	Engine No:	2ZR2C27274
Make & Model:	TOYOTA PRIUS TAXI, 1.8 (A)	Chassis No:	JTDBK3FUX03081246
Reg. Date:	31/05/2019 (Man. Year: 2018)	Odometer:	515520 km
Colour:	Blue		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Excellent	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,685.51	669.74	1,015.77	60.26
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	970.00	630.00	340.00	35.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,666.51	1,310.74	1,355.77	50.84
Approved Total (Overridden) (S\$)		1,050.00		
(S\$)	2,666.51	1,050.00	1,616.51	60.62
+ GST 7.00/7.00% (S\$)	186.66	73.50	113.16	60.62
Nett Amount (S\$)	2,853.17	1,123.50	1,729.67	60.62

INSPECTION

Date of Assignment:	03/10/2022	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	04/10/2022	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Nov 2022)
Parts:	144	TOYOTA PRIUS TAXI 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHA3255L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	503.04 FL	*- FL
2	1		*REAR BUMPER LOWER MOULDING	Deformed	654.96 FL	*654.96 FL
3	1		*REAR BUMPER REINFORCEMENT	Not Necessary	378.32 FL	*- FL
4	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
5	1		*REAR BUMPER TOWING COVER	Deformed	82.70 FL	*82.70 FL
6	2		*REAR BUMPER SIDE RETAINER	Not Necessary	225.40 FL	*- FL
7	1		*REAR BUMPER MAT	Not Necessary	50.00 FS	*- FS
8	1		*REAR BUMPER ADVERTISEMENT	Cut	100.00 FS	*100.00 FS
9	1		*REAR BUMPER SENSOR	Not Necessary	135.70 FS	*- FS
						F=Franchise part. S=SpcNett. L=ListItemDisc.
Sub Total (\$\$)					2,152.12	859.66
- List Item Discount on L Items 25.00/25.00% (\$\$)					466.61	189.92
Total Parts (\$\$)					1,685.51	669.74

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	550.00	350.00
2	SPRAY PAINTING	New	300.00	250.00
3	REMOVE/REFIX REVERSE SENSOR	New	60.00	30.00
4	TUFF COATING	New	60.00	0.00
Gross Labour Cost (\$\$)			970.00	630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >