

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Douglas Ong Chu Chong

Date: 12 Oct 2022

## **Preliminary Advice**

Insured Vehicle No : SMM4485K

TP Vehicle No : SLL9014X

Make : HONDA HR-V

Date of Inspection : 04/10/2022

Inspection At : MS CAR AUTO PTE LTD

Accident Date : 30/09/2022

Assignment Date : 04/10/2022

Est. Duration of Repair : 04 DAYS

### **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,127.28
Revised Amount	:S\$	3,629.76
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,629.76
Lump Sum Repair	:S\$	2,900.00

### **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

### **Remarks**

- ( ) The vehicle is economical for repair
- ( ) The vehicle is not economical for repair
- ( ) Part-by-Part repair
- ( X ) Lump Sum repair

- ( X ) The above survey was conducted on a 'without prejudice' basis.

Please note that the preliminary advice amount (Revised) stated are subject to consistency check, part prices and labour cost.