

Not withain
Return B4 paint

AAD2209-

11 Lump @ 1500p

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5322Y

Vehicle No.:

28 SEP 2022

SHD5322Y

Chassis No.:

JTDKB3FU603078747

Co UEN:

200303878K

Vehicle Make:

TOYOTA

Vehicle Model:

PRIUS

Date of Accident :

26/09/2022

Third Party Insurer :

SNB182G/AIG

Date of Registration:

11/01/2019

	PART		LIST	
1	COVER, FRONT BUMPER	\$	Bu 516.00	✓
1	FRONT BUMPER SIDE RETAINER RH	\$	Di 80.10	✓
1	REINFORCEMENT SUB-ASSY, FRONT BUMPER	\$	R 716.60	X
1	ABSORBER, FRONT BUMPER ENERGY	\$	su 79.60	X
1	LAMP ASSY, FOG, RH	\$	W 951.40	✓
1	UNIT ASSY, HEADLAMP, RH	\$	su 2,637.60	X
1	COVER, FRONT BUMPER HOLE, RH	\$	su 29.30	X
1	JAR ASSY, WINDSHIELD WASHER	\$	su 219.10	X
1	GRILLE SUB-ASSY, RADIATOR	\$	su 346.00	X
1	EMBLEM ASSY, RADIATOR GRILLE	\$	su 90.80	X
1	GRILLE, RADIATOR, LOWER NO.1	\$	su 170.10	X
1	FENDER SUB-ASSY, FRONT RH	\$	R 977.80	X
1	LINER, FRONT FENDER, RH	\$	su 206.70	X
1	FRONT FENDER EMBLEM RH	\$	su 54.60	X
TOTAL		\$	7,075.70	
25%		\$	1,768.93	
		\$	5,306.78	

Special Nett

1	FRT BUMPER CLIP	\$	su 65.00	60su
1	FRT NUMBER PLATE WITH HOLDER	\$	su 120.00	X
1	FRT BUMPER SIDE RETAINER CLIP	\$	su 65.00	X
1	FENDER LINER CLIP	\$	su 75.00	X
TOTAL		\$	325.00	

TOTAL PARTS \$ 5,631.78

LABOUR

Trans-cab Auto Services Pte Ltd

AAD2209-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5322Y

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	<i>nn</i> 250.00	<i>X</i>
Putty And Spray Painting Of The Affected Portion.	\$	1,800.00	<i>4401</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i> 380.00	<i>X</i>
To Check Electrical Lighting Concerned.	\$	170.00	<i>201</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,000.00	<i>2001</i>
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00	<i>X</i>
To transfer of rear fender panel fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00	<i>X</i>
TOTAL	\$	4,990.00	
Over All Total	\$	10,621.78	

(PART-BY-PART) Repair Days

20 Days

2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: