

*Not Authorised
 Return By paint
 11 Sep @ 1500h*

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111
 Tel No. : 6287 6666 Fax No. : 6257 1330
 CO./GST Reg. No. 201019626G
SHD5322Y

AAD2209-

Vehicle No.: *28 SEP 2022*
 Chassis No.:
 Co UEN:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :
 Date of Registration:

SHD5322Y
 JTDKB3FU603078747
 200303878K
 TOYOTA
 PRIUS
 26/09/2022
SNB182G/AIG
 11/01/2019

PART	LIST		
1 COVER, FRONT BUMPER	Bu	\$ 516.00	✓
1 FRONT BUMPER SIDE RETAINER RH	Di	\$ 80.10	✓
1 REINFORCEMENT SUB-ASSY, FRONT BUMPER	R	\$ 716.60	X
1 ABSORBER, FRONT BUMPER ENERGY	su	\$ 79.60	X
1 LAMP ASSY, FOG, RH	su	\$ 951.40	✓
1 UNIT ASSY, HEADLAMP, RH	su	\$ 2,637.60	X
1 COVER, FRONT BUMPER HOLE, RH	su	\$ 29.30	X
1 JAR ASSY, WINDSHIELD WASHER	su	\$ 219.10	X
1 GRILLE SUB-ASSY, RADIATOR	su	\$ 346.00	X
1 EMBLEM ASSY, RADIATOR GRILLE	su	\$ 90.80	X
1 GRILLE, RADIATOR, LOWER NO.1	su	\$ 170.10	X
1 FENDER SUB-ASSY, FRONT RH	R	\$ 977.80	✓
1 LINER, FRONT FENDER, RH	su	\$ 206.70	X
1 FRONT FENDER EMBLEM RH	su	\$ 54.60	X
TOTAL		\$ 7,075.70	
25%		\$ 1,768.93	
		\$ 5,306.78	

Special Nett

1 FRT BUMPER CLIP	\$	65.00	✓
1 FRT NUMBER PLATE WITH HOLDER	\$	120.00	X
1 FRT BUMPER SIDE RETAINER CLIP	\$	65.00	X
1 FENDER LINER CLIP	\$	75.00	X
TOTAL	\$	325.00	

TOTAL PARTS \$ 5,631.78

LABOUR

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5322Y

AAD2209-

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	<i>nn</i>	250.00	<i>X</i>
Putty And Spray Painting Of The Affected Portion.	\$		1,800.00	<i>4401</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i>	380.00	<i>X</i>
To Check Electrical Lighting Concerned.	\$		170.00	<i>201</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$		2,000.00	<i>2001</i>
To check steering geometry and computer wheel alignment	\$	<i>nn</i>	220.00	<i>X</i>
To transfer of rear fender panel fittings, attachment and perform water seepage test.	\$	<i>nn</i>	170.00	<i>X</i>
TOTAL	\$		4,990.00	
Over All Total	\$		10,621.78	

(PART-BY-PART) Repair Days

20 Days

2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: