

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKS 8866K Yr Regn: 13/7/21
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Volkswagen Golf c.c. 1498
 Colour: White A/C: Insured / Std / NI / NA
 Sp. Reading: 17836 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: WVW222CD1MW356842
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modl: Nil / SRM / STD A/Rim or
 Tyre Size: F: 195/50R16
 R: 17
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or .
 Front Rear
 R/Bal. 4 mm R/Bal. 4 mm
 L/Bal. 4 mm L/Bal. 4 mm
 D.O.A. 1/10/21 D.O.I. 5/10/21
 Survey held at Volkswagen
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>MMV-130K</u>

Date/Time, File Pass to?

☐ : Prel. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Repair Format: _____

Lump Sum / L.B.F. (\$ _____)

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



*Sten (LTK)
5/10/22, 11.40*

*W R
4 4 5
P/P
L y BL y*

Quotation

Non binding - Preview

Page 1/2

Company
INDIA INTERNATIONAL INSURANCE
64 CECIL STREET
#04-05 IOB BUILDING
Singapore 049711

Customer Details:
Ms.
DONG
CHENGJIE
BLK 321 HOUGANG AVE 5
#11-34
SINGAPORE 530321

Document no.
Document date
Customer no.
Customer GST-ID
Dealer
Job order number
Job order date
Service Advisor
04-10-2022
5211000972
198703792K
30001
2022029099/ 1
04-10-2022
Dass Anthonidas
Christopher

License plate	Model code	First registration	VIN	Model	Mileage
SKS8866K	CD13LMP0	13-07-2021	WWWZZCDZMW356842	Golf Life Plus 1.5 eTSI 110kW DSG	20

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
9801B004	B&P CHECK SHORT CIRCUIT / HARNESS REPAIR				5.00% #1	266.00	284.62
9801B005	B&P DIAGNOSIS AND PROGRAMMING				5.00% #1	456.00	487.92
5H6807417P GRU	Cover For Bumper Primed	1	pcs.	1,266.90	10.00% #1	1,140.21	1,220.02
5H6807393D	Guide Piece	1	pcs.	41.89	10.00% #1	37.70	40.34
	LHR BUMPER BRACKET -(SIDE)	1	pcs.				
5H6807394D	Guide Piece	1	pcs.	41.89	10.00% #1	37.70	40.34
	RHR BUMPER BRACKET (SIDE)	1	pcs.				
5H6807393E	Guide Piece	1	pcs.	41.89	10.00% #1	37.70	40.34
	LHR BUMPER BRACKET (OUTER)	1	pcs.				
5H6807394E	Guide Piece	1	pcs.	41.89	10.00% #1	37.70	40.34
	RHR BUMPER BRACKET (OUTER)	1	pcs.				
5H6807863	Attachment Strip	1	pcs.	68.24	10.00% #1	61.42	65.72
	RR BUMPER BRACKET (CENTER)	1	pcs.				
5WA919275B GRU	Sensor Primed	1	pcs.	190.18	10.00% #1	171.16	183.14
3Q0919133 9B9	Seal Ring Satin Black	4	pcs.	4.72	10.00% #1	16.99	18.18
5H0919491	Sensor Bracket	1	pcs.	12.89	10.00% #1	11.60	12.41
5H0919491A	Sensor Bracket	2	pcs.	12.89	10.00% #1	23.20	24.82
5H0919492	Sensor Bracket	1	pcs.	12.89	10.00% #1	11.60	12.41
D 180KU2A1	2k-Plastic Adhesive	1	pcs.	85.94	10.00% #1	77.35	82.76
D 822150A1	Bonding Agent For Plastic	1	pcs.	68.85	10.00% #1	61.97	66.31
5H0807305F	Bumper	1	pcs.	542.11	10.00% #1	487.90	522.05
	REINFORCEMENT						
5H6807568 9B9	Rear Diffuser Satin Black	1	pcs.	278.12	10.00% #1	250.31	267.83
WHT005263	Rivet	3	pcs.	1.32	10.00% #1	3.56	3.81
5H0945106	Reflector	1	pcs.	79.04	10.00% #1	71.14	76.12
	RHR						
5H0945105	Reflector	1	pcs.	79.04	10.00% #1	71.14	76.12
	LHR						
3G5943021A	Led Licence Place Light	2	pcs.	64.07	10.00% #1	115.33	123.40
	REAR NUMBER PLATE	1	pcs.	80.00	5.00% #1	76.00	81.32
	LABOUR	31	pcs.	840.00	5.00% #1	2,394.00	2,561.58
	SPRAY PAINTING	32	pcs.	800.00	5.00% #1	2,280.00	2,439.60
	INDIA DIRECT						
	DOA: 1/10/2022						
	TP VEH NO: SMR267Z						
	SURVEY BY:						

Logo (golf & eTSI) - MC

Quotation valid till 11-10-2022

Tax Code	Labour	Labour Discount	Material	Material Discount	GST %	GST	Total Discount	Total amount excl. GST	Total amount incl. GST
#1	722.00	38.00	7,475.68	552.84	7%	573.84	590.84	8,197.68	8,771.52
Total	722.00	38.00	7,475.68	552.84		573.84	590.84	8,197.68	8,771.52

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page

2/2

Company
INDIA INTERNATIONAL INSURANCE
64 CECIL STREET
#04-05 IOB BUILDING
Singapore 049711

Customer Details:
Ms.
DONG
CHENGJIE
BLK 321 HOUGANG AVE 5
#11-34
SINGAPORE 530321

Document no.
Document date
Customer no.
Customer GST-ID
Dealer
Job order number
Job order date
Service Advisor
04-10-2022
5211000972
198703792K
30001
2022029099/ 1
04-10-2022
Dass Anthonidas
Christopher

License plate	Model code	First registration	VIN	Model	Mileage				
SKS8866K	CD13LMP0	13-07-2021	WVWZZZCDZMW356842	Golf Life Plus 1.5 eTSI 110kW DSG	20				
Tax Code	Labour	Labour Discount	Material	Material Discount	GST %	GST	Total Discount	Total amount excl. GST	Total amount incl. GST

Customer

Service Advisor

--- VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions). ---

All invoices are denominated in SGD, unless otherwise stated.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: