

Date: 29/09/2022

Vehicle No: SLH7000U

Model: MERCEDES BENZ GLC 250 AMG

Chassis: WDC2539462F099267-2016

Reg.Year: 2016

Third Party Insurer: CHINA TAIPING

Third Party Veh No: YQ3662J

Date of Accident: 29/09/2022

Estimator:

TING AN

Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE	1		By \$2,945.00
2	REAR TAILGATE "GLC 250" EMBLEM	1		na \$120.00
3	REAR TAILGATE "4 MATIC" EMBLEM	1		na \$150.00
4	REAR TAILGATE LOGO EMBLEM	1		na \$80.00
5	REAR TAILGATE INNER TRIM BOARD	1		na \$450.00
6	REAR TAILGATE INNER LOCK	1		na \$320.00
7	REAR TAILGATE WEATHERSTRIP	1		\$510.00
8	REAR TAILGATE LAMP LH	1		\$580.00
9	REAR TAILGATE LAMP RH	1		\$580.00
10	REAR TAIL LAMP LH	1		na \$580.00
11	REAR TAIL LAMP RH	1		na \$580.00
12	REAR BUMPER	1		na \$1,100.00
13	REAR BUMPER LOWER DIFFUSER	1		na \$760.00
14	REAR BUMPER LOWER CHROME MOULDING	1		CM \$500.00
15	REAR BUMPER TOWING COVER	1		na \$80.00
16	REAR BUMPER SIDE RETAINER LH	1		\$190.00
17	REAR BUMPER SIDE RETAINER RH	1		\$190.00
18	REAR BUMPER REFLECTOR LH	1		na \$60.00
19	REAR BUMPER REFLECTOR RH	1		na \$60.00
20	REAR BUMPER INNER BRACKET	1		\$220.00
21	REAR EXHAUST CHROME TIP LH	1		na \$460.00
22	REAR EXHAUST CHROME TIP RH	1		na \$460.00
23	REAR END PANEL	1		\$1,500.00
24	REAR END PANEL UPPER COVER	1		na \$380.00
25	FRONT BONNET	1		na \$2,200.00
26	FRONT BONNET LOGO EMBLEM	1		na \$90.00
27	FRONT GRILLE BASE	1		\$280.00
28	FRONT GRILLE OUTER GARNISH COVER	1		\$280.00
29	FRONT BUMPER	1		\$1,900.00
30	FRONT BUMPER REINFORCEMENT	1		na \$490.00
31	FRONT BUMPER ABSORBER FOAM	1		\$230.00
32	FRONT BUMPER NUMBER PLATE GARNISH HOLDER	1		na \$175.00
33	FRONT BUMPER LOWER GRILLE	1		na \$190.00
SUB TOTAL				\$18,690.00
LESS 10%				-\$1,869.00
PARTS TOTAL				\$16,821.00

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554600
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1893

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 29/09/2022
 Vehicle No: SLH7000U
 Model: MERCEDES BENZ GLC 250 AMG
 Chassis: WDC2539462F099267-2016
 Reg.Year: 2016

Third Party Insurer: CHINA TAIPING
 Third Party Veh No: YQ3662J
 Date of Accident: 29/09/2022
 Estimator: TING AN
 Surveyor:

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR WINDSCREEN SEALANT	1		<i>Rec</i> \$80.00
2	REAR TAILGATE INNER TRIM BOARD CLIPS	1		<i>Rec</i> \$50.00
3	REAR BUMPER CLIPS	1		<i>Rec</i> \$60.00
4	REAR END PANEL JOINT SEALANT	1		\$80.00
5	REAR END PANEL UPPER COVER CLIPS	1		\$40.00
6	REAR NUMBER PLATE & HOLDER	1		<i>Rec</i> \$50.00
7	FRONT BUMPER CLIPS	1		\$50.00
8	FRONT NUMBER PLATE & HOLDER	1		<i>Rec</i> \$50.00
9	FRONT GRILLE BASE CLIPS	1		\$40.00
			S/N TOTAL	\$500.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST REAR ACCIDENT AREAS & ETC.

\$1,200.00 *700*

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR TAILGATE, REAR BUMPER, REAR END PANEL, FRONT BONNET, FRONT BUMPER & ETC.

\$1,200.00 *1000*

LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN GLASS, REAR WINDSCREEN SEALANT & ETC.

\$150.00 *120*

LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM & ETC. TO EFFECT REPLACE OF REAR TAILGATE.

\$120.00 *60*

TO TUFF KOTE & UNDERSEAL MATERIALS.

\$120.00 *30*

TO DIAGNOSIS FAULT CODE & RESET MEMORY.

\$150.00 *7*

TO CHECK WIRING & ELECTRICAL SYSTEM.

\$120.00 *40*

LABOUR TOTAL \$3,060.00

TING AN

TOTAL \$20,381.00

Head office

6 Kung Chong Road Singapore 159143

Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500

Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 688047

Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

