

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: EQ Insurance Company Ltd
5 Maxwell Road,#17-00 Tower Block
MND Complex
Singapore 069110From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Josephine Wong

Date: 27 Dec 2022

Preliminary Advice

| | | | |
|--------------------|-------------------------------------|-------------------------|--------------|
| Insured Vehicle No | : SMG9792Y | Accident Date | : 03/10/2022 |
| TP Vehicle No | : SHB6253S | Assignment Date | : 04/10/2022 |
| Make | : HYUNDAI IONIQ HYBRID | Est. Duration of Repair | : 02 |
| Date of Inspection | : 04/10/2022 | | |
| Inspection At | : COMFORTDELGRO ENGINEERING PTE LTD | | |

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

| | | |
|-----------------------------|------|----------|
| Repairer's Estimate (Gross) | :S\$ | 2,415.56 |
| Revised Amount | :S\$ | 1,388.60 |
| Check Items (Estimated) | :S\$ | 0.00 |
| Total | :S\$ | 1,388.60 |
| Lump Sum Repair | :S\$ | 1,100.00 |

Total Loss Consideration

| | |
|--------------------|------|
| New for Old Value | :S\$ |
| Pre-Accident Value | :S\$ |
| COE / PARF Rebate | :S\$ |
| Salvage Value | :S\$ |
| Margin for Repair | :S\$ |

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments : The above survey was conducted on a 'Without Prejudice' basis. Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.