

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG22009751/UQY3E2
Date: 26/04/2023**REFERENCE**

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	30001968203
Claimant Vehicle No :	SMG2057H	Insured Vehicle No :	YN3855K
Date of Loss:	29/09/2022	Nature of Claim:	TP
		Claim No:	286504

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMG2057H	Engine No:	2ZR2A08228
Make & Model:	TOYOTA C-HR HYBRID, 1.8 S CVT (A)	Chassis No:	ZYX102126763
Reg. Date:	10/12/2018 (Man. Year: 2018)	Odometer:	33870 km
Colour:	Black		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R17	Rear Tyre Size:	215/60 R17
Front Left Side:	KAPSEN 6 mm	Rear Left Side:	Davanti 6 mm
Front Right Side:	KAPSEN 6 mm	Rear Right Side:	Davanti 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,699.00	2,936.02	1,762.98	37.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,970.00	1,070.00	1,900.00	63.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,669.00	4,006.02	3,662.98	47.76
Approved Total (Overridden) (S\$)		3,200.00		
	(S\$)	7,669.00	3,200.00	4,469.00
+ GST 8.00/8.00% (S\$)	613.52	256.00	357.52	58.27
Nett Amount (S\$)	8,282.52	3,456.00	4,826.52	58.27

INSPECTION

Date of Assignment:	03/10/2022	Ms Car Auto Pte Ltd (HQ)
Date Inspected:	10/10/2022 Inspected At:	8 KAKI BUKIT AVE 4 #01-07 PREMIER @ KAKI BUKIT
Estimated Period of Repair:	3.0 days	Singapore 415875

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 10 Apr 2023)
Parts: M1-SUV	TOYOTA C-HR HYBRID 1.8 S CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SMG2057H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT HEADLAMP RH	Scratched / Cracked	1,727.00 FL	*1,727.00 FL
2	1		*FRONT FENDER RH	Dented / Bent	826.00 FL	*645.10 FL
3	1		*FRONT FENDER GARNISH RH	Grazed	143.00 FL	*143.00 FL
4	1		*FRONT FENDER HYBRID EMBLEM RH (2PCS)	Necessary (1Pc Only)	150.00 FL	*75.00 FL
5	1		*FRONT FENDER SHIELD RH	Torn	236.00 FL	*182.10 FL
6	1		*FRONT BUMPER	Cut	495.00 FL	*495.00 FL
7	1		*FRONT BUMPER SIDE GARNISH RH	Not Necessary	159.00 FL	*- FL
8	1		*FRONT BUMPER LOWER DIFFUSER	Deformed / Torn	505.00 FL	*505.00 FL
9	1		*FRONT BUMPER RETAINER RH	Bent	115.00 FL	*62.50 FL
10	1		*WASHER TANK	Not Necessary	189.00 FL	*- FL
11	1		*WASHER TANK NECK	Not Necessary	97.00 FL	*- FL
12	1		*FRONT DOOR RH	Not Necessary	1,350.00 FL	*- FL
13	1		*SET FRONT NO. PLATE	Not Necessary	65.00 FS	*- FS
14	1		*SET FRONT BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
15	1		*SET FRONT FENDER SHIELD CLIPS	Necessary	60.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	6,197.00	3,894.70
- List Item Discount on L Items 25.00/25.00% (S\$)	1,498.00	958.68
Total Parts (S\$)	4,699.00	2,936.02

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO PANEL BEAT / CUT / WELD AFFECTED PANELS, REALIGN AND REFIT / REPLACE NECESSARY AFFECTED PARTS	New	1,400.00	420.00
2	TO PUTTY AND SPRAY PAINT ON ACCIDENT AFFECTED PORTION	New	1,000.00	600.00
3	TO DISCONNECT / RECONNECT AND CHECK FOR PROPER WIRING AND ELECTRICAL FUNCTION	New	100.00	20.00
4	TO APPLY ANTI RUST COATING	New	120.00	30.00
5	TO DISMANTLE AND REPLACED FRONT UNDER CARRIAGE RH	New	350.00	0.00
Gross Labour Cost (\$\$)			2,970.00	1,070.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >