

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22009752/UPA3Q2**Date:** 23/05/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210152351
Claimant Vehicle No :	FBQ6382U	Insured Vehicle No :	SMU6226L
Date of Loss:	29/09/2022	Nature of Claim:	TP
		Claim No:	5617287385SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBQ6382U		
Make & Model:	YAMAHA MX KING T150, 150cc	Engine No:	G3E6E0535147
Reg. Date:	14/11/2019 (Man. Year: 2019)	Chassis No:	MH3UG0750KK040541
Colour:	Multi-colour	Odometer:	57924 km
Engine Capacity:	150 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	90-80-17	Rear Tyre Size:	120-70-17
Front Left Side:	Maxxis 6 mm	Rear Left Side:	Maxxis 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,135.80	2,346.20	3,789.60	61.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,010.00	300.00	710.00	70.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	7,145.80	2,646.20	4,499.60	62.97
Approved Total (Overridden) (\$\$)		2,100.00		
Nett Amount (\$\$)	7,145.80	2,100.00	5,045.80	70.61
Global Sum Settlement (\$\$)		0.00		

INSPECTION

Date of Assignment:	04/10/2022	Erofia Motor Trading Pte Ltd - (kaki Bukit) (HQ)
Date Inspected:	04/10/2022 Inspected At:	1 Kaki Bukit Avenue 6, #02-62 AutoBay @ Kaki Bukit
Estimated Period of Repair:	4.0 days	Singapore 417883

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*FRONT FORK TUBE ASSY	Not Necessary	640.00 FL	*- FL
2	1		*FORK UNDER BRACKET	Not Necessary	220.00 FL	*- FL
3	1		*FRONT WHEEL RIM	Not Necessary	350.00 FL	*- FL
4	1		*FRONT RIM SHAFT	Not Necessary	68.00 FL	*- FL
5	1		*FRONT RIM BEARING	Not Necessary	78.00 FL	*- FL
6	1		*FRONT BRAKE DISC	Not Necessary	155.00 FL	*- FL
7	1		*HANDLE -BAR	Bent	158.00 FL	*118.00 FL
8	1		*SET HAND GRIP	Not Necessary	68.00 FL	*- FL
9	1		*HANDLE BAR ENDS	Cut	128.00 FL	*30.00 FL
10	1		*CSIDE MIRRORS	O/S Cut	110.00 FL	*50.00 FL
11	1		*BRAKE LEVER (O/S)	Cut	72.00 FL	*72.00 FL
12	1		*BRAKE MASTER PUMP	Cut	485.00 FL	*305.00 FL
13	1		*FRONT SIGNALS	O/S Cracked	140.00 FL	*70.00 FL
14	1		*SET PILOT LIGHT	Cracked	285.00 FL	*285.00 FL
15	1		*FRONT SIGNAL LOWER GARNISH (O/S)	Cut	135.00 FL	*135.00 FL
16	1		*HEADLAMP	Cracked	580.00 FL	*400.00 FL
17	1		*SET FAIRING ASSY	Cut	580.00 FL	*493.00 FL
18	1		*FRONT FOOTREST BRACKETS	Repair	155.00 FL	*- FL
19	1		*FRONT FOOTREST	O/S Cut	110.00 FL	*40.00 FL
20	1		*BRAKE PEDAL	Cut	72.00 FL	*72.00 FL
21	2		*REAR FOOTREST	Not Necessary	95.00 FL	*- FL
22	1		*REAR FOOTREST BRACKET	Not Necessary	220.00 FL	*- FL
23	1		*EXHAUST ASSY	Repair	650.00 FL	*- FL
24	1		*EXHAUST PROTECTOR	Cut	80.00 FL	*80.00 FL
25	1		*EXHAUST PROTECTOR END CAP	Cut	68.00 FL	*68.00 FL
26	1		*SET NUMBER PLATE	Frnt Necessary	38.00 FS	*10.00 FS
27	2		*FORK OILS	Not Necessary	30.00 FS	*- FS
28	2		*FORK OIL SEALS	Not Necessary	56.00 FS	*- FS
29	1		*SET STEERING CONE	Not Necessary	95.00 FS	*- FS
30	1		*REAR BOX	Cut	480.00 FS	*280.00 FS
31	1		*REAR BOX BRACKET	Not Necessary	180.00 FS	*- FS
32	1		*SET STICKER	Necessary	125.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,706.00	2,568.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	570.20	221.80
Total Parts (\$\$)	6,135.80	2,346.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING AND RESET HEADLAMP FORCUSING	New	80.00	0.00
2	TO REPAIR BODY FRAME	New	480.00	0.00
3	TO PROVIDE LABOUR	New	450.00	300.00
Gross Labour Cost (S\$)			1,010.00	300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >