

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Email: erofia@singnet.com.sg

ALG

Name : Ng Beng Kiat (96156332)

Not Affected
der

Accident Date : 29-Sep-22

Vehicle No : FBQ6382U (COE131129)

2/5 & 2100

Vehicle Model :

Yamaha MX

King T150

Manual

ah phl. After reg
4 days!

Estimated Repair Costs

Qty	Description	4/10/22	Amount S(\$)
	<u>List Items</u>		
2	Front fork tube assy		\$ 11 640.00 X
1	Fork under bracket		\$ 17 220.00 X
1	Front wheel rim		\$ 18 350.00 X
1	Front rim shaft		\$ 17 68.00 X
1	Front rim bearing		\$ 17 78.00 X
1	Front brake disc		\$ 17 155.00 X
1	Handle-bar	118	\$ 307 158.00 X
1	Hand grip (1 set)		\$ 17 68.00 X
1	Handle bar ends	30	\$ 117 128.00 ✓
2	Side mirrors	50	\$ 117 110.00 1/2
1	Brake lever 0/5		\$ 117 72.00 ✓
1	Brake master pump	305	\$ 117 485.00 ✓
2	Front signals	70	\$ 117 140.00 1/2
1	Pilot light (1 set)		\$ 117 285.00 ✓
1	Front signal lower garnish 0/5		\$ 117 135.00 ✓
1	Headlamp		\$ 117 580.00 ✓
1	Fairing assy (1 set)	400 493	\$ 117 580.00 ✓
1	Front footrest brackets		\$ 117 155.00 X
2	Front footrest	40	\$ 117 110.00 1/2
1	Brake pedal		\$ 117 72.00 ✓
2	Rear footrest		\$ 117 95.00 X
1	Rear footrest bracket		\$ 117 220.00 X
1	Exhaust assy		\$ 117 650.00 X
1	Exhaust protector		\$ 117 80.00 ✓
1	Exhaust protector end cap		\$ 117 68.00 ✓
			\$ 5,702.00
			Less 10% \$ 570.20
			\$ 5,131.80

P-2218
A96.2

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Email: erofia@singnet.com.sg

Name : Ng Beng Kiat (96156332)

Accident Date : 29-Sep-22

Vehicle No : FBQ6382U (COE131129)

Vehicle Model : Yamaha MX
King T150
Manual

Estimated Repair Costs

<u>Special Nett Items</u>	
1	Number plate (1 set)
2	Fork oils
2	Fork oil seals
1	Steering cone (1 set)
1	Rear box
1	Rear box bracket
1	Sticket (1 set)

\$	111	38.00	10
\$	11	30.00	X
\$	11	56.00	X
\$	11	95.00	X
\$	617	480.00	280
\$	11	180.00	X
\$	111	125.00	60
\$		<u>1,004.00</u>	

S/No. Labour

1	To provide towing serving (LOD) S\$70.00
2	To check wiring and reset headlamp focusing
3	To repair body frame
4	To provide labour

\$	-	X
\$	11	80.00 X
\$	11	480.00 X
\$		450.00 320
\$		<u>1,010.00</u>

Grand Total

\$ 7,145.80

Singapore Dollars: Seven Thousand One Hundred Forty-Five and Cents: Eighty only

2646.2

EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: