



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTOMOTIVE ENGRG. & MGT. DIVISION (TP)		Ref:	CS/SPF22009754/Gvy3m4
ACCIDENT CLAIMS SECTION (SPORE POLICE FORCE) POLICE LOGISTICS BASE (PLB) 1 HEMMANT ROAD SINGAPORE 438675		Date:	02/02/2023
ATTN: HAFIZUL FARHAN		Code:	SPF
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	QX 1843A	Veh. Inspected	SGD 3788L
Policy No.		Coverage (\$)	0.00
Claim No.	ACS/105/009/2022/058	Excess (\$)	0.00
Assign From	HAFIZUL FARHAN	Assign Date	04/10/2022
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA PRIUS PLUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	JTDZS3EU40J033933	Colour	RED
Odometer	82858 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/60 R16	YOKOHAMA	6 mm
L/H Front Tyre	205/60 R16	YOKOHAMA	6 mm
R/H Rear Tyre	205/60 R16	YOKOHAMA	6 mm
L/H Rear Tyre	205/60 R16	YOKOHAMA	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	01/10/2022	Inspection Date	07/10/2022
Survey held at	KAN FOOK SING MOTOR WORKSHOP BLK.8 JTC DEFU INDUSTRIAL CITY #04-29 DEFU SOUTH STREET 1 SINGAPORE 533758		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		1 Working Days	