



# 簡福星噴呀工廠

## KAN FOOK SING MOTOR WORKSHOP

Headquarter: Blk 8 JTC Defu Industrial City #04-29 Defu South Street 1, S533758

Tel: (65) 6747 9560, 6743 5344 • Fax: (65) 6748 1006

E-mail: ryan@kanfs.net / patricia@kanfs.net

Branch: 1 Kaki Bukit Avenue 6 #01-13, Singapore 417883

Tel: (65) 6481 5180 • Fax: (65) 6481 8683

ATTORNEY GENERAL CHAMBERS  
1 COLEMAN STREET #10-00 S(0617)

DATE : 03-10-2022

VEHICLE NO. : SGD3788L  
ACCIDENT DATE : 01-10-2022 17:40  
THIRD PARTY REF. : QX1843A

ATTN: ATTORNEY GENERAL CHAMBERS

ESTIMATE COST OF REPAIR TO VEHICLE SGD3788L TOYOTA PRIUS PLUS (AUTO)

#	QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
1	1	FRONT SIDE MIRROR RH / <i>riz</i>	847.73
2	1	FRONT SIDE MIRROR COVER RH / <i>riz</i>	111.97
3	1	FRONT SIDE MIRROR GLASS RH / <i>?</i>	139.52
4	1	FRONT SIDE MIRROR SIGNALLAMP RH / <i>CAA</i>	69.34
			<hr/>
			1,168.56
			<hr/>
LESS 25 %			292.14
			<hr/>
TOTAL ( A )			876.42

### LABOUR CHARGES

1	1	TO CHECK WIRING SYSTEM	50.00 <i>X 200</i>
2	1	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	300.00 <i>100</i>
3	1	SORAYPAINTING CHARGES	300.00 <i>100</i>
			<hr/>
TOTAL ( D )			650.00
			<hr/>
ESTIMATE TOTAL			1,526.42

*Give Quary*

*1 Day*

*P/P*

*7/10/22*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are based on market condition
- Third party claims are on "no prejudice" basis
- No illegal practices are allowed
- Supplier must be approved by the Insurer and is subject to the Insurer's Insurance Company

Acknowledged by:

Signature:

Date: