

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/TMI22009755/KVCQ2**Date:** 25/10/2022REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MT102743
Claimant Vehicle No :	SHD9968H	Insured Vehicle No :	GX4979R
Date of Loss:	30/09/2022	Nature of Claim:	TP
		Claim No:	M2205470

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD9968H	Engine No:	2ZR2H61823
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Chassis No:	JTDKB3FUX03093509
Reg. Date:	28/01/2021 (Man. Year: 2020)	Odometer:	125313 km
Colour:	Metallic White/Red		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Sailun 8 mm	Rear Left Side:	Dunlop 3 mm
Front Right Side:	Sailun 8 mm	Rear Right Side:	Dunlop 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,663.67	2,433.45	5,230.22	68.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,100.00	1,540.00	3,560.00	69.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	12,763.67	3,973.45	8,790.22	68.87
+ GST 7.00/7.00% (S\$)	893.46	278.14	615.32	68.87
Nett Amount (S\$)	13,657.13	4,251.59	9,405.54	68.87

INSPECTION

Date of Assignment:	05/10/2022	
Date Inspected:	03/10/2022	Inspected At: Trans-cab Auto Services Pte Ltd (Ang Mo Kio) 2, Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	6.0 days	

Adjuster: KENNETH KONG**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 25 Oct 2022)**Parts:** 144 TOYOTA PRIUS 1.8 5DR HATCHBACK (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for SHD9968H)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PANEL SUB-ASSY ,REAR DOOR ,LH	Bent	1,294.90 FL	*1,294.90 FL
2	1		*FRAME SUB-ASSY ,REAR DOOR OUTSIDE HANDLE ,RH	Repair	193.50 FL	*- FL
3	1		*HANDLE ASSY ,REAR DOOR OUTSIDE ,RH	Service item	97.40 FL	*- FL
4	1		*WEATHERSTRIP ,REAR DOOR OPENING TRIM ,LH	Serviceable	293.00 FL	*- FL
5	1		*HINGE ASSY ,REAR DOOR ,LOWER LH	Repair	87.10 FL	*- FL
6	1		*HINGE ASSY ,REAR DOOR ,UPPER LH	Repair	98.90 FL	*- FL
7	1		*TAPE ,BLACK OUT NO.1 REAR LH	Necessary	21.90 FL	*21.90 FL
8	1		*TAPE ,BLACK OUT NO.2 REAR LH	Necessary	34.90 FL	*34.90 FL
9	1		*TAPE ,BLACK OUT NO.3 REAR LH	Necessary	15.40 FL	*15.40 FL
10	1		*MOTOR ASSY ,POWER WINDOW REGULATOR LH	Bent	926.00 FL	*926.00 FL
11	1		*REGULATOR SUB-ASSY ,REAR DOOR WINDOW ,LH	Serviceable	206.70 FL	*- FL
12	1		*MIRROR ASSY ,OUTER REAR VIEW ,LH	Serviceable	1,339.30 FL	*- FL
13	1		*COVER ,REAR BUMPER	Repair	485.60 FL	*- FL
14	1		*REAR BUMPER SIDE RETAINER LH	Serviceable	132.60 FL	*- FL
15	1		*PANEL SUB-ASSY ,QUARTER LH	Bent	871.50 FL	*871.50 FL
16	1		*LINER ,REAR WHEEL HOUSE ,LH	Serviceable	139.80 FL	*- FL
17	1		*MOULDING ASSY ,BODY ROCKER PANEL ,LH	Serviceable	594.80 FL	*- FL
18	1		*HUB CAP	Serviceable	211.50 FL	*- FL
19	1		*RIM	Serviceable	1,900.10 FL	*- FL
20	1		*TYRE	Serviceable	350.00 FS	*- FS
21	1		*REAR BUMPER CLIP	Not Necessary	65.00 FS	*- FS
22	1		*FENDER CLIP	Not Necessary	60.00 FS	*- FS
23	1		*FENDER LINER CLIP	Not Necessary	65.00 FS	*- FS
24	1		*SET DOOR TRIM CLIP	Not Necessary	85.00 FS	*- FS
25	1		*SET DOOR WEATHERSTRIP CLIP	Not Necessary	65.00 FS	*- FS
26	1		*DOOR STICKER TRANSCAB	Not Necessary	100.00 FS	*- FS
27	1		*DOOR STICKER TEL NO	Necessary	100.00 FS	*60.00 FS
28	1		*SET CLIP ,ROCKER PANEL MOULDING	Not Necessary	65.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,899.90	3,224.60
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,236.23	791.15
Total Parts (\$\$)	7,663.67	2,433.45

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	240.00	60.00
2	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	100.00
3	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.	New	1,600.00	700.00
4	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENT TO FACILITATE BODYWORK REPAIR	New	380.00	0.00
5	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,600.00	660.00
6	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	0.00
7	TO TRANSFER OF TIRE RIM AND ON WHEEL BALANCING	New	170.00	0.00
8	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
9	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
10	TO REMOVE AND REFIT OF REAR FENDER FITTINGS ,ATTACHMENT AND	New	170.00	0.00
			Gross Labour Cost (S\$)	5,100.00
				1,540.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >