

Not Authored
Presurvey B& paint

Trans-cab Auto Services Pte Ltd

AAD2209-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9968H

Vehicle No.:

Chassis No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

03 OCT 2022

SHD9968H

JTDKB3FUX03093509

200303878K

TOYOTA

PRIUS GEN 4

30/09/2022

GX 4479R / Tokio

28/01/2021

	PART		LIST
1	PANEL SUB-ASSY, REAR DOOR, LH	\$	1,294.90 ✓
1	FRAME SUB-ASSY, REAR DOOR OUTSIDE HANDLE, RH	\$	193.50 X
1	HANDLE ASSY, REAR DOOR OUTSIDE, RH	\$	97.40 X
1	WEATHERSTRIP, REAR DOOR OPENING TRIM, LH	\$	293.00 X
1	HINGE ASSY, REAR DOOR, LOWER LH	\$	87.10 X
1	HINGE ASSY, REAR DOOR, UPPER LH	\$	98.90 X
1	TAPE, BLACK OUT, NO.1 REAR LH	\$	21.90 ✓
1	TAPE, BLACK OUT, NO.2 REAR LH	\$	34.90 ✓
1	TAPE, BLACK OUT, NO.3 REAR LH	\$	15.40 ✓
1	MOTOR ASSY, POWER WINDOW REGULATOR, LH	\$	926.00 ✓
1	REGULATOR SUB-ASSY, REAR DOOR WINDOW, LH	\$	206.70 7
1	MIRROR ASSY, OUTER REAR VIEW, LH	\$	1,339.30 X
1	COVER, REAR BUMPER		485.6 X
1	REAR BUMPER SIDE RETAINER LH		132.6 X
1	PANEL SUB-ASSY, QUARTER, LH	\$	871.50 ✓
1	LINER, REAR WHEEL HOUSE, LH	\$	139.80 X
1	MOULDING ASSY, BODY ROCKER PANEL, LH	\$	594.80 X
1	HUB CAP	\$	211.50 X
1	RIM	\$	1,900.10 X
TOTAL		\$	8,944.90
25%		\$	2,236.23
		\$	6,708.68

Special Nett

1 TYRE

\$ 350.00 X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2209-

SHD9968H

1 REAR BUMPER CLIP	\$	na	65.00	X
1 FENDER CLIP	\$	na	60.00	X
1 FENDER LINER CLIP	\$	na	65.00	X
1SET DOOR TRIM CLIP	\$	na	85.00	X
1SET DOOR WEATHERSTRIP CLIP	\$	na	65.00	X
1 DOOR STICKER TRANSCAB	\$	na na	100.00	X
1 DOOR STICKER TEL NO.	\$	na	100.00	6050
1SET CLIP, ROCKER PANEL MOULDING	\$	na	65.00	X
TOTAL	\$		955.00	

TOTAL PARTS \$ 7,663.68**LABOUR**

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$		240.00	601
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$		380.00	1001
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$		1,600.00	7001
To transfer of rear end panel fittings, attachment to facilitate bodywork repair.	\$	na	380.00	X
Putty And Spray Painting Of The Affected Portion.	\$		1,600.00	6601
To reinstall rear bumper parking sensor.	\$	na	170.00	X
To transfer of tire, rim and on wheel balancing.	\$	na	170.00	X
To Check Electrical Lighting Concerned.	\$		170.00	201

Trans-cab Auto Services Pte Ltd

AAD2209-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9968H

To check steering geometry and computer wheel alignment	\$	<i>na</i>	220.00 X
To remove and refit of rear fender fittings, attachment and	\$	<i>na</i>	170.00 X
TOTAL	\$		5,100.00
Over All Total	\$		12,763.68

(PART-BY-PART) Repair Days

20 days

6 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: