

Not Notified
Resurvey B & paint

Trans-cab Auto Services Pte Ltd

AAD2209-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9968H

Vehicle No.:

03 OCT 2022

Chassis No.:

SHD9968H

JTDKB3FUX03093509

Co UEN:

200303878K

Vehicle Make:

TOYOTA

Vehicle Model:

PRIUS GEN 4

Date of Accident :

30/09/2022

Third Party Insurer :

GX 4A79R / Tokio

Date of Registration :

28/01/2021

	PART		LIST
1	PANEL SUB-ASSY, REAR DOOR, LH	\$	B 1,294.90 ✓
1	FRAME SUB-ASSY, REAR DOOR OUTSIDE HANDLE, RH	\$	N 193.50 X
1	HANDLE ASSY, REAR DOOR OUTSIDE, RH	\$	Sm 97.40 X
1	WEATHERSTRIP, REAR DOOR OPENING TRIM, LH	\$	B 293.00 X
1	HINGE ASSY, REAR DOOR, LOWER LH	\$	N 87.10 X
1	HINGE ASSY, REAR DOOR, UPPER LH	\$	N 98.90 X
1	TAPE, BLACK OUT, NO.1 REAR LH	\$	Sm 21.90 ✓
1	TAPE, BLACK OUT, NO.2 REAR LH	\$	Sm 34.90 ✓
1	TAPE, BLACK OUT, NO.3 REAR LH	\$	Sm 15.40 ✓
1	MOTOR ASSY, POWER WINDOW REGULATOR, LH	\$	926.00 ✓
1	REGULATOR SUB-ASSY, REAR DOOR WINDOW, LH	\$	206.70 7
1	MIRROR ASSY, OUTER REAR VIEW, LH	\$	Sm 1,339.30 X
1	COVER, REAR BUMPER		N 485.6 X
1	REAR BUMPER SIDE RETAINER LH		Sm 132.6 X
1	PANEL SUB-ASSY, QUARTER, LH	\$	B 871.50 ✓
1	LINER, REAR WHEEL HOUSE, LH	\$	Sm 139.80 X
1	MOULDING ASSY, BODY ROCKER PANEL, LH	\$	Sm 594.80 X
1	HUB CAP	\$	Sm 211.50 X
1	RIM	\$	Sm 1,900.10 X
TOTAL		\$	8,944.90
25%		\$	2,236.23
		\$	6,708.68

Special Nett

1 TYRE

\$ Sm 350.00 X

Trans-cab Auto Services Pte Ltd

AAD2209-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9968H

1 REAR BUMPER CLIP	\$	na	65.00 X
1 FENDER CLIP	\$	na	60.00 X
1 FENDER LINER CLIP	\$	na	65.00 X
1SET DOOR TRIM CLIP	\$	na	85.00 X
1SET DOOR WEATHERSTRIP CLIP	\$	na	65.00 X
1 DOOR STICKER TRANSCAB	\$	na na	100.00 X
1 DOOR STICKER TEL NO.	\$	na	100.00 605a
1SET CLIP, ROCKER PANEL MOULDING	\$	na	65.00 X
TOTAL	\$		955.00
		TOTAL PARTS	\$ 7,663.68

LABOUR

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$		240.00 601
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$		380.00 1001
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$		1,600.00 7001
To transfer of rear end panel fittings, attachment to facilitate bodywork repair.	\$	na	380.00 X
Putty And Spray Painting Of The Affected Portion.	\$		1,600.00 6601
To reinstall rear bumper parking sensor.	\$	na	170.00 X
To transfer of tire, rim and on wheel balancing.	\$	na	170.00 X
To Check Electrical Lighting Concerned.	\$		170.00 201

Trans-cab Auto Services Pte Ltd

AAD2209-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9968H

To check steering geometry and computer wheel alignment	\$	<i>na</i>	220.00 X
To remove and refit of rear fender fittings, attachment and	\$	<i>na</i>	170.00 X
TOTAL	\$		5,100.00
Over All Total	\$		12,763.68

(PART-BY-PART) Repair Days

20 days

6 days

- LKK Auto Consultants hence notify the Repairer of the following:**
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	30/09/2022 20:19 (SGT)
Reported by	Driver
Date of Accident	30/09/2022 15:05 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	Blk 153 Ang Mo Kio Avenue 5 560153 Open Space Carpark
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SHD9968H

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Company Reg No	2XXXXX878K
Email Address	claims@transcab.com.sg
Mobile Phone No	(Phone) +65-62876666
Alternative Phone No	(Office) +65-62876666

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	PRIUS 5DR HATCHBACK (AUTO)
Variants	-
Exact purpose for which vehicle was being used at time of accident	Private hire
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Taxi
Transmission	Auto
CC	1798

INSURANCE COMPANY

Name of Insurance Company	AXA Insurance Pte Ltd
Policy Number / Cover Note Number	VFX/P2413997

DRIVER

Name of Driver	TAN KWANG JOONG
NRIC No	SXXXX420B
Date Of Birth	31/07/1954
Occupation	Outdoor

Date Of Driving Pass 06/11/1978
 Driving experience 43 YEARS AND 10 MONTHS
 Gender Male
 Mobile Number (Phone) +65-89525438
 Alt. Phone Number -
 Email Address Claims@transcab.com.sg
 Address HDB Yio Chu Kang Grove, 153 Ang Mo Kio Avenue 5
 Address complement #09-3090
 Postcode 560153
 Is the driver the policyholder? No
 If No, Relationship of the Driver with the Insured Hirer
 Does Driver Own Other Vehicles? No
 Vehicle Registration Number of Other Vehicle Owned by Driver -
 Insurance Company of Other Vehicle Owned by Driver -

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Side Swipe
 Weather Conditions Clear
 Road Surface Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident? No
 Number of vehicles involved in the accident 2
 Was anybody injured in the Accident? No
 Was any injured conveyed to hospital by ambulance? -
 Was any other vehicle or property damaged? Yes
 Number of Passengers (Including Driver) 1
 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No
 Translator's name -
 Translator's ID -
 Translator's phone number -
 Translator's email -
 Original language used in the statement -

DETAILS OF POLICE ACTION

Was the accident reported to the police? No
 Was notice of intended Prosecution given? No
 If yes, against whom? -

CIRCUMSTANCES OF ACCIDENT

I WAS AT THE MENTIONED LOCATION OPEN SPACE CARPARK GOING STRAIGHT WHEN SUDDENLY THIRD PARTY REVERSED AND COLLIDED ONTO MY VEHICLE LEFT SIDE. ONLY TWO VEHICLES WERE INVOLVED WITHOUT ANY INJURIES.


ATTACHMENT(S)

Are accident photos available for attachment? Yes
 Was there any video captured by Car Camera? Yes
 Reasons for not uploading a video of the accident WITH TRANSCAB

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GX4979R
 Vehicle Manufacturer Toyota
 Vehicle Model DYNA 150 D
 Vehicle Variant -
 Vehicle Colour White

ACCIDENT DIAGRAM



Veh A: SHD9968H
Veh B: GX4979R

Blk 153 Ang Mo Kio Ave 5
open space carpark

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed By Reporting Officer
Ang Qi Hao, Victor
Witnessed by Reporting Personnel