

SLN8399G.

Mercedes Benz E250

WDD2130452A136876.

TP ALG

Oct 22

Xiao Long

Rees Bumper	Debond	1874	✓
Rees Bumper Clips.	Mer	30(SN)	✓
Rees Bumper Side Holder x 02	NE Mer	192 x 2 = 384	X
Rees Bumper Lower Garnish.	Ut	485	✓
Rees Bumper Lower Garnish Chrome Moulding.	Couled	291	✓
Rees Bumper Exhaust Chrome Pipe x 02.	Mer	231 x 2 = 462	X
Rees Bumper Reflector x 02.	XL Mer	68 x 2 = 138	X
Rees Bumper Reinforcement.	Dented	846	✓
Rees Bumper Exhaust Chrome Pipe Bracket x 02.	Couled	32 x 2 = 64	✓
Rees Bumper Centre Guide.	Couled	275	✓
Rees Bumper Reinforcement Cover.	Couled	149	✓
Rees Bumper Kick Sensor.	Mer	316	X
Reverse Sensor x 04.	2 Pliers damaged	536. 268 x 4 = 1072	
Reverse Sensor Holder x 04.	Mer	25 x 4 = 100.	✓

SLN 8388 G.

Reverse Sensor Wire Harness. ^{MP} _W 622 X

Tailamp x 02 Cracked 785x2=1570 ✓

Tailamp lower Bracket x 02. ^{Cracked} 77x2=154 ✓

Bootlid. ^{Decked} 2398. ✓

Bootlid Lock. ^{Engd} 294. ✓

Bootlid Weatherstripe. ^{Ut} 292 ✓

Bootlid Outer Chrome Moulding. ^{Ut} 267. ✓

Mercedes Benz Logo. 93 ✓

E250 Wordling. 97 ✓

Cycle and Carriage Logo. ^{Mer} 45. ✓

9 G Tronic Wordling. 95 ✓

Spore Tyre Panel Top Board. ^{xp} _{Mer} 710 X

Rees Fender Inner Trim Board x 02 } 655x2=1310 X

Rees Fender Inner Trim Board Clips } ^{xp} _{Mer} 60(SW) X

Rees Camera. ^{xlp} _{Mer} 859. X

SLH 8399 G.

Rees End Panel. Dented 998.
Debond 1302 ✓
Rees End Panel Top Garnish. 229. ✓
Rees End Panel Top Garnish Clips. ^{na} 20(SN) ✓
Rees End Panel Sealant. ^{na} 60(SN). ✓

11153 S-N: 110

10037.70

SLN 8399 G.

Panel Beating
Spray Painting.

Wiring.

To apply. tuft coat.

To remove reverse sensor

To remove rear camera.

To remove upholstery.

To transfer bootlid fittings

To perform diagnostic test.

~~1600~~ 1000

~~1400~~ 800

~~100~~ 30

~~150~~ 60

~~100~~ 50

~~100~~ 50

~~150~~ 60

~~150~~ 60 2110

250 X

total: 12257.70

W/S: 9.8K.

06 Days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

9,800

6 days