

ESTIMATE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Ang Jie	Cust No/Name /Ang Jie
624 Senja Road	Reg No/Reg Date SME6702M / 11/10/201
#06-98	Date In/Mileage / 0
Singapore 670624	Chassis No MMBSTA13AJH002566
Contact No Mobile: 96673272	Engine No 3A92UHC3753
	Make/Model MIT/18MY ATTRAGE 1.2 CVT
	Colour/Trim W05 WHITE PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00041	Cash	03/10/2022/ 17:50		442 / CocoLu	27741			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW REAR BUMPER, REPAIR BOOTLID, REAR END PANEL, REAR FENDER RH					2 X 640			2560.00
E PNT98000 SPRAY PAINT FOR REAR BUMPER, BOOTLID, REAR END PANEL, REAR FENDER RH					3 X 550			2200.00
E PNT88000 REMOVE & INSTALL PARKING SENSOR								100.00
M SUNDRY SUPPLY PARKING SENSOR NN								280.00
M SUNDRY C&C LOGO NEC								50.00
A 54900099 CHECK WIRING & ELECTRICAL SYSTEM								50.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM								280.00
M SUNDRY Sundry NEC								20.00
M FACE,RR BUMPER					1.00	1242.00	00.00	1242.00
M BRACKET,RR BUMPER,RH					1.00	34.00	00.00	34.00
M LATCH,TRUNK LID					1.00	220.00	00.00	220.00
M MARK,THREE-DIA					1.00	84.00	00.00	84.00
M MARK,ATTRAGE					1.00	25.00	00.00	25.00
M REFLECTOR					1.00	27.00	00.00	27.00
<div>Stew (LKK) 7/10/22, 12.00pm WL M PIP My Rel</div> <div>LKK Auto Consultants hereby notify the Reparer of the following:<ul style="list-style-type: none">To resurvey before/after spray paintingTo display damaged parts during resurveyParts prices are subject to confirmationThird party survey is on a "Without Prejudice" basisNo illegal modifications is allowedSupplementary item(s) must be resurveyed and is subject to final approval from Insurance Company</div>								
Confirm & accepted by 5 days					Acknowledged by Reparer Signature: Date:			
					7% GST on	Nett		7,172.00
						7172.00		502.04
					Total Payable			7,674.04
Authorized signatory and company stamp								

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.