



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 197701469G

Invoice Name & Address	Owner Name & Vehicle Info	
Ang Jie	Cust No/Name	/Ang Jie
624 Senja Road	Reg No/Reg Date	SME6702M / 11/10/201
#06-98	Date In/Mileage	/ 0
Singapore 670624	Chassis No	MMBSTA13AJH002566
Contact No Mobile: 96673272	Engine No	3A92UHC3753
	Make/Model	MIT/18MY ATTRAGE 1.2 CVT
	Colour/Trim	W05 WHITE PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00041	Cash	03/10/2022/ 17:50		442 / CocoLu	27741			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								2560.00
RENEW REAR BUMPER, REPAIR BOOTLID, REAR END PANEL, REAR FENDER RH								2200.00
E PNT98000								
SPRAY PAINT FOR REAR BUMPER, BOOTLID, REAR END PANEL, REAR FENDER RH								100.00
E PNT88000								
REMOVE & INSTALL PARKING SENSOR								280.00
M SUNDRY								
SUPPLY PARKING SENSOR								50.00
M SUNDRY								
C&C LOGO								50.00
A 54900099								
CHECK WIRING & ELECTRICAL SYSTEM								280.00
A 10028901								
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM								20.00
M SUNDRY								
Sundry					1.00	1242.00	00.00	1242.00
M FACE,RR BUMPER					1.00	34.00	00.00	34.00
M BRACKET,RR BUMPER,RH					1.00	220.00	00.00	220.00
M LATCH,TRUNK LID					1.00	84.00	00.00	84.00
M MARK,THREE-DIA					1.00	25.00	00.00	25.00
M MARK,ATTRAGE					1.00	27.00	00.00	27.00
M REFLECTOR								
Confirm & accepted by						Nett		7,172.00
						7% GST on	7172.00	502.04
						Total	Payable	7,674.04
Authorized signatory and company stamp								

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.