



Final Report

Estimate No. : **b1 63418**
Date Estimated : **24/09/2022**
Prepared By : **Foong Shiuh Jye**

Page No. :

- ESTIMATE REPAIR FOR -

Vu Heng Lye, Melvin (Wu Xinglai)
68 Elias Road
#04-16

Singapore 519942

- ACCOUNT - 135

China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	M LEAGE
SMF1177G	WBA12CM0X08C60742	11/05/2022	220i Coupe	5006

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace front number plate carrier include making good the front bumper and knocking out dents caused by the accident	850.00	0.00	850.00
To spray paint front bumper	986.00	0.00	986.00
To supply front emboss number plate	83.00	0.00	83.00
To check electrical wiring system at the front section for proper function	168.00	0.00	168.00
Sundries	40.00	0.00	40.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
FRT NUMBER PLATE CARRIER (ECE)	74.50	1.00	0.00	74.50

SUPPLEMENTARY ITEMS

Total Labour :	2,127.00
Total Parts :	74.50
Total Labour & Parts :	2,201.50
Deduction for Excess :	
Total Repair Costs less Excess:	2,201.50
GST @7%:	154.11
Grand Total :	2,355.61

Performance Motors Limited.

Sime Darby Performance Centre, 303 Alexandra Road

Tel: 1800-2255-269

Co Reg No. 197401559W

