

Wt 2029 May

Veh No: SMK 8447F Yr Regn: 2009, Nov

Type: ☒ M. Car / ☐ M. Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make: Mercedes Benz C180 C.C 1597

Colour Silver A/C: Insured / Std / NI / NA

Sp. Reading 121370 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WDD 26424576A 328787



Gen. Cond: Good / Fair / Poor / Burnt

Steering: in order / Jammed / Leaked / Burnt on

Brake: In order / Jammed / Leaked / Burnt on

Modi: Nil / S/Rim / STD A/Rim or/

Type Size: F:

| | |
|---|-----|
|  | |
| N/S | O/S |
|  | |

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO DJ

Front Rear

| | | | | | |
|--------|---|----|--------|---|----|
| R/Bal. | 6 | mm | R/Bal. | 6 | mm |
|--------|---|----|--------|---|----|

| | | | | | |
|--------|---|----|--------|---|----|
| L/Bal. | 6 | mm | L/Bal. | 1 | mm |
|--------|---|----|--------|---|----|

D.O.A. D.O.I. 5/10/77

Survey held at 61 West

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass, Lo?

☐: Preli. Report

Final Report

Days Of Repair: .

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$

□: Interview (\$

| | |
|--|-----------------|
| | Tech. Invs (\$) |
|--|-----------------|

Weekend (5)

Survey Fee:

Transportation:

.) $S \div RS, SI$

1) Photos

1) Others

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT

#01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Company Reg No: 201929175W

Repair Estimate

Vehicle number: SMK8447E

Make & Model: Mercedes Benz C180

Chassis number: WDD2040452A328187

Date of survey:

Name of surveyor:

Contacts:

| No. | Description of spare parts | Qty | Amount S\$ |
|-----|--|-----|---------------------------|
| 1 | Bootlid | 1 | \$ bt 1,520.00 |
| 2 | Bootlid centre emblem | 1 | \$ rel 63.00 |
| 3 | Bootlid lock | 1 | \$ x 315.00 |
| 4 | Bootlid lock catch | 1 | \$ x 45.00 |
| 5 | Bootlid weatherstrip | 1 | \$ x 197.00 |
| 6 | Bootlid RH hinge | 1 | \$ x 198.00 |
| 7 | Bootlid LH hinge | 1 | \$ x 198.00 |
| 8 | Rear bumper | 1 | \$ de 1,283.00 |
| 9 | Rear bumper RH side reverse sensor | 1 | \$ x 188.00 |
| 10 | Rear bumper RH centre reverse sensor | 1 | \$ nn 188.00 |
| 11 | Rear bumper LH centre reverse sensor | 1 | \$ nn 188.00 |
| 12 | Rear bumper LH side reverse sensor | 1 | \$ x 188.00 |
| 13 | Rear bumper reverse sensor rubber seal | 4 | \$ rel 86.00 |
| 14 | Rear bumper reverse sensor holders | 4 | \$ rel 40.80 |
| 15 | Rear bumper towing cover | 1 | \$ x 56.00 |
| 16 | Rear bumper centre bracket | 1 | \$ one 132.00 |
| 17 | Rear bumper reinforcement | 1 | \$ bt 665.00 |
| 18 | Rear bumper RH side bracket | 1 | \$ x 48.00 |
| 19 | Rear bumper LH side bracket | 1 | \$ de 48.00 |
| 20 | Rear bumper lower cover | 1 | \$ x 178.00 |
| 21 | LH taillamp assy | 1 | \$ one 612.00 |
| 22 | LH taillamp lower bracket | 1 | \$ mis 86.00 |
| 23 | LH taillamp panel | 1 | \$ x 189.00 |
| 24 | RH taillamp assy | 1 | \$ one 612.00 |
| 25 | RH taillamp lower bracket | 1 | \$ mis 86.00 |
| 26 | RH taillamp panel | 1 | \$ x 189.00 |
| 27 | End panel | 1 | \$ bt 1,189.00 |
| 28 | End panel inner garnish | 1 | \$ de 167.00 |
| 29 | Spare tyre panel top cover | 1 | \$ x 317.00 |

| | | | |
|----|--|---|---------------|
| 30 | Spare tyre panel tool tray | 1 | \$ ✕ 187.00 |
| 31 | Rear windscreen glass with rubber moulding | 1 | \$ ✕ 1,168.00 |
| 32 | Rear LH fender | 1 | \$ ✓ 2,395.00 |
| 33 | Rear LH fender inner trim board | 1 | \$ ✕ 378.00 |
| 34 | Rear LH fender spalsh shield | 1 | \$ ✕ 144.00 |
| 35 | Rear RH fender | 1 | \$ ✕ 2,395.00 |
| 36 | Rear RH fender inner trim board | 1 | \$ ✕ 378.00 |
| 37 | Rear RH fender spalsh shield | 1 | \$ ✕ 144.00 |
| 38 | Exhaust silencer | 1 | \$ ✕ 1,456.00 |
| 39 | Exhaust silencer gasket | 1 | \$ ✕ 54.00 |
| 40 | Passenger headrest assy | 1 | \$ ✕ 930.00 |
| 41 | Passenger seat belt | 1 | \$ ✕ 733.00 |
| 42 | Passenger seat belt buckle | 1 | \$ ✕ 166.00 |
| 43 | Front LH headrest assy | 1 | \$ ✕ 930.00 |
| 44 | Front LH seat belt | 1 | \$ ✕ 733.00 |
| 45 | Front LH seat belt buckle | 1 | \$ ✕ 166.00 |
| 46 | Rear RH passenger seat belt | 1 | \$ ✕ 733.00 |
| 47 | Rear RH passenger seat belt buckle | 1 | \$ ✕ 155.00 |
| 48 | Rear LH passenger seat belt | 1 | \$ ✕ 733.00 |
| 49 | Rear LH passenger seat belt buckle | 1 | \$ ✕ 155.00 |
| 50 | SRS control unit | 1 | \$ ✕ 1,853.00 |
| | | | |
| | | | |

\$ 25,257.80

Parts less 10% \$ 2,525.78

Total \$ 22,732.02

| No. | Special Nett Items | Qty | Amount S\$ |
|-----|---|------|-------------------|
| 1 | Bootlid "AMG" emblem | 1 | \$ net 220.00 |
| 2 | Bootlid sealant | 1 | \$ ✕ 120.00 |
| 3 | Bootlid spoiler | 1 | \$ ✕ 1,350.00 |
| 4 | Rear bumper clips | 1set | \$ 300 net 80.00 |
| 5 | Rear bumper lower garnish (after market) | 1 | \$ 500 net 980.00 |
| 6 | Rear bumper lower garnish RH exhaust chrome | 1 | \$ net 450.00 |
| 7 | Rear bumper lower garnish LH exhaust chrome | 1 | \$ net 450.00 |
| 8 | Rear windscreen glass sealant | 1 | \$ ✕ 80.00 |
| 9 | Rear windscreen glass inner seal | 1 | \$ ✕ 60.00 |
| 10 | Rear LH fender joint sealant | 1 | \$ ✕ 100.00 |
| 11 | Rear LH fender inner trim board clips | 1set | \$ ✕ 80.00 |
| 12 | Rear LH fender spalsh shield clips | 1set | \$ ✕ 60.00 |
| 13 | Rear RH fender joint sealant | 1 | \$ ✕ 100.00 |
| 14 | Rear RH fender inner trim board clips | 1set | \$ ✕ 80.00 |
| 15 | Rear RH fender spalsh shield | 1set | \$ ✕ 60.00 |

| | | | |
|----|------------------|---|------------------------|
| 16 | Rear numbr plate | 1 | \$ 80 80.00 |
| | | | |
| | | | |
| | | | |

Total: \$ 4,350.00

| No. | Labour and painting | Amount S\$ |
|-----|--|----------------------------|
| | | |
| | | |
| 1 | Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas | \$ 600 1,800.00 |
| | | |
| 2 | Spray painting on affected areas and panels | \$ 700 1,600.00 |
| | | |
| 3 | Check wiring and lighting system on affected areas | \$ 30 100.00 |
| | | |
| 4 | Apply rust coating chemical on affected areas and panels | \$ 30 180.00 |
| | | |
| 5 | Remove and replace rear windscreen glass to assist repair | \$ X 200.00 |
| | | |
| 6 | Remove and replace bootlid inner mechanism to new bootlid | \$ 600 150.00 |
| | | |
| 7 | Remove and replace rear bumper reverse sensors to assist repair | \$ 30 100.00 |
| | | |
| 8 | Remove and replace rear inner trims and garnish to assist repair | \$ 60 320.00 |
| | | |
| 9 | Remove and replace exhaust silencer and gasket to assist repair | \$ X 220.00 |
| | | |
| 10 | Remove and reinstall roof lining, seats and carpet to assist repair | \$ X 550.00 |
| | | |
| 11 | Remove and reinstall fuel tank, pipes and hoses to assist repair | \$ X 280.00 |
| | | |
| 12 | Remove and replace seat belts and buckles to assist repair | \$ X 500.00 |
| | | |
| 13 | Diagnose fault code and reset control unit | \$ X 580.00 |
| | | |
| | | |

Total: \$ 6,580.00

Agreed Amount: _____ (Part by Part / Lump sum)

Working days: _____

Spare Parts: \$ 22,732.02

Special Nett \$ 4,350.00

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT

#01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Company Reg No: 201929175W

Repair Supplementary Estimate

Vehicle number: SMK8447E

Make & Model: Mercedes Benz C180

Chassis number:

Date of survey:

Name of surveyor:

Contacts:

| No. | Description of spare parts | Qty | Amount S\$ |
|-----|----------------------------|-----|------------|
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |

\$ -
Parts less 10% \$ -
Total \$ -

| No. | Special Nett Items | Qty | Amount S\$ |
|-----|----------------------------------|-----|---------------|
| | | | |
| 1 | Bootlid body wrap sticker | 1 | \$ 200 580.00 |
| 2 | Rear bumper body wrap sticker | 1 | \$ 200 580.00 |
| 3 | Rear RH fender body wrap sticker | 1 | \$ X 850.00 |
| 4 | Rear LH fender body wrap sticker | 1 | \$ L 850.00 |
| | | | |
| | | | |

Total: \$ 2,860.00

| No. | Labour and painting | Amount S\$ |
|-----|---------------------|------------|
| | | |
| | | |
| | | |

Total: \$ -

Agreed Amount: _____ (Part by Part / Lump sum)

Working days: _____

Spare Parts: \$ -
Special Nett: \$ 2,860.00
Labour: \$ -

Labour: \$ 6,580.00

Total Amount: \$ 33,662.02

Tanpin 9749541

WP 5/10/22 @ 5/5

1/2 Resurvey after repair

Tanpin @ hands.com

6 days

- * To check consistency of accident
- To check part prices

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

| | |
|----------------|----------------|
| Owner ID Type: | Singapore NRIC |
| Owner ID: | 682J |

Vehicle Details

| | |
|-------------------------------|--------------------|
| Vehicle No.: | SMK8447E |
| Vehicle to be Exported: | Yes |
| Intended Deregistration Date: | 04 Oct 2022 |
| Vehicle Make: | MERCEDES BENZ |
| Vehicle Model: | C180K |
| Primary Colour: | Black |
| Manufacturing Year: | 2009 |
| Engine No.: | 27191031273751 |
| Chassis No.: | WDD2040452A328187 |
| Maximum Power Output: | 115.0 kW (154 bhp) |
| Open Market Value: | \$36,978.00 |
| Original Registration Date: | 12 Nov 2009 |
| First Registration Date: | 12 Nov 2009 |
| Transfer Count: | 3 |
| Actual ARF Paid: | \$36,978.00 |

Intended PARF Rebate Details

| | |
|-------------------------------|-----------|
| PARF Eligibility: | Forfeited |
| PARF Eligibility Expiry Date: | - |
| PARF Rebate Amount: | \$0.00 |

Intended COE Rebate Details

| | |
|-----------------------------|--------------------------|
| COE Expiry Date: | 31 May 2029 |
| COE Category: | A - Car (1600cc & below) |
| COE Period(Years): | 10 |
| PQP Paid: | \$27,886.00 |
| COE Rebate Amount: | \$18,560.00 |
| Total Rebate Amount: | \$18,560.00 |

The information contained herein is correct as at 03 Oct 2022

OK

VEHICLE NO: SMK 8447 E

MAKE & MODEL: MERC C180K

AUTO/MANUAL

| | | |
|--|--|---------------------------|
| DATE OF ACCIDENT | 03 / 10 / 22 | C.C. 1.6 |
| TIME OF ACCIDENT | 0800 | (AM)/PM |
| LOCATION OF ACCIDENT | PIE (HANGI) BER STEVENS EXIT | |
| EXACT PURPOSE USED AT TIME OF ACCIDENT | EMPLOYMENT / PRIVATE USE / PRIVATE HIRE | |
| NAME OF OWNER | UM ZHONG MIN | |
| EMAIL | JOEMINLIM@gmail.com | OFFICE: MOBILE: 9447 0447 |
| NRIC | S911682J | |
| CLAIM TYPE | OD / THIRTY PARTY / REPORTING ONLY | |
| FLEET POLICY | YES / NO? | |
| INCURANCE CO. | NTUC | |
| TYPE OF COVERAGE | Comprehensive / Third Party / Third Party Fire & Theft | |
| POLICY NO. | S118231703 - 01 | |
| NAME OF DRIVER | AS ABOVE / IF NO: YOLANDA YONG JI YIN | |
| NRIC | C9507752H | |
| DATE OF BIRTH | 01 / 04 / 91 | |
| ANY PASSENGER | YES / NO? DRIVER ONLY | |
| NAME OF PASSENGER | - | |
| GENDER OF PASSENGER | MALE / FEMALE | |
| OCCUPATION | Outdoor / Indoor | |
| DATE OF DRIVING PASS | 22 / 02 / 17 | |
| GENDER | MALE / FEMALE | |
| CONTACT NO. | Mobile: 8399829 Office: Home: | |
| EMAIL | ADNALOXANG95@gmail.com | |
| ADDRESS | 287 Chua CHU KANG AVE 2 #02-209 SC 680 287) | |
| DOES DRIVER OWN OTHER VEHICLES? | NO / If yes, Reg No: INSURE: - | |
| RELATIONSHIP | Employee / If No: FINANCE | |
| WEATHER CONDITION | Clear / Raining / Other: | |
| ROAD SURFACE | Dry / Wet / Other: | |
| ANY INJURIES | No / If yes, Who? DRIVER (SERIOUS) - A | |
| CONTACT NO. | | |
| ROLICE REPORT | No / If yes, Where? | |
| NOTICE OF INTENDED PROSECUTION? | No / If yes, Who? | |
| VEHICLE B NO. | CKD 2975Y | Any Passenger: |
| NAME | | |
| CONTACT NO. | | |
| VEHICLE C NO. | Any Passenger: | |
| VEHICLE D NO. | Any Passenger: | |
| VEHICLE E NO. | Any Passenger: | |
| VEHICLE F NO. | Any Passenger: | |
| ANY WITNESS | | |
| WITNESS CONTACT NO. | | |
| WAS THERE ANY VIDEO CAPTURE? | YES / NO | |
| WAS THERE ANY AUDIO RECORDED? | YES / NO | |
| SCENE ACCIDENT PHOTOS TAKEN? | YES / NO | |
| WHO IS REPORTING | DRIVER/ OWNER/ BOTH | |
| Original Language Used | English/ Mandarin/ Others: | |
| Have you been approach by unknown person soliciting (s) / offering accident claims assistance? | YES / NO | |

IMPORTANT NOTICE

SKETCH PLAN

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the Insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)

Sketch Plan

PTE CHANG 12

A
B
C
D

A: SHK 8947E
B: SKD 2535Y

Describe Circumstance of the Accident

ON THE STATED DATE AND TIME, I CAME TO A STOP

DUE TO THE CONGESTION.

OUT OF NOWHERE, I FELT A HUGE IMPACT FROM THE REAR.

Declaration

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time



Driver's Signature (if driver is not the policyholder) / Date

Witnessed by Reporting Centre Personnel