

**Note: This document has not been finalised.**

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance  
(Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Khong Lin Hui Lynn

Date: 09 Nov 2022

**Preliminary Advice**

Insured : SLQ6373C  
Vehicle No  
TP Vehicle : SJP7987D Accident Date : 03/10/2022  
No  
Make : HONDA STREAM Assignment Date : 04/10/2022  
Date of : 05/10/2022 Est. Duration of : 5  
Inspection Repair  
Inspection At : ACCORD AUTO SERVICES PTE LTD (HQ)  
10 ANG MO KIO IND PARK 2A #03-11, AMK AUTO POINT  
SINGAPORE 568047

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,120.96
Revised Amount	:S\$	3,259.94
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,259.94

Lump Sum Repair	:S\$	2,600.00
-----------------	------	----------

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$

Salvage Value :S\$

Margin for Repair :S\$

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.