

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Jenny Lew

Date: 05 Oct 2022

## **Preliminary Advice**

Vehicle No	: SNH2592L	Accident Date	: 02/10/2022
Make	: BMW 328I	Policy No.	: DMPCSNW00178152200
Assignment Date	: 04/10/2022	Excess	: S\$0.00
Date of Inspection	: 04/10/2022	Est. Duration of Repair	:
Inspection At	: CAR CITY AUTO CENTRE PTE LTD		

### **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	39,465.20
Revised Amount	:S\$	25,691.20
Check Items (Estimated)	:S\$	11,674.00
Total	:S\$	37,365.20

Lump Sum Repair	:S\$	
-----------------	------	--

### **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	142,000.00
COE / PARF Rebate	:S\$	116,177.00
Salvage Value	:S\$	
Margin for Repair	:S\$	25,823.00

### **Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( x ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( x ) Other comments :at the time of inspection,all the tyres of the insured vehicle were found to be in good serviceable condition with remaining tread depth of approximately 5mm.