ASS. RECEBY: TOUTH - REF. CS/ CT127	2009785/Tvy3
1	IGNMENT
From: Date:	Veh No: 405789P. Yr Regn: 2024 Jan.
Estimated lost	Type: M.Car / M.Cycle / Bus / Van / Corry / Taxi / Prime Mover /
OD I P I NS ITP RES I OD RES I EVA I INV I MV	Truck / Trailer or
To Inspectivehicle No:	Make: To Yoke Dyng c.c 2754
at Workstopm/s	Colour Silver A/C: Insured / Std / NI / NA
	Sp.Reading 32092 T/Radio: Insured / Std / NI / NA
Insured:	Eng/No:
Policy No.	C/No: JWHAG V4600 KOO (680
Claims No.	Gen. Cond: Good) Fair / Poor / Burnt
Sum insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: inorder / Jammed / Leaked / Burnt or
Make of Vet.	Modi: NID / S/Rim / STD A/Rim or
	Tyre Size: F: (75/21)
(Policy Condition)	R: 147/80113.
Remark: The veh had commenced its N/S O/S	BS DUN / EXNOVA / GY /FS / LIZA / MIC / OHTSU / PIR / SUM! /
repair at the time of inspection.	TOYO I YOKO DI
Ball or Market Value:	Front 6 Rear
IDAC Accident Roort Consistent? : Yes or No	R/Bal. mm POBal. G/O
GIA / PR Seen: Consistent? : Yes or No	
Est. Repairs: days Res.: Yes or No	0.1.4
Lum Sum: % 3 Val.: Yes or No	Des. of Damages: Frt Rear   O/S   N/S   U/C   Rooftop or
CA / REV / REP. / 24 HRS	
Date: Person Contacted: Vehicle: IN / C	The U/C / Chassis frame / Body Structure affected due to collision
Date / Time   Action / Instruction	
)	
	1
	<u> </u>
Date/Time, File Pass 10? : Preli. Report	Days Of Repair:
i) : Final Report	Resurvey No. of Trip: Survey Fee:
Date/Time, File Return to?	Transportation:
2)Add	Fee: : Site Insp (\$) _s+Rs_si
	: Interview (\$ ) Photos

# **Bifrost Auto Pte Ltd**

8 Kaki Bukit Ave 4 #01-49, Premier @ Kaki Bukit Singapore 415875 Tel: 93290237 Email: claims\_rar@bifrostauto.com

SJE:	Vehicle Nos:	YQ 5789P
Date of Survey :	Made :	Toyota
Date of ReSurvey:	Model :	Dyna
Contacts:	Chassis No:	
* AGREED Cost Of Repair and Repair Day/s with	SJE *	
Amount:	Working Day:	

Nos.	PARTS	Qty	Unit S\$		TOTAL	S\$
1	Front Bumper	1	\$ 468.20	\$	6t/	468.20
2	Front Bumper Reinforcement	1	\$ 279.80	\$	Bt-	279.80
3	Front Bumper Bracket RH	1	\$ 232.70	\$	X	232.70
4	Front Bumper Bracket LH	1	\$ 232.70	\$	*	232.70
5	Front Bumper Foglamp Garnish RH	1	\$ 105.30	\$	×	105.30
6	Front Bumper Foglamp Garnish LH	1	\$ 105.30	\$	K	105.30
7	Front Grille Assembly	1	\$ 465.60	\$	and/	465.60
8	Front Grille Emblem	1	\$ 78.40	\$	art	78.40
9	Front Panel	1	\$ 1,150.00	\$	b{-	1,150.00
10	Front Panel Emblem	1	\$ 67.20	\$	001/	67.20
11	Front Wiper Panel	1	\$ 285.20	\$	ht	285.20
12	Front Windscreen Glass Moulding	1	\$ 309.80	\$	au /	309.80
13	Front Headlamp Assembly RH	1	\$ 1,009.70	\$	ent	1,009.70
14	Front Headlamp Assembly LH	1	\$ 1,009.70	\$	an-	1,009.70
15	Front Headlamp Assembly Lower Rubber RH	1	\$ 38.10	\$	×	38.10
16	Front Headlamp Assembly Lower Rubber LH	1	\$ 38.10	\$	*	38.10
17	Front Corner Panel RH	1	\$ 343.20	\$	×i	343.20
18	Front Corner Panel LH	1	\$ 343.20	\$	×	343.20
19	Front Corner Garnish ( Upper ) RH	1	\$ 110.70	\$	X	110.70
20	Front Corner Garnish ( Upper ) LH	1	\$ 110.70	\$	7	110.70
21	Cabin Hinge ( Front )	1	\$ 205.20	\$	1	205.20
22	Front Pillar Support Bar	1	\$ 455.30	\$	×	455.30
23	Aircon Pipe	1	\$ 289.70	\$		289.70
24	Aircon Blower Motor	1	\$ 1,572.50	\$	5	1,572.50
25	Aircon Cooling Coil & Heater Assembly	1	\$ 1,882.20	\$		1,882.20
26	Aircon Condenser Assembly	1	\$ 828.60	\$		828.60
27	Wiper Washer Tank	1	\$ 155.70	\$		155.70
28	Brake Pipe	1	\$ 135.80	١.	er arcev	
29	Front Wire Harness	1	\$ 428.70	+		135.8
30	Side Mirror with Stand LH	1	\$ 	+	1	428.7
31	Side Mirror Round LH	_	\$ 690.30	+		690.3
32	Front Dashboard Assembly	1	139.60	+		139.6
,,,	Front Dashboard Assembly	1	\$ 1,008.00	\$	<b>X</b>	1

33	Front Dookhoord Dainforcoment Day	1	۲.	704 30	\$	X,	704.20
	Front Dashboard Reinforcement Bar	1	\$				794.30
34	Front Wiper Arm RH	1	\$		\$	K	122.00
35	Front Wiper Arm LH	1	\$		\$	X	122.00
36	Front Wiper Blade RH	1	\$	100000000000000000000000000000000000000	\$	X-0.54	56.00
37	Front Wiper Blade LH	1	\$		\$	×	56.00
38	Front Wiper Linkage	1	\$		\$	У.	420.00
39	Front Wiper Motor	1	\$	760.00	\$	×	760.00
40	Rear Tailgate	1	\$		\$	11-	1,680.20
41	Rear Tailgate "Dyna" Sticker	1	\$	57.60	\$	al-	57.60
42	Rear Tailgate Hinge	4	\$	124.20	\$	ne -	496.80
43	Rear Tailgate Side Lock RH	1	\$	192.60	\$	×	192.60
44	Rear Tailgate Side Lock LH	1	\$	192.60	\$	K	192.60
45	Rear Tailgate Stopper Bracket RH	1	\$	109.90	\$	×	109.90
46	Rear Tailgate Stopper Rubber RH	1	\$	48.60	\$	×	48.60
47	Rear Tailgate Stopper Bracket LH	1	\$	109.90	\$	x	109.90
48	Rear Tailgate Stopper Rubber LH	1	\$	48.60	\$	×	48.60
49	Rear Tailgate Lower Panel (End Panel)	1	\$	698.10	\$	RY	698.10
50	Rear Taillamp Assembly RH	1	\$	345.80	\$	au	345.80
51	Rear Taillamp Panel RH	1	\$	255.60	\$	6+	255.60
52	Rear Taillamp Assembly LH	1	\$	345.80	\$	Crar	345.80
53	Rear Taillamp Panel LH	1	\$	255.60	\$	61	255.60
54	Rear Number Plate Bracket	1	\$	119.50	\$	X	119.50
55	Rear Number Plate Lamp	1	\$	139.20	\$	1	139.20
56	Spare Tyre Carrier	1	\$	385.90	\$	7	385.90
57	Spare Tyre Carrier Bracket	1	\$	185.20	\$	×	185.20
58	Rear Exhaust Pipe	1	\$	895.00	\$	X	895.00
59	Rear Exhaust Pipe Mounting	1	\$	138.00	\$	×	138.00
60	Rear Mudguard RH	1	\$	343.00	\$	F	343.00
61	Rear Mudflap RH	1	\$	114.20	\$		114.20
62	Rear Mudguard LH	1	\$	343.00	Ś	×	343.00
63	Rear Mudflap LH	1	\$	114.20	-	*	114.20
64	Rear Chassis Crossmember	1	\$	894.50	+	*	894.50
65	Rear Side Gate RH	1	\$	1,945.20	+		
66	Rear Side Gate LH	1	\$		+	001.000.0	1,945.20
67	Rear Side Gate Lower Panel RH	_	-	1,945.20	-		1,945.20
68	Rear Side Gate Lower Panel LH	1	\$	845.20	+	\$ <b>×</b>	845.20
	inear side date tower Faller Ln	1	\$	845.20	+	\$ ×	845.20
				Parts Sub Total :	15		30,995.70
		25	%	Discount	1	\$	7,748.93
					0.00		and the state of t

Nos.	SPECIAL NETT	Qty	us is	Unit S\$		TOTAL S\$
1	Front Number Plate	1	\$	40.00	Ś	bi - 30. 40.00
2	Front Grille Assembly Clips - Set	1	\$	50.00	Ś	re( 20. 50.00
3	Front Corner Panel Clips - Set	1	Ś	30.00	4	X 30.00
4	Front Windscreen Glass Sealant	1	\$	150.00	-	60 NU -150.00

PARTS TOTAL: \$

23,246.78

5	Front Panel Sealant	1	\$	150.00	\$ 4 cme 150	0.00
6	Front Wiper Panel Sealant	1	\$	120.00	* /.	0.00
7	Front Windscreen Panel Sealant	1	\$	200.00	\$ 20	0.00
8	Front Panel Artwork Sticker	1	\$	650.00	\$ 7 300 65	0.00
9	Front Windscreen Panel Artwork Sticker	1	\$	500.00	+/	0.00
10	Rear Number Plate	1	\$	50.00	771	0.00
11	Rear Reverse Sensor	1	\$	250.00	747-	0.00
12	Rear Reverse Camera	1	\$	500.00	7 /	00.00
13	Rear Tailgate "60km/h" Sticker	1	\$	50.00	7700	50.00
14	Rear Tailgate "13 Pax" Sticker	1	\$	50.00	7/00	50.00
15	Rear Tailgate Artwork Sticker , Side gate LH RH	1	\$	1,000.00	\$14-600 1,00	100000000
16	Rear Tailgate P Plate	1	\$	50.00	7	50.00
17	Rear Sidegate Top Stainless Steel Railing RH	1	\$	1,500.00	+ /\	00.00
18	Rear Sidegate Top Stainless Steel Railing LH	1	\$	1,500.00	-	00.00
19	Rear Floor Panel Aluminium Plate	1	\$	3,500.00	T#1 1000	00.00
20	Rear Tailgate Aluminium Plate	1	\$	1,200.00	# U	200.00
21	Rear Sidegate Aluminium Plate RH	1	\$	1,800.00	+ /\	300.00
22	Rear Sidegate Aluminium Plate LH	1	\$	1,800.00	¥ 7.	800.0
23	Rear Canopy	1	\$	3,000.00	T /	0.000
24	Rear Reinforcement Beam	1	\$	1,500.00	\$64-5021,	500.0
25	Rear Tailgate Lower Panel (End Panel) Sealant	1	\$	150.00	\$ X	150.0
26	Rear Sidegate Sealant RH	1	\$	150.00	\$ X	150.0
27	Rear Sidegate Sealant LH	1	\$	150.00	\$ 🗶	150.0
28	Rear Tailgate Sealant	1	\$	150.00	\$ X	150.0
			SPECIAL	NETT TOTAL :	\$ 20	,240.0

Nos.	LABOUR	TOTAL S\$
1	To Panel Beat, Remove & Refix Parts ( Front )	\$ 700 1,200.00
2	To Spray Paint Affected Areas ( Front )	\$ 700 1,200.00
3	To Panel Beat, Remove & Refix Parts ( Rear )	\$ 800 1,800.00
4	To Spray Paint Affected Areas ( Rear )	\$ 900@ 1,600.00
5	Wiring & Bulb Check ( Front )	\$ 30 120.00
6	Wiring & Bulb Check ( Rear )	\$ 30 100.00
7	To Remove & Refix Front Windscreen Glass	\$ 120 ? 150.00
8	To Remove & Refix Aircon Cooling Coil & Heater Assembly	\$7 100 70 350.00
9	To Remove & Refix Aircon Blower Motor	\$5 (5 0) 300.00
10	To Remove & Refix Aircon Condenser & Top Up Gas	\$ (60 % 150.00
11	To Remove & Refix Front Dashboard Assembly	\$ × 500.00
12	To Remove & Refix Rear Reverse Sensor	\$ 30 150.00
13	To Remove & Refix Rear Camera	\$ 7 150.00
14	To Remove & Refix Rear Exhaust Pipe	\$ % 150.00
15	To Remove & Refix Rear Aluminium Plates	\$ 7 1600 300.00
16	To Remove & Refix Rear Floor Panel Aluminium Plate	\$ 3 100 400.00
17	To Remove & Refix Rear Canopy	\$ 🗶 400.00
18	To apply anti rust on affected parts	\$ 80 250.00

19	To Conduct Water Leak Test	\$ ×	100.00
20	To Send for Diagnostic and Reset Control Unit. Programming & Calibration	\$ X	480.00
	LABOUR TOTAL:	\$	9,850.00
	PARTS TOTAL :	\$ :	23,246.78

LABOUR TOTAL: \$ 53,336.78 GRAND TOTAL: \$

20,240.00

9,850.00

SPECIAL NETT TOTAL: \$

Taylor 97495749

WP 5/w/22 440pm

Cls Resur affar repair

tenfish athlanto.com

10 days.

To cheek consistency of raident

To cheek part prias.

# LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

# > Back to OneMotoring

Enquire	PARF/	COE	Rebate for	Registered	Vehicle
1111	_	_		Bistel ed	Actificie

2
5MT
74
00K001680
ehicle & Bus

The information contained herein is correct as at 05 Oct 2022

pliciting (s) / offering accident claims	YES / NO
Original Language Used  Tave you been approach by unknown person	English/ Mandarin/ Others:
WHO IS REPORTING	DRIVER/ OWNER/ BOTH
SCENE ACCIDENT PHOTOS TAKEN?	YES MO.
WAS THERE ANY AUDIO RECORDED?	YES (NO
WAS THERE ANY VIDEO CAPTURE?	YES /NO
WITNESS CONTACT NO.	ARICE VALOS
ANY WITNESS	
VEHICLE F NO.	Any Passenger:
VEHICLE E NO.	Any Passenger:
VEHICLE D NO.	YQ 56962 Any Passenger:   DIZIVOL ? YASSENG
VEHICLE C NO.	JJR 1965 Any Passenger:   DR IVER ? 179.SSE NG
CONTACT NO.	CALALLY Am December 1 Day to 7 120 CCC.
NAME	UNKNOWN AMT OF PAISE
VEHICLE B NO.	YQ51946 Any Passenger: I DRIVER
NOTICE OF INTENDED PROSECUTION?	No./ If yes, Who?
ROLICE REPORT	No / If yes, Where? TP MQ.
CONTACT NO.	
ANY INJURIES	No / If yes, Who? DRIVER (SEPIOUS) - A.
ROAD SURFACE	Dry /Wet / Other:
WEATHER CONDITION	Clear / Raining / Other:
RELATIONSHIP	Employee / If No:
DOES DRIVER OWN OTHER VEHICLES?	NO If yes, Reg No: INSURE:
ADDRESS	32019 UNIAN PD S(424712).
EMAIL	SHIKPAR 1985 e GMAIL. CM
CONTACT NO.	Mobile:90989353 Office: Home:
GENDER	MALE / FEMALE
DATE OF DRIVING PASS	14 / 01 / 22.
OCCUPATION	Outdoor Andoor
GENDER OF PASSENGER	-MALE / FEMALE
NAME OF PASSENGER	(m) REJAUL, (m) UNKNOUN.
ANY PASSENGER	XES / NO: 2
DATE OF BIRTH	04/02/85.
NRIC	66961894
NAME OF DRIVER	AS ABOVE HEND: SHIKDAR IND AL AMIN
POLICY NO.	5125564735.
TYPE OF COVERAGE	Comprehensive / Third Party / Third Party Fire & Theft
INCURENCE CO.	MNC.
FLEET POLICY	YES / NO?
CLAIM TYPE	OD / THIRTY PARTY / REPORTING ONLY
NRIC	202015727m
EMAIL ASLINTER-2020 Comple. Com	m OFFICE: MOBILE: 92386305
NAME OF OWNER	ASL INTERNATIONAL (S) PTE LTD.
EXACT PURPOSE USED AT TIME OF ACCIDENT	EMPLOYMENT / PRIVATE USE / PRIVATE HIRE
LOCATION OF ACCIDENT	SERANGOON AN BEFORE VAVENDER ST.
	7:05 AM (PM)
TIME OF ACCIDENT	62/6/22. C.C. 3000

#### SKETCH PLAN

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Actual Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy flability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Traffic Police Department for investigation.
- 6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the
  report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law-firms, may/are permitted to collect, use, disclose and/or process my Personal information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date

Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)


Sketch Plan

| Control | C

escribe Circumstance of the		To police	REPORT.	· ·	
			17.0		
			1		
				2 - 1	
					9 (4)
					<u> </u>
			-		
					•
		(d)			
	***				
		1.00			
		<del>- 2</del>			
				1	
	<del></del>				
	·				

# Declaration

I/We declare the foregoing particulars are true in every respect.



Sh





1 of 3

Report No. T/20221002/7031

Police Station Of Origin: Traffic Police

10 Ubi Avenue 3 SINGAPORE 408865

Tel No: 65470000

REPORT	OF A	TRAFFIC	ACCIDENT
neruni	UFA	INALLIC	ACCIDENT

Date/Time Report Made: 02/10/2022 21:02		Vide Report No.:	Station Diary No.:	
's Particu	lars			
	MIN	Address:		
ID Type / ID No.: FIN NO / G6961189W		Contact No.: Home/Office:	Mobile: 90989353	
		Email: SHIKDAR19850209@GMAIL.	COM	
Sex: Age: Date of Birth: Male 37 09/02/1985		Type of Informant: Driver		
Race: Bangladeshi		Language: English	Institution / School Name:	
Occupation: MANAGER		Driving Licence Information: Class: 3	Date of Expiry:	
	's Particular formant: MD AL Al D No.: 66961189 : ESHI Age: 37	2 21:02  's Particulars  Informant:  MD AL AMIN  D No.:  66961189W :  ESHI  Age: Date of Birth:  37 09/02/1985	Ps Particulars  Iformant:  MD AL AMIN  D No.:  G6961189W  ESHI  Age:  Date of Birth:  37  D9/02/1985  Driver  Language: English  Driving Licence Information:	

General Infor	mation of the Acci	SCHOOL SC	in a subject to the second	
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 02/10/2022 19:05	Type of Location Straight Road
Location: SERANGOON	N ROAD			
Weather: Raining		Road Surface:		Road Speed Limit:
Traffic Flow: Traffic Control: Traffic Light - Working		orking	Traffic Volume: Moderate	
Type of Collision Between Movid	on: ng Vehicles - Head	To Rear		Anyone conveyed by ambulance:

Vehicle No.	Type	Make	Model	Color	Conditio	No of
SJR1965X	Car					0
YQ5194E	Lorry				Seriously Damaged	2.5
YQ5696Z	Lorry				Seriously Damaged	25.00





Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000

2 of 3 Report No. T/20221002/7031

#### CONTINUATION OF REPORT

Details of Vehicle Involved						
Vehicle No.	Туре	Make	Model	Color	Conditio	No of
YQ5789P	Lorry				Seriously Damaged	

Details of Perso	n Involved				The State of	
Any Pedestrian I	nvolved: No					
No. of Pedestrians Injured: NIL Use of				Pedestrian Crossing: NA		
Driver						
Name	SHIKDAR MD AL AMIN			ID No.	G6961189W	
Related Vehicle	YQ5789P (Lorry)			Contact N	No. 90989353	
Hospital/Clinic	NIL			Class of Driving Licence 8 Expiry	Class: 3 Date of Expiry: NIL	
Date	NIL		Date	N	IL .	
No. of Days granted Medical Leave 03			Degree of	S	erious	

### Brief Details.

ON THE STATED DATE AND TIME, I WAS STOPPED BEHIND YQ5696Z WITHOUT ANY CONTACT TO YQ5696Z DUE TO THE TRAFFIC LIGHT BEING RED.

OUT OF NOWHERE, I FELT A GREAT IMPACT FROM THE REAR AND THE IMPACT CAUSED MY VEHICLE TO HIT ONTO YQ5696Z AND YQ5696Z TO SURGE FORWARD AND HIT ONTO SJR1965X.

AFTER THE ACCIDENT, I FELT PAIN AND WENT TO SEEK FOR PROFESSIONAL MEDICAL HELP FROM A DOCTOR AND WAS GIVEN 3 DAYS OF MEDICAL LEAVE.

1ST VEH: SJR1965X 2ND VEH: YQ5696Z 3RD VEH: YQ5789P 4TH VEH: YQ5194E





Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000

3 of 3 Report No. T/20221002/7031

## CONTINUATION OF REPORT

SI	cet	ch	PI	an
O	VC!			an

Informant is not able to provide sketch

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by Singpass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 02/10/2022 21:02
Officer In Charge Of Case: TP / TPIB / FAHKRUL RAZI BIN SUHAIME Contact No.: 65470000	Classification Of Case: