

KFS motor

ERGO INSURANCE PTE LTD

8 TEMASEK BOULEVARD

#04-01 SUNTEC TOWER 3

SINGAPORE 038988

VEHICLE NO. : GBK9945H

ACCIDENT DATE : 28-07-2022 09:55

THIRD PARTY REF. : YM3463M

INVOICE NO : TEST

DATE : 12-10-2022

ATTN: MOTOR CLAIMS DEPT.

INVOICE COST OF REPAIRS TO VEICLE GBK9945H TOYOTA DYNA 150 5MT

<u>QTY</u>	<u>PARTS DESCRIPTION</u>	<u>AMOUNT (SG\$)</u>
1	FRONT WINDSCREEN GLAS	450.00
1	FRONT WINDSCREEN RUBBER	95.00
1	FRONT WIPER PANEL	130.00
1	FRONT PANEL	400.00
1	FRONT PANEL DYNA EMBLEM	28.00
1	FRONT GRILLE	175.00
8	FRONT GRILLE CLIP@\$3.00	24.00
1	FRONT HEADLAMP LH	300.00
1	FRONT BUMPER	220.00
1	FRONT BUMPER BRACKET @\$95.00	95.00
		1,917.00
	ADD 10 %	
		191.70
	TOTAL (A)	
		2,108.70
SPECIAL NETT ITEMS		
1	ERP STICKER	
		15.00
	TOTAL (C)	
		15.00
LABOUR CHARGES		
1	TO CHECK WIRING SYSTEM	
		30.00
1	TO REMOVE/REFIT FRONT WINDSCREEN GLASS	
		120.00

1/2

VEHICLE NO. : GBK9945H
ACCIDENT DATE : 28-07-2022 09:55
THIRD PARTY REF. : YM3463M

<u>QTY</u>	<u>PARTS DESCRIPTION</u>	<u>AMOUNT (SG\$)</u>
1	TO REMOVE/REFIT AIR CON BLOWER SYSTEM AND REFILL AIR CON GAS	220.00
1	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	600.00
1	SPRAYPAINTING CHARGES	600.00
1	To remove & refit Dashboard Assy to facilitate front panel replacement.	
	TOTAL (D)	1770.00
	TOTAL REPAIR COST :	3893.70
	G S T % :	237.56
	EXCESS AMOUNT :	500.00
	INVOICE AMOUNT :	3431.26

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 16 Aug 2022)

Parts: N/A TOYOTA DYNA 150 3.0 D (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Kan Fook Sing Motor Workshop/GBK9945H/16/08/2022 18:18

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT WINDSCREEN GLASS / CAA	0.00	0.00	*350.00 F 450
2	1		*FRONT WINDSCREEN RUBBER / MC	0.00	0.00	*95.00 F
3	1		*FRONT WIPER PANEL / ee	0.00	0.00	*130.00 F
4	1		*FRONT PANEL / MC	0.00	0.00	*390.00 F 400
5	1		*FRONT PANEL DYNE EMBLEM / MC	0.00	0.00	*28.00 F
6	1		*FRONT GRILLE / CA	0.00	0.00	*175.00 F
7	1		*FRONT GRILLE EMBLEM / MC	0.00	0.00	*28.00 F
8	1		*FRONT HEADLAMP LH / CA	0.00	0.00	*300.00 F
9	1		*FRONT BUMPER / BT	0.00	0.00	*220.00 F
10	1		*FRONT BUMPER BRACKET RH ?	0.00	0.00	*95.00 F
11	1		*FRONT BUMPER BRACKET LH ?	0.00	0.00	*95.00 F
12	1		*AIR CON BLOWER ?	0.00	0.00	*900.00 F
13	1		*HEATER UNIT ?	0.00	0.00	*155.00 F
14	8		*FRONT GRILLE CLIP / MC	0.00	0.00	*24.00 F

F=Franchise part.

Sub Total (\$\$) 2,985.00

+ Margin on L,N Items 10.00% (\$\$) 298.50

Total Parts (\$\$) 3,283.50

Kan Fook Sing Motor Workshop/GBK9945H/16/08/2022 18:18. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1	1	ERP STICKER / KCL	15.00
2	1	FRONT NUMBER PLATE X NN	40.00
Sub Total (S\$)			55.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Paintwork Labour

1	SPRAYPAINTING CHARGES	New	600 780.00
---	-----------------------	-----	------------

Labour Items

2	TO CHECK WIRING SYSTEM	New	30 50.00
3	TO REMOVE/REFIT FRONT WINDSCREEN GLASS	New	120.00
4	TO REMOVE/REFIT AIR CON BLOWER SYSTEM AND REFILL AIR CON GAS	New	220.00
	TO REMOVE ALL NECESSARY AFEKTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	New	600 820.00

Gross Labour Cost (S\$) 1,990.00

Kan Fook Sing Motor Workshop/GBK9945H/16/08/2022 18:18. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Excess: 500

Not Authorized.

Guo Qi q

5/10/22

5 Days.

P/P

before parts photos.