

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

XIAO LIANGRONG
 2 TAY LIAN TECK ROAD
 SINGAPORE 455616

Contact : 93213898

TAX INVOICE *T? Allianz*
Xiao Tong

Repair Code : CLM17400
 Date in : 01/10/2022
 Vehicle Num. : SLN6789C
 Model : TOYOTA HARRIER PREMIUM 2.0 CVT
 Chassis/Eng# : ZSU600092077/3ZRB911046

Parts and Labour Assessment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>Del'd</i>	1	1217.40	✓ 1,217.40
REAR BUMPER INNER SPONGE <i>could</i>	1	172.25	✓ 172.25
REAR BUMPER LID GARNISH <i>Del'd.</i>	1	481.00	✓ 481.00
REAR BUMPER REFLECTOR L/R <i>LH could</i>	2	59.80	119.60 <i>55.50</i>
REAR BUMPER SIDE RETAINER L/R <i>LH could</i>	2	122.50	245.00 <i>122.50</i>
REAR CENTER DECK BOARD TOP COVER <i>new</i>	1	731.20	+ 731.20
REAR END PANEL <i>Dented</i>	1	781.85	✓ 781.85
REAR END PANEL ANTENNA SENSOR <i>could</i>	1	255.00	✓ 255.00
REAR END PANEL INNER TOP GARNISH <i>Del'd</i>	1	591.60	✓ 591.60
REAR LH DECK BOX GARNISH <i>Del'd</i>	1	789.10	✓ 789.10
REAR LH FENDER AIR VENT <i>Del'd</i>	1	278.10	✓ 278.10
REAR LH FENDER AIR VENT COVER <i>new</i>	1	78.30	+ 78.30
REAR LH FENDER INNER TRIM GARNISH <i>Del'd</i>	1	972.10	972.10 <i>791</i>
REAR TAILGATE <i>Dented</i>	1	2379.00	2379.00 <i>1750</i>
REAR TAILGATE 'HARRIER' EMBLEM <i>new</i>	1	121.25	✓ 121.25
REAR TAILGATE DUST PROOF SEAL <i>new</i>	4	71.45	+ 285.80
REAR TAILGATE INNER PULL GARNISH <i>new</i>	1	49.50	+ 49.50
REAR TAILGATE INNER TRIM GARNISH <i>Del'd</i>	1	731.35	✓ 731.35

581

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

XIAO LIANGRONG
 2 TAY LIAN TECK ROAD
 SINGAPORE 455616

Contact : 93213898

TAX INVOICE

Repair Code : CLM17400
 Date in : 01/10/2022
 Vehicle Num. : SLN6789C
 Model : TOYOTA HARRIER PREMIUM 2.0 CVT
 Chassis/Eng# : ZSU600092077/3ZRB911046

REAR TAILGATE MECHANISM LOCK <i>Del'd</i>	1	974.00	<i>A35</i> 974.00
REAR TAILGATE MECHANISM LOCK COVER <i>see u</i>	1	122.40	<i>+</i> 122.40
REAR TAILGATE NETWORK MODULE UNIT <i>Del'd</i>	1	780.30	<i>S45</i> 780.30
REAR TAILGATE OPENER BUTTON SENSOR <i>see u</i>	1	278.10	<i>+</i> 278.10
REAR TAILGATE OUTER GARNISH <i>cancel'd</i>	1	1217.95	<i>G/S</i> 1217.95
REAR TAILGATE OUTER GARNISH 'LOGO' EMBLEM <i>see u</i>	1	182.10	182.10
REAR TAILGATE REFLECTOR BACK RUBBER GASKET L/R <i>see u</i>	2	43.75	<i>+</i> 87.50
REAR TAILGATE REFLECTOR L/R <i>LH cancel'd</i>	2	581.90	<i>581.90</i> 1163.80
REAR TAILGATE RUBBER GUIDE STOPPER L/R <i>see u</i>	2	43.75	<i>+</i> 87.50
REAR TAILGATE SIDE SENSOR L/R <i>see u</i>	2	1350.00	<i>+</i> 2,700.00
REAR TAILGATE WEATHER STRIP <i>cancel'd</i>	1	442.00	<i>412</i> 442.00
REAR TAILGATE WINDSCREEN MOULDING L/R <i>see u</i>	2	171.45	<i>150</i> 342.90
REAR TAILGATE WINDSCREEN MOULDING LOWER <i>see u</i>	1	172.10	<i>60</i> 172.10
REAR TAILGATE WINDSCREEN MOULDING TOP <i>see u</i>	1	172.10	<i>60</i> 172.10
REAR TAILLAMP L/R <i>cancel'd</i>	2	610.00	1,220.00
REAR TAILLAMP LOWER BRACKET L/R <i>cancel'd</i>	2	121.10	242.20

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

XIAO LIANGRONG
 2 TAY LIAN TECK ROAD
 SINGAPORE 455616

TAX INVOICE

Repair Code : CLM17400
 Date in : 01/10/2022
 Vehicle Num. : SLN6789C
 Model : TOYOTA HARRIER PREMIUM 2.0 CVT
 Chassis/Eng# : ZSU600092077/3ZRB911046

Contact : 93213898

		Subtotal before discount	20,464.35
Percentage discount	25%	12495.55	5,116.09
		Sub-total 1	15,348.26
REAR BUMPER CLIPS - SET	<i>nc</i>	1	50.00 30 50.00
REAR BUMPER REVERSE SENSOR - SET	<i>nc</i>	1	250.00 20 250.00
REAR END PANEL INNER TOP GARNISH CLIPS - SET	<i>nc</i>	1	20.00 ✓ 20.00
REAR END PANEL SEALANT	<i>nc</i>	1	100.00 60 100.00
REAR FENDER INNER TRIM GARNISH CLIPS L/R - SET	<i>nc</i>	2	50.00 30 100.00
REAR TAILGATE INNER TRIM GARNISH CLIPS - SET	<i>nc</i>	1	50.00 30 50.00
REAR TAILGATE OUTER GARNISH CLIPS - SET	<i>nc</i>	1	50.00 20 50.00
REAR TAILGATE WINDSCREEN SEALANT	<i>nc</i>	1	80.00 60 80.00
REAR TAILLAMP CLIPS L/R - SET	<i>nc</i>	2	30.00 20 60.00
		Subtotal before discount	760.00
Percentage discount	0%		0.00
		Sub-total 2	760.00
		Parts-total	16,108.26

LABOUR

To reset system after repair works	x	280.00
To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.	✓	80.00
To remove, reinstall tailgate windscreen	120	150.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

XIAO LIANGRONG
 2 TAY LIAN TECK ROAD
 SINGAPORE 455616

Contact : 93213898

TAX INVOICE

Repair Code : CLM17400
 Date in : 01/10/2022
 Vehicle Num. : SLN6789C
 Model : TOYOTA HARRIER PREMIUM 2.0 CVT
 Chassis/Eng# : ZSU600092077/3ZRB911046

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	80 150.00
To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare tyre panel and rear bumper.	low 1,600.00
To remove and reinstall exhaust pipe.	+ 80.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	1800 1,300.00
To apply anti-rust chemical on repaired and replaced panel.	2A.20 60 100.00
To remove, reinstall tailgate mechanism and check for function	✓ 80.00
Labour Total	3,820.00
Parts & Labour Total	19,928.26

*** This is a computer-generated document which requires no signature.***

Adrian L.
 2/s 06/10/22.
 O.T. Days

Total: 12261.66
 L/s: 9.81K
 9.81K.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: